



**HEWLETT-PACKARD COMPANY
LOGIC SYSTEMS DIVISION**

**HP 64000
Logic Development
System**

SYSTEM RELEASE BULLETIN

Part Number: 5958-6019
E0187

Printed: **JANUARY 1987**

SSSSS	RRRRRR	BBBBBB
S S	R R	B B
S	R R	B B
SSSSS	RRRRRR	BBBBBB
S	R R	B B
S S	R R	B B
SSSSS	R R	BBBBBB

SYSTEM RELEASE BULLETIN

64000 Logic Development System

JANUARY 1987

This System Release Bulletin (SRB) documents all fixes and enhancements that are incorporated in the latest release of software for the 64000 Logic Development System.

The SRB is provided as a benefit of Hewlett-Packard's Software Support Services.

The five sections of the SRB are:

SOFTWARE RELEASE CONTENTS - lists the new revision codes for the 64000 products.

PRODUCT INDEX - lists product names and numbers which are included in this issue.

KPR NUMBER INDEX - sequential list of SR numbers.

KEYWORD INDEX - brief description of each SR.

KNOWN PROBLEM REPORTS - the actual reports.

Software release contents

Product name	Product number	uu.ff
*68000 ASSEMB	64845	01.11
*68000 ASSEMB	300 64845S004	01.10
*68000 ASSEMB	500 64845S001	01.50
*68000 ASSEMB	VAX 64845S003	01.70
*68HCII ASSEMB	64865	01.00
*68HCII ASSEMB	300 64865S004	01.00
*68HCII ASSEMB	500 64865S001	01.00
*68HCII ASSEMB	VAX 64865S003	01.00
*80286 EMULATION	64228	01.01
*8051 ASSEMB	64855	01.08
*8051 ASSEMB	300 64855S004	01.20
*8051 ASSEMB	500 64855S001	01.50
*8051 ASSEMB	VAX 64855S003	01.60
*8096 ASSEMB	64860	01.03
*8096 ASSEMB	300 64860S004	01.20
*8096 ASSEMB	500 64860S001	01.30
*8096 ASSEMB	VAX 64860S003	01.40
*F9450 EMULATION	64286	01.04
*HP TEAMWORK SA	300 64710S004	01.00
*SOFTKEY EDITOR	300 64790S004	01.00
*SW PERF ANALYZER	300 64310S004	01.10
*TMS 32010 MODULES	64285	01.01
*USER INTERFACE	300 64808S004	01.10
*USER INTERFACE	500 64808S001	01.10

Product index

Product name		Product number	Page
68000 ASSEMB	300	64845S004	1
68000 ASSEMB	500	64845S001	3
68000 ASSEMB	VAX	64845S003	5
8051 ASSEMB		64855	7
8051 ASSEMB	300	64855S004	9
8051 ASSEMB	500	64855S001	10
8051 ASSEMB	VAX	64855S003	11
8096 ASSEMB		64860	12
8096 ASSEMB	300	64860S004	15
8096 ASSEMB	500	64860S001	16
8096 ASSEMB	VAX	64860S003	17
F9450 EMULATION		64286	18

Report number index

Report #	page	Report #	page	Report #	page	Report #	page
5000129189	7	5000142463	13	D200053421	1	D200055269	18
5000129304	7	D200048314	3	D200053876	8	D200055301	16
5000133041	12	D200048322	5	D200054189	16	D200055319	17
5000133058	12	D200048330	1	D200054197	17	D200055327	15
5000133066	12	D200049296	4	D200054205	15	D200059451	2
5000133074	13	D200049304	6	D200054288	10	D200059501	2
5000133710	13	D200049312	2	D200054296	11	D200063172	19
5000136796	3	D200053405	3	D200054304	9	D200064261	19
5000141820	8	D200053413	5	D200054643	18	D200064279	19

Keyword index

- 68000 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
*****none*****	64845S004	00.00	Linker output file should use alternate file extension.	D200049312	2
	64845S004	01.00	Macro def. including .IF, within a IF causes assembler to stop code gen.	D200053421	1
	64845S004	01.00	Link_sym file contains bad data in relocatable name record.	D200059451	2
	64845S004	01.00	"-v" option does not work with asm inside pmon	D200059501	2
MACRO	64845S004	01.00	Conditional instr. .IF with rational oper. in Macro creates bad code	D200048330	1

- 68000 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
*****none*****	64845S001	00.00	Linker output file should use alternate file extension.	D200049296	4
	64845S001	01.40	Macro def. including .IF, within a IF causes assembler to stop code gen.	D200053405	3
ASSEMBLER	64845S001	01.40	LR error flagged for correct offset using PC+INDEX+OFFSET mode of addr.	5000136796	3
MACRO	64845S001	01.40	Conditional instr. .IF with rational oper. in Macro creates bad code	D200048314	3

- 68000 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
*****none*****	64845S003	00.00	Linker output file should use alternate file extension.	D200049304	6
	64845S003	01.50	Macro def. including .IF, within a IF causes assembler to stop code gen.	D200053413	5
MACRO	64845S003	01.50	Conditional instr. .IF with rational oper. in Macro creates bad code	D200048322	5

- 8051 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
*****none*****	64855	01.06	HIGH does not funct. correctly on label defined using DS	5000141820	8
CODE GENERATOR	64855	01.05	JMP command generates a SJUMP instead of a LJMP when jmping to ext label	5000129189	7
	64855	01.05	Incorrect opcode "MOV A,ACC" allowed by our assembler	5000129304	7
	64855	01.06	Relative offset from PC incorrectly calculated with the CJNE opcode	D200053876	8

- 8051 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
CODE GENERATOR	64855S004	01.00	Relative offset from PC incorrectly calculated with the CJNE opcode	D200054304	9

- 8051 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
CODE GENERATOR	64855S001	01.30	Relative offset from PC incorrectly calculated with the CJNE opcode	D200054288	10

- 8051 ASSEMB -

Keyword	Product number	uu.ff	Description	Report #	page
CODE GENERATOR	64855S003	01.40	Relative offset from PC incorrectly calculated with the CJNE opcode	D200054296	11

Keyword index

- 8096 ASSEMB -

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64860	01.00 DCW and DCB will not function with negative operands.	5000133041	12
	64860	01.00 SKIP listing control pseudo does not work.	5000133058	12
	64860	01.00 Linker generates incorrect absolute code.	5000133066	12
	64860	01.00 Problem with "CSEG" generating nonsense code	5000133074	13
	64860	01.00 Using indexed addressing mode with a label generates LR error.	5000133710	13
CODE GENERATOR	64860	01.02 8096 Jump instruc. w/ \$ as operand access PC after instr. instead before	5000142463	13

- 8096 ASSEMB -

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64860S004	01.00 SKIP listing control pseudo does not work.	D200054205	15
	64860S004	01.00 DCW and DCB will not function with negative operands.	D200055327	15

- 8096 ASSEMB -

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64860S001	01.10 SKIP listing control pseudo does not work.	D200054189	16
	64860S001	01.10 DCW and DCB will not function with negative operands.	D200055301	16

- 8096 ASSEMB -

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64860S003	01.20 SKIP listing control pseudo does not work.	D200054197	17
	64860S003	01.20 DCW and DCB will not function with negative operands.	D200055319	17

- F9450 EMULATION -

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64286	01.02 Keybd Simio drops last character if odd # typed in & CA in User Memory.	D200054643	18
	64286	01.02 Symbol INT_SER_PTR must be mapped to emul. memory for "break" to work.	D200055269	18
	64286	01.03 display memory_mnemonic may fail after display trace mnemonic	D200063172	19
	64286	01.03 The inverse assembler fails to show the mnemonic for a very short branch	D200064261	19
	64286	01.03 The inverse assembler may get confused in some cases.	D200064279	19

Number: D200048330 Product: 68000 ASSEMB 300 64845S004 01.00

Keywords: MACRO

One-line description:

Conditional instr. .IF with rational oper. in Macro creates bad code

Problem:

The use of the conditional instruction, .IF, with rational operator (.EQ.,.NE.,.LT.,.GT.,.LE.,.GE.) in a macro functions incorrectly. The following program demonstrates this problem:

```

BUG          MACRO          &VAR
              .IF &VAR .LE. 0 SUB&&&&
              NOP
              NOP
SUB&&&&      NOP
              NOP
              MEND

              BUG 3
              BUG -1
              BUG 0
              END

```

Passing a 3 appears to create correct code, but 0 causes a ML error. Passing -1 to the MACRO creates code which doesn't call the subroutine. This is incorrect since -1 is less than 0. This same problem occurred with all the rational operators on all processors. The problem was consistent on the 64000, VAX, and 9000.

Signed off 09/09/86 in release 401.10

Number: D200053421 Product: 68000 ASSEMB 300 64845S004 01.00

One-line description:

Macro def. including .IF, within a IF causes assembler to stop code gen.

Problem:

If you have a ".IF" in a macro definition and that macro definition is within a conditional assembly "IF" then no code is generated. The program provided demonstrates the problem.

"68000"

```

ESSAI        EQU            0
              IF            ESSAI

MAC           MACRO
              .IF            ESSAI.EQ.0      FIN
LABEL        MOVE          D3,D4
FIN          MEND

              MAC
              ENDIF

START        MOVE          D4,D5

```

- 68000 ASSEMB -

Temporary solution:

Pull the macro definition outside of the conditional if. No code will be generated for the definition.

"68000"

```

ESSAI        EQU            0

MAC           MACRO
              .IF            ESSAI.EQ.0      FIN
LABEL        MOVE          D3,D4
FIN          MEND

              IF            ESSAI
              MAC
              ENDIF

```

START MOVE D4,D5

Signed off 09/09/86 in release 401.10

Number: D200059451 Product: 68000 ASSEMB 300 64845S004 01.00

One-line description:

Link_sym file contains bad data in relocatable name record.

Number: D200059501 Product: 68000 ASSEMB 300 64845S004 01.00

One-line description:

"-v" option does not work with asm inside pmon

Problem:

Note that the status messages do not increment.

Number: D200049312 Product: 68000 ASSEMB 300 64845S004 00.00

One-line description:

Linker output file should use alternate file extension.

Signed off 09/09/86 in release 401.10

- 68000 ASSEMB -

Number: 5000136796 Product: 68000 ASSEMB 500 64845S001 01.40

Keywords: ASSEMBLER

One-line description:
LR error flagged for correct offset using PC+INDEX+OFFSET mode of addr.

Temporary solution:
Temporary solution:

"68000"

```

      ORG   OFFH
      MOVE  TABLE-($+2)[PC,D0],D1
TABLE DS   1

```

Number: D200048314 Product: 68000 ASSEMB 500 64845S001 01.40

Keywords: MACRO

One-line description:
Conditional instr. .IF with rational oper. in Macro creates bad code

Problem:
The use of the conditional instruction, .IF, with rational operator (.EQ.,.NE.,.LT.,.GT.,.LE.,.GE.) in a macro functions incorrectly. The following program demonstrates this problem:

```

      BUG          MACRO          &VAR
                      .IF &VAR .LE. 0 SUB&&&&
                      NOP
      SUB&&&&        NOP
                      NOP
                      MEND

                      BUG 3
                      BUG -1
                      BUG 0
                      END

```

Passing a 3 appears to create correct code, but 0 causes a ML error. Passing -1 to the MACRO creates code which doesn't call the subroutine. This is incorrect since -1 is less than 0. This same problem occurred with all the rational operators on all processors. The problem was consistent on the 64000, VAX, and 9000.

Signed off 09/09/86 in release 101.50

Number: D200053405 Product: 68000 ASSEMB 500 64845S001 01.40

One-line description:
Macro def. including .IF, within a IF causes assembler to stop code gen.

Problem:
If you have a ".IF" in a macro definition and that macro definition is within a conditional assembly "IF" then no code is generated.

- 68000 ASSEMB -

The program provided demonstrates the problem.

"68000"

```

ESSAI      EQU      0
           IF      ESSAI

MAC         MACRO
           .IF      ESSAI.EQ.0      FIN
LABEL      MOVE     D3,D4
FIN        MEND

           MAC
           ENDIF

START      MOVE     D4,D5

```

Temporary solution:
Pull the macro definition outside of the conditional if. No code will be generated for the definition.

"68000"

```

ESSAI      EQU      0

MAC         MACRO
           .IF      ESSAI.EQ.0      FIN
LABEL      MOVE     D3,D4
FIN        MEND

           IF      ESSAI
           MAC
           ENDIF

START      MOVE     D4,D5

```

Signed off 09/09/86 in release 101.50

Number: D200049296 Product: 68000 ASSEMB 500 64845S001 00.00

One-line description:
Linker output file should use alternate file extension.

Signed off 09/09/86 in release 101.50

- 68000 ASSEMB -

Number: D200048322 Product: 68000 ASSEMB VAX 64845S003 01.50

Keywords: MACRO

One-line description:

Conditional instr. .IF with rational oper. in Macro creates bad code

Problem:

The use of the conditional instruction, .IF, with rational operator (.EQ.,.NE.,.LT.,.GT.,.LE.,.GE.) in a macro functions incorrectly.

The following program demonstrates this problem:

```

      BUG          MACRO          &VAR
                  .IF &VAR .LE. 0 SUB&&&&
                  NOP
      SUB&&&&       NOP
                  NOP
                  MEND

                  BUG -3
                  BUG 1
                  BUG 0
                  END

```

Passing a 1 appears to create correct code, but 0 causes a ML error. Passing -3 to the MACRO creates code which doesn't call the subroutine. This is incorrect since -3 is less than 0. This same problem occurred with all the rational operators on all processors. The problem was consistent on the 64000, VAX, and 9000.

Signed off 09/09/86 in release 301.70

Number: D200053413 Product: 68000 ASSEMB VAX 64845S003 01.50

One-line description:

Macro def. including .IF, within a IF causes assembler to stop code gen.

Problem:

If you have a ".IF" in a macro definition and that macro definition is within a conditional assembly "IF" then no code is generated. The program provided demonstrates the problem.

"68000"

```

ESSAI          EQU          0
               IF          ESSAI

MAC            MACRO
               .IF          ESSAI.EQ.0      FIN
LABEL         MOVE          D3,D4
FIN           MEND

               MAC
               ENDIF

START         MOVE          D4,D5

```

- 68000 ASSEMB -

Temporary solution:

Pull the macro definition outside of the conditional if. No code will be generated for the definition.

"68000"

```

ESSAI          EQU          0

MAC            MACRO
               .IF          ESSAI.EQ.0      FIN
LABEL         MOVE          D3,D4
FIN           MEND

               IF          ESSAI
               MAC
               ENDIF

START         MOVE          D4,D5

```

Signed off 09/09/86 in release 301.70

Number: D200049304 Product: 68000 ASSEMB VAX 64845S003 00.00

One-line description:

Linker output file should use alternate file extension.

Signed off 09/09/86 in release 301.70

- 68000 ASSEMB -

Number: 5000129189 Product: 8051 ASSEMB 64855 01.05

Keywords: CODE GENERATOR

One-line description:

JMP command generates a SJUMP instead of a LJMP when jumping to ext label

Problem:

The following example generates a SJUMP when it should generate a LJMP:

```
"8051"
EXT SETUP
CSEG
ORG 0
JMP SETUP
END
```

This generates an out of range error during linking when SETUP has a value such that 8 signed bits cannot refer to it relative to opcode location. Since the EXT is assigned a value of 0000 by the assembler, it assumes that any org less than 80H needs only a SJUMP.

Temporary solution:

Use LJMP SETUP instead of JMP

or

Put the EXT's at the end of the file. For Example:

```
PROG
ORG 0
JMP SETUP      {opcode 20000 - LJMP}
EXT SETUP
END
```

Signed off 10/24/86 in release 501.08

Number: 5000129304 Product: 8051 ASSEMB 64855 01.05

Keywords: CODE GENERATOR

One-line description:

Incorrect opcode "MOV A,ACC" allowed by our assembler

Problem:

The instruction "MOV A,ACC" was assemble and emulated by our products; however, the Intel 8051 goes into the weeds at this instruction. At first glance the machine code in the assembler listing appears valid (MOV A,ACC ->0000 E5E0), but the bottom of page 8-35 in Intel's microcontroller handbook states: *MOV A,ACC is not a valid instruction.

Neither our manuals nor AMD's user manual mention this instruction.

Temporary solution:

No known temporary solution.

Signed off 10/24/86 in release 501.08

Number: 5000141820 Product: 8051 ASSEMB 64855 01.06

One-line description:

HIGH does not funct. correctly on label defined using DS

Problem:

The pseudo instruction HIGH does not function properly when operating on a label that was defined with the DS pseudo

For example:

```
"8051"
ORG 1234H
LABEL1 EQU $
LABEL2 EQU 3344H
LABEL3 DS 1
MOV A,#HIGH(LABEL1) correct - moves 12H into A
MOV A,#HIGH(LABEL2) correct - moves 33H into A
MOV A,#HIGH(LABEL3) wrong - moves 34H into A
MOV DPTR,#LABEL3 correct - moves 1234H into DPTR
```

Temporary solution:

No known temporary solution.

Signed off 10/24/86 in release 501.08

Number: D200053876 Product: 8051 ASSEMB 64855 01.06

Keywords: CODE GENERATOR

One-line description:

Relative offset from PC incorrectly calculated with the CJNE opcode

Problem:

The assembler generates B413FE for the following statement:

```
CJNE A,#13H,$+1
```

The first byte (B4) is the correct opcode for CJNE, and the second byte (13) is the correct representation for the immediate data. The third byte (FE) is not the correct relative offset.

Temporary solution:

No known temporary solution.

Signed off 10/24/86 in release 501.08

SRB detail reports as of 10/24/86

Page: 9

Number: D200054304 Product: 8051 ASSEMB 300 64855S004 01.00

Keywords: CODE GENERATOR

One-line description:
Relative offset from PC incorrectly calculated with the CJNE opcode

Problem:
The assembler generates B413FE for the following statement:
CJNE A,#13H,\$+1

The first byte (B4) is the correct opcode for CJNE, and the second
byte (13) is the correct representation for the immediate data.
The third byte (FE) is not the correct relative offset.

Temporary solution:
No known temporary solution.

- 8051 ASSEMB -

SRB detail reports as of 10/24/86

Page: 10

Number: D200054288 Product: 8051 ASSEMB 500 64855S001 01.30

Keywords: CODE GENERATOR

One-line description:
Relative offset from PC incorrectly calculated with the CJNE opcode

Problem:
The assembler generates B413FE for the following statement:
CJNE A,#13H,\$+1

The first byte (B4) is the correct opcode for CJNE, and the second
byte (13) is the correct representation for the immediate data.
The third byte (FE) is not the correct relative offset.

Temporary solution:
No known temporary solution.

- 8051 ASSEMB -

SRB detail reports as of 10/24/86 Page: 11
Number: D200054296 Product: 8051 ASSEMB VAX 64855S003 01.40

Keywords: CODE GENERATOR

One-line description:
Relative offset from PC incorrectly calculated with the CJNE opcode

Problem:
The assembler generates B413FE for the following statement:
CJNE A,#13H,\$+1

The first byte (B4) is the correct opcode for CJNE, and the second
byte (13) is the correct representation for the immediate data.
The third byte (FE) is not the correct relative offset.

Temporary solution:
No known temporary solution.

- 8051 ASSEMB -

SRB detail reports as of 10/24/86 Page: 12
Number: 5000133041 Product: 8096 ASSEMB 64860 01.00

One-line description:
DCW and DCB will not function with negative operands.

Problem:
An assembler error is generated if the operand of a DCB or DCW
instruction is a negative number. According to the manual,
negative values in the legal range are valid operands.

"8096"

```
LABEL1 DCB -10  
          ^IC - Illegal constant, illegal character found  
          in constant
```

Temporary solution:
No known temporary solution.

Signed off 10/24/86 in release 001.03

Number: 5000133058 Product: 8096 ASSEMB 64860 01.00

One-line description:
SKIP listing control pseudo does not work.

Problem:
The SKIP listing control instruction does not work. It generates
assembler errors when used in the source program.

Temporary solution:
Insert formfeeds (control L) in the listing file before printing
it.

Signed off 10/24/86 in release 001.03

Number: 5000133066 Product: 8096 ASSEMB 64860 01.00

One-line description:
Linker generates incorrect absolute code.

Problem:
If the following code is assembled and linked with PROG at
2080H, the absolute code is incorrect at address 200CH. Instead
of generating 2084H, it generates 2480H.

"8096"

```
PROG  
LD SP,#100H  
L1 PUSHE  
   ORG 200CH  
   DCW L1
```

Temporary solution:
No known temporary solution.

Signed off 10/24/86 in release 001.03

- 8096 ASSEMB -

 Number: 5000133074 Product: 8096 ASSEMB 64860 01.00

 One-line description:
 Problem with "CSEG" generating nonsense code

Signed off 10/24/86 in release 001.03

 Number: 5000133710 Product: 8096 ASSEMB 64860 01.00

 One-line description:
 Using indexed addressing mode with a label generates LR error.

 Problem:
 The following code generates a legal range (LR) error when the indexed addressing mode is used. Also, the code generated for the SJMP instruction is incorrect.

```

"8096"
AX      EQU      30H
BX      EQU      31H

        ORG      2800H
LDB     AX, TABLE[BX]
        ^LR ERROR
        SJMP     L1 (*The code generated is 2001, but should be 2002*)
        CLR     AX
L1:     NOP

        ORG      2986H
TABLE   DCB      0
  
```

 Temporary solution:
 No known temporary solution.

Signed off 10/24/86 in release 001.03

 Number: 5000142463 Product: 8096 ASSEMB 64860 01.02

Keywords: CODE GENERATOR

 One-line description:
 8096 Jump instruc. w/ \$ as operand access PC after instr. instead before

 Problem:
 All 8096 jump instructions using \$ as an operand use the PC value after the jump instruction. It should use the PC value prior to this instruction executing.
 For example,

			opcodes	
			actual	expected
"8096"				
IOSO	EQU	15H		
	JGE	\$	D6FF	D6FE
	JBS	IOSO,7,\$	3F15FF	3F15FD

Temporary solution:

- 8096 ASSEMB -

No known temporary solution.

Signed off 10/24/86 in release 001.03

- 8096 ASSEMB -

SRB detail reports as of 10/24/86

Page: 15

Number: D200054205 Product: 8096 ASSEMB 300 64860S004 01.00

One-line description:
SKIP listing control pseudo does not work.

Problem:
The SKIP listing control instruction does not work. It generates assembler errors when used in the source program.

Temporary solution:
Insert formfeeds (control L) in the listing file before printing it.

Number: D200055327 Product: 8096 ASSEMB 300 64860S004 01.00

One-line description:
DCW and DCB will not function with negative operands.

Problem:
An assembler error is generated if the operand of a DCB or DCW instruction is a negative number. According to the manual, negative values in the legal range are valid operands.

"8096"

LABEL1 DCB -10
^IC - Illegal constant, illegal character found
in constant

Temporary solution:
No known temporary solution.

SRB detail reports as of 10/24/86

Page: 16

Number: D200054189 Product: 8096 ASSEMB 500 64860S001 01.10

One-line description:
SKIP listing control pseudo does not work.

Problem:
The SKIP listing control instruction does not work. It generates assembler errors when used in the source program.

Temporary solution:
Insert formfeeds (control L) in the listing file before printing it.

Number: D200055301 Product: 8096 ASSEMB 500 64860S001 01.10

One-line description:
DCW and DCB will not function with negative operands.

Problem:
An assembler error is generated if the operand of a DCB or DCW instruction is a negative number. According to the manual, negative values in the legal range are valid operands.

"8096"

LABEL1 DCB -10
^IC - Illegal constant, illegal character found
in constant

Temporary solution:
No known temporary solution.

SRB detail reports as of 10/24/86 Page: 17
Number: D200054197 Product: 8096 ASSEMB VAX 64860S003 01.20

One-line description:
SKIP listing control pseudo does not work.

Problem:
The SKIP listing control instruction does not work. It generates assembler errors when used in the source program.

Temporary solution:
Insert formfeeds (control L) in the listing file before printing it.

Number: D200055319 Product: 8096 ASSEMB VAX 64860S003 01.20

One-line description:
DCW and DCB will not function with negative operands.

Problem:
An assembler error is generated if the operand of a DCB or DCW instruction is a negative number. According to the manual, negative values in the legal range are valid operands.

"8096"
LABEL1 DCB -10
^IC - Illegal constant, illegal character found
in constant

Temporary solution:
No known temporary solution.

SRB detail reports as of 10/24/86 Page: 18
Number: D200054643 Product: F9450 EMULATION 64286 01.02

One-line description:
Keybd Simio drops last character if odd # typed in & CA in User Memory.

Temporary solution:
Two temporary fixes exist for this problem.

- 1) Put the Control Address in emulation memory.
- 2) Modify the emulation monitor to the following:

Old Code:(Existing Monitor)	New Code:(Modified Monitor)
508 L R11,PRAM4 Byte Count.	508 L R11,PRAM4 Byte Count.
509 SRL R11,1 Word Count.	508.1 TBR 0,R11 Test for even count.
	508.2 BNZ EVEN Even, so skip
	508.3 AIM R11,1 Make Count Even
	508.4EVEN
	509 SRL R11,1 Word Count.

Signed off 10/24/86 in release 601.04

Number: D200055269 Product: F9450 EMULATION 64286 01.02

One-line description:
Symbol INT_SER_PTR must be mapped to emul. memory for "break" to work.

Problem:
If the symbol INT_SER_PTR from the emulation boot routine is not mapped to emulation memory, then the internal jam-registers of the emulator are not programmed. The internal jam-registers are programmed with the two addresses INT_SER_PTR and LINKAGE_PTR so that the emulator will be able to break into the monitor properly. It may be desirable to map the address location INT_SER_PTR to user memory since INT_SER_PTR must be located in address state 0 and the user can very well program the three words associated with INT_SER_PTR in user ROM. As it is now, INT_SER_PTR must be in emulation memory in address state 0, necessitating that the user map a whole 2K block of address state 0 as emulation memory.

Temporary solution:
Two work-arounds exist for this problem.

- 1) To avoid having to map a 2K block of memory in address state 0 as emulation memory, first map the INT_SER_PTR location as emulation memory, load the absolute file thus programming the appropriate address for INT_SER_PTR, then modify the configuration remapping address state 0 as user memory as desired. For this method to work, it is the user's responsibility to be sure that the INT_SER_PTR location in user memory is appropriately programmed.
- 2) To avoid having to map a 2K block of memory in address state 0 as emulation memory, first re-link your absolute file, moving the module that contains INT_SER_PTR to an available address state mapped as emulation memory. Load the absolute file. Note that the jam-register is programmed only with the lower 16 bits

of the INT_SER_PTR address. Now, you must be sure that you have the appropriate locations in address state 0 programmed with the correct values. For example, if you re-linked such that INT_SER_PTR was located at 31234H, the jam register would be programmed with 1234H, and therefore you should be sure that user memory at 1234H is programmed with the correct values.

Signed off 10/24/86 in release 601.04

Number: D200063172 Product: F9450 EMULATION 64286 01.03

One-line description:
display memory mnemonic may fail after display trace mnemonic

Problem:
Display memory mnemonic will show all "unused prefetch"'s if the last trace display had an "unused prefetch" as the last disassembled state.

Signed off 10/24/86 in release 601.04

Number: D200064279 Product: F9450 EMULATION 64286 01.03

One-line description:
The inverse assembler may get confused in some cases.

Problem:
In some cases, the inverse assembler will fail to properly perform inverse assembly. For example:

```
LIM R1,1234H
OR R1,5678H
AND R1,6789H
JS R13,4321H <---- THIS INSTRUCTION IS MARKED AS AN UNUSED
JC 07H,0,R12   PREFETCH
```

Signed off 10/24/86 in release 601.04

Number: D200064261 Product: F9450 EMULATION 64286 01.03

One-line description:
The inverse assembler fails to show the mnemonic for a very short branch

Signed off 10/24/86 in release 601.04



5958-6019, January 1987
E0187

Printed in U.S.A.