

PRODUCT IMPROVEMENT BULLETIN

PERIPHERAL EQUIPMENT DIVISION

TITLE OPTICAL SECTOR TRANSDUCER DETERIORATION					DK 3018 &
TAPE [] LINE. FORMATTER []	EQUIPMENT CHA All Logic Po		DDEL SERIES AFF D3000		effective date pril 5, 1976
CLASS OF BULLETIN: IMPROVEMENT RETROFIT ON FAILURE RETROFIT RECOMMENDED SERVICE INFORMATION ONLY	C	DRDER PART KIT NO. N/A	replaces P	PIB DK3018	TY es.PIB DK3018B A in its entirety. PIB DK3018A.

PURPOSE

In an emergency, an upper sector transducer with low amplitude can possibly be revived for an undetermined period of time. Removal of a jumper from the Logic PCBA, effectively doubles the gain of operation amplifier, U425. Reinstallation of the jumper is mandatory when the optical sector transducer (P/N 102685) is replaced. Failure to do so will shorten the life of the amplifier circuitry. Because this "QUICK FIX" is not permanent, replacement of the optical transducer assembly (P/N 102685) is recommended as soon as possible.

SYMPTOMS

- Unexplainable controller time outs
- Missing sector pulses
- Intermittent sector errors
- , Low amplitude at Logic PCBA test point E2 (reference Figure 1)




FIGURE 1 - (MINIMUM ACCEPTANCE LEVEL)

PARTS

None

TOOLS

No special tools required

REWORK INSTRUCTIONS

- 1. Remove W19 if standard PERTEC Logic PCBA or W20 if DIABLO Compatible.
- Place parts order for optical sector transducer assembly (P/N 102685).

TEST PROCEDURE

None

DRAWING CHANGES

None

TIME REQUIRED

One half hour

ould Additional Information Be Required — Contact

DISTRIBUTION CODE - 6318

PERTEC

PERIPHERAL EQUIPMENT DIVISION
9600 Irondale Avenue, Chatsworth, California 91311
Phone (213) 882-0030 / TWX (910) 494-2093
ATTENTION: PRODUCT SUPPORT MANAGER
PERTEC 20:K012G(1)