

SUBJECT: IDENTIFICATION AND CONVERSION OF FLASHWRITER II BOARD UNITS AFFECTED: ALL SYSTEMS	MODEL: V3	V3-0026
	DATE: 8 DEC. 1981	PAGE: 1 OF 1

**CONDITION:** Identification of the different versions of the Flashwriter II PCB.

**CORRECTION:** The list below contains a brief summary of identifying features and conversion procedures of the Flashwriter II Board.

### FWII PCBA

#### #3514-0000 4Mhz VERSION

**Identifying Features:** Area "S" does not have a two pin molex connector. Does not have added resistor between pin 13 of IC U13 and ground. Memory chips at location U17, U18, U31, and U32 will be either #2114-3 or #2114-4.

#### #3514-0000 4/6Mhz VERSION

**Identifying Features:** The IC's at U17, U18, U31, and U32 must be #2114-2 and there will be a added 1K resistor(R-19) connecting pin 13 of U13 to pin 7 of U-14.

**NOTE:** Maybe used in either 4Mhz or 6Mhz, no modifications required.

#### #3514-0006 6Mhz VERSION FOR MULTI-USER SYSTEMS

**Identifying Features:** This version has a wire (part #3599-0000) terminated with a two pin female molex connector, from pad 2 of Area "S" (to right of C28) or a two pin male molex connector in Area "S". A wire connection has been made between pin 15 of U39 and pad 1 of area "S". Also the trace between pad 1 and pad 2 of area "S" has been cut. Jumper area "L" may be cut-software dependent.

**To convert to 4/6Mhz for other than 5005 systems:** Jumper the two pads 1 and 2 together in area "S" (C-28).

#### #3514-0008 4/6Mhz VERSION

**Identifying Features:** The IC's at U17, U18, U31, and U32, must be #2114-2 and the traces have been added to R19 which is now between U39 and U40. Does not have a wire soldered in Pad 2 of Area "S".

**NOTE:** Maybe used in 4Mhz or 6Mhz; no modification required.

<b>SUBJECT:</b> <b>FWII REV.7</b>	<b>MODEL FWII</b>	<b>VIA# V3-014</b>
	<b>DATE 4/22/81</b>	<b>PAGE 1 of 5</b>

**UNITS EFFECTED: ALL SYSTEMS**

Category: As required, Not Field Mandatory FLASHWRITER II, Rev 7

*U30-8 to U30-7*

The addition of the 100 pf capacitor, C31, which created Rev 6 of the FW II PCB, did not sufficiently, compensate for the difference in various 2114 Ram manufacturer's specifications that impact timing and race conditions. Vector now recommends removing the 100 pf capacitor and implementing the following procedures:


Component Side:

1. Cut the trace between U29 and U30, which passes between pins U30-6 & 7, and U 29-10 & 11.
2. Add a 1K resistor between U13-13 and U14-7. Solder the resistor directly to the I.C. pins. The top lead of the resistor should not touch the lower lead of C6.


Circuit Side:


1. Install a jumper between U30-9 and U13-10.
2. Install a jumper between U13-11 and U13-12.
3. Install a jumper between U13-13 and U28-11.
4. Install a jumper between U28-12 and the feed-through hole just to the right of U29-10. (*Under U29*)


This will be revision 7 of the Flashwriter II PCBA.




u28 IS USED TO EXPAND u30. (NO SPARE LS10 IS AVAILABLE ON THE BOARD.)







CIRCUIT SIDE



CONVERSION OF FLASHWRITER II	FLASHWRITER II	VTA# V3-0028
	FEB. 20 1980	PAGE 1 OF 2


AFFECTED UNITS: FLASHWRITER II REV. 3.

The following will explain the cuts and jumpers necessary to incorporate the APL Character Generator PROMs on the Flashwriter II Rev. 3.

Previous instructions sent with each order of APL were for rev. 2 only.

I. For INTEL 2716 or TMS 2516 only--

A) Add switch as shown below



B) Cut etches Jumper from

I1-I2	B1-B3
E1-E4	E1-E5
E2-E5	

C) Insert APL PROMs at U22 and U23


Use APL TMS 2516 or INTEL 2716 at U22  
Use APL 2708 at U23

CONVERSION OF FLASHWRITER II	FLASHWRITER II	VTA# V3-0028
	FEB. 20 1980	PAGE 2 OF 2

FLASHWRITER II Rev.3 APL MODIFICATION

II. For TMS 2716 proms only -

A) Add switch as shown below



B) Cut Etches

- I1 to I2
- E1 to E4
- E2 to E5
- E3 to E9
- trace from U22-18

Jumper from

- B1 to B2
- E1 to E3
- E2 to E6
- E5 to U22-18

C) Insert APL PROMs at U22 and U23

- Use APL TMS 2716 at U22
- Use APL 2708 at U23



# PRODUCT IMPROVEMENT BULLETIN

PART FW II	DATE 4-21-80	NUMBER 0063
---------------	-----------------	----------------

REASON:

Intermittent memory errors caused by marginal timing in retrace wait circuit.

DESCRIPTION OF CHANGE:

Add 470 pF (P/N 13-2479) between U30-8 and U30-7.

EFFECTIVITY: All new production	PRIORITY
------------------------------------	----------

ORIG. R. Dieges	DATE 4-21-80
APPVD. R. Harp <i>R.H.</i>	DATE 4-21-80

DISTRIBUTION:

- PRODUCTION
- TEST
- QA
- MATERIAL
- PURCHASING
- FIELD

# PRODUCT IMPROVEMENT BULLETIN

RT

FW II for Vector 3

DATE

4-24-80

NUMBER

0065

## REASON:

Eliminate need for MTI bd. in Vector 3.

## DESCRIPTION OF CHANGE:

1. Replace R4(100 ohm) with 330 ohm 1/4W 5%.
2. Replace R6(68 ohm) with jumper wire.
3. Replace C2(470 pF) with 150 pF capacitor.
4. Remove R5(150 ohm).
5. Cut leg 10 of U10 from board.
6. Place jumper from one hole on right side of optional R3 to second hole on right side of R3. (Jumper these optional holes together.)
7. Add 150 pF cap to contrast pot.  
Solder capacitor leads to potentiometer leads where blue wires are soldered.

EFFECTIVITY:

Immediate

PRIORITY

RIG.

M. Musial

DATE 4/24/80

APPVD.

*R. Hays*

DATE

## DISTRIBUTION:

PRODUCTION

TEST

QA

MATERIAL

PURCHASING

FIELD



VECTOR GRAPHIC INC.

# PRODUCT IMPROVEMENT BULLETIN

ART

Flashwriter II

DATE

4/8/80

NUMBER 0061

REASON:

In order to test the optional monitor socket on FWII boards.

DESCRIPTION OF CHANGE:

Install 20 pin socket in U43 position on all production boards.

EFFECTIVITY: Immediate

PRIORITY

ORIG. Mark Musial

DATE 4/8/80

APPVD. *P. Hap*

DATE 4/17/80



DISTRIBUTION:

PRODUCTION

MATERIAL

TEST

PURCHASING

QA

FIELD

# PRODUCT IMPROVEMENT BULLETIN

PART Flashwriter II	DATE 2-1-80	NUMBER 0055
------------------------	----------------	----------------

REASON:

All Flashwriter II boards will have the jumper installed in area L for generating interrupts. All FW IIs will respond to keyboard input under WMS software.

DESCRIPTION OF CHANGE:

Jumper installed in area L by P.C.B. assemblers.

EFFECTIVITY: February 4, 1980

*M. Musial*

PRIORITY  
*New Prod. only.*

ORIG. M. Musial	DATE 2-1-80
APPVD. R. Harp <i>R.H.</i>	DATE 2-1-80

DISTRIBUTION:

- PRODUCTION
- TEST
- QA
- MATERIAL
- PURCHASING
- FIELD



**VECTOR GRAPHIC INC.**

# PRODUCT IMPROVEMENT BULLETIN

PART	FLASHWRITER 2 VIDEO BOARD	DATE	1/29/80	NUMBER	0054
------	---------------------------	------	---------	--------	------

REASON:

1. TO ELIMINATE NEED FOR MTI BOARD IN VECTOR 3
2. TO ELIMINATE "SWIMMING VIDEO"

DESCRIPTION OF CHANGE:

1. CHANGE R4 FROM A 100 OHM 1/4 WATT RESISTOR TO A 330 OHM 1/4 WATT RESISTOR
2. DELETE R5, A 150 OHM, 1/4 WATT RESISTOR
3. DELETE R6, A 68 OHM, 1/4 WATT RESISTOR AND PLACE A JUMPER WIRE IN ITS PLACE
4. CHANGE THE 14.31818MHz CRYSTAL TO A 14.3347MHz CRYSTAL

MAKE THE FOLLOWING CHANGES TO FLASHWRITER 2 PARTS LIST

ACTION	QTY	PART DESCRIPTION	PART NUMBER
DELETE	1	RESISTOR, 100 OHM, 1/4 WATT	14-1101
ADD	1	RESISTOR, 330 OHM, 1/4 WATT	14-1331
DELETE	1	RESISTOR, 150 OHM, 1/4 WATT	14-1151
DELETE	1	RESISTOR, 68 OHM, 1/4 WATT	14-1680
DELETE	1	CRYSTAL, 14.318MHz	19-1004
ADD	1	CRYSTAL, 14.3347MHz	19-1006

EFFECTIVITY:

FLASHWRITER 2'S INSTALLED IN VECTOR 3 CHASSIS

PRIORITY

ORIG. <i>C. SECOR</i>	DATE <i>1/29</i>
APPVD. <i>R. Hay</i>	DATE

DISTRIBUTION:

- PRODUCTION
- TEST
- QA

- MATERIAL
- PURCHASING
- FIELD

# PRODUCT IMPROVEMENT BULLETIN

PART flashwriter 2	DATE 9/7/79	NUMBER 0043
-----------------------	----------------	----------------

REASON: The 16 Ga. Wire now used is difficult to install and dress and puts stress on connector JZ.

## DESCRIPTION OF CHANGE:

Use 18 or 20 Ga. wire for connector to J2 on flashwriter.

EFFECTIVITY:

9/7/79

PRIORITY

Normal

ORIG. B. Jones	DATE 9/7/79
APPVD. R. Harp	DATE 9/7/79

## DISTRIBUTION:

- PRODUCTION
- TEST
- QA

- MATERIAL
- PURCHASING
- FIELD

# PRODUCT IMPROVEMENT BULLETIN

PART FW 11	DATE 8/9/79	NUMBER 0039
---------------	----------------	----------------

**REASON:**

To remove decoding glitch on output of U 2.

**DESCRIPTION OF CHANGE:**

Add 150 PF capacitor (P1N13-1159) between U2 pin and U2 pin 8.

EFFECTIVITY: All FW 11

PRIORITY

ORIG. <i>R. D. ...</i>	DATE 8/14/79
APPVD. <i>P. Hay</i>	DATE 8/22/79

**DISTRIBUTION:**

- PRODUCTION
- TEST
- QA

- MATERIAL
- PURCHASING
- FIELD

# PRODUCT IMPROVEMENT BULLETIN

PART FW II	DATE 8-7-79	NUMBER 0038
---------------	----------------	----------------

REASON:

FW II does not work at 2 MHz

DESCRIPTION OF CHANGE:

Change R13 and R14 to 560 r 1/4W 5%

EFFECTIVITY: All new Production

PRIORITY

ORIG. R. Dieges	DATE 8/7/79
APPVDR. Harp	DATE 8/7/79

DISTRIBUTION:

- PRODUCTION
- TEST
- QA

- MATERIAL
- PURCHASING
- FIELD



# PRODUCT IMPROVEMENT BULLETIN

<b>PART</b> FLASHWRITER II	<b>DATE</b> 1-18-79	<b>NUMBER</b> 0024
-------------------------------	------------------------	-----------------------

**REASON:** TO REMOVE GLITCHES ON VIDEO OUTPUT SIGNAL

**DESCRIPTION OF CHANGE:**

ADD 100pf CAPACITOR BETWEEN U19-7 AND U19-8

**EFFECTIVITY:** ALL PRODUCTION

**PRIORITY**

<b>ORIG.</b>	<b>DATE</b> 1-18-79
<b>APPVD.</b>	<b>DATE</b> 1-19-79

**DISTRIBUTION:**

- PRODUCTION
- TEST
- QA

- MATERIAL
- PURCHASING
- FIELD

