Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4912-Ø2
Description	TRSDOS II
Model	Model II/12/16
Stock No.	26-4912 Ver. Ø4.Ø2.Ø1
Date	May 18, 1983
Page 1 of	1

Problem

Errors are occurring after SPOOL followed by a DO filename command. If SPOOL is on, the error 'OPEN ATTEMPT FOR FILE ALREADY OPEN' is returned. If SPOOL is off, the error 'PARAMETER FOR OPEN IS INCORRECT' is returned.

* * THE FOLLOWING PATCHES ARE REQUIRED FOR USE WITH ENHANCED MODEL II/12 AND MODEL 16! * *

Solution

After patches from this Bulletin have been applied, the version number will be Ø4.Ø2.Ø2. Please make the necessary entry in your Version Log.

```
PATCH IFC R=6 B=187 F=2143ØØ C=C38E3C
PATCH IFC R=11 B=135 F=ØØØØØØØØØØØØ C=21C8FC2281FC
PATCH IFC R=11 B=141 F=ØØØØØØØØØØØØ C=21C8FE2283FC
PATCH IFC R=11 B=147 F=ØØØØØØØØØØØØ C=2143ØØC3D937
```