

Please substitute this page for the similar page in your manual.

March 5, 1977

CPA REV 4 MODIFICATION (*done 25 March 83*)

Modification to cause front panel to always come up in "stop" mode at power-up time.

- 1) Cut (comp. side) U-22 pin 11 free. (U-22 pin 11 was connected to U-22 pin 4 (ground) by a heavy trace under the chip.)
- 2) Connect (solder side) U-18 pin 13 to U-16 pins 11 and 12. Connect wire at the pads.
- 3) Connect (solder side) U-16 pin 13 to U-22 pin 11. Connect wire at the pads.

