

TITLE ELIMINATION OF BRUSHES AND BRUSH MOTOR				PIB NO. DK3076	
PRODUCT LINE:		TAPE DISK FORMATTER <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	EQUIPMENT CHANGED	MODEL SERIES AFFECTED D3X1X; D3X2X	EFFECTIVE DATE July 5, 1978
CLASS OF BULLETIN:		ECN NO.	EFFECTIVITY <i>New units being built at factory</i>		
<input type="checkbox"/> IMPROVEMENT		PARTS KIT NO.			
<input type="checkbox"/> RETROFIT ON FAILURE		TIME REQ.			
<input type="checkbox"/> RETROFIT RECOMMENDED					
<input checked="" type="checkbox"/> SERVICE INFORMATION ONLY					
<p><i>Pertec has eliminated the disk cleaning brushes and brush motor from top loading D3000 disk drives. It has been found that, by eliminating the brush opening into the disk cavities, the particle count is reduced due to increased cavity pressure.</i></p> <p><i>Should replacement of brushes or brush motor be required, this change may be implemented to eliminate the disk cleaning brushes and brush motor in units already in the field when the kit becomes available in the future.</i></p> <p><i>At such time as the kit becomes available, a PIB with the kit number and installation instructions will be published.</i></p>					

Should Additional Information Be Required - Contact

Distribution Code: 6318