

# SERVICE LETTER

Date: January 5, 1973  
DK3001  
(Number Disk 025 )

Subject: D3000 DISKS FAILING INITIAL CHECKOUT

Reference: Molex Connector Seating

D3000 Disk failures experienced during initial check-out after shipment have been traced to faulty contact between connector pins and the molex connectors. If failures are encountered on initial checkout, the molex connectors on cards A100, A200, A300 and A400 should be checked for proper seating.

**PERTEC**