

# SERVICE LETTER

DATE: 5/3/73

NUMBER: DK3007

SUBJECT: ELECTRONIC SECTOR TO MECHANICAL SECTOR  
CONVERSION OF D3000 DISK DRIVES

PRODUCT EFFECTED: Mechanically sectored D3000 Disk Drives

INFORMATION: It has been disclosed that due to a compatibility problem between spindles in the D3000 disk drives a unit originally shipped from the factory as a mechanically sectored unit will not be able to be converted in the field to an electronically sectored unit. There are no restrictions in the conversion of an electronically sectored unit to a mechanically sectored unit however.

This restriction applies to all D3000 series mechanically sectored disk drives shipped from the plant with the first two digits of the serial number being either 42, 13 or 23.

ACTION: None

DIAGRAM  
CORRECTION: None