

# CUSTOMER SERVICE BULLETIN

## Radio Shack<sup>®</sup> CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	4716-02
<b>Description</b>	Bisync
<b>Model</b>	Model II
<b>Stock No.</b>	26-4716 Version 1.0
<b>Date</b>	Dec. 16, 1981
<b>Page 1 of</b>	1

### Problem

The following patch corrects problems with form feeds when using the 26-4716 Bisync Package. The problem is characterized by invalid 'line skips' and 'page ejects'.

### Solution

The following patch corrects the problem and should result in properly printed documents.

1. Make a backup copy of your Bisync 26-4716 Package.
2. At TRSDOS READY apply the following Patch to your diskette.

PATCH BIS3780 A=4BDD,F=C3EC,C=C3BE