RH11-RS03/4

RH11-RS03-RS03/LA-RS04

MD-11-DZRSB-F

BASIC FUNCTION

EP-DZRSB-F-DL

FICHE 1 OF 1

DEC 1977

digital

MADE IN USA

EOF1DZRP2CSEQ	00010000	771114	PDP10 411	ONHDR1DZRSBFSEQ	00010000 771114

```
2588
2589
2590
```

.REM ə

IDENTIFICATION

PRODUCT CODE:	MAINDEC-11-DZRSB-F-D
PRODUCT NAME:	RH11-RS03-RS03/LA-RS04 BASIC FUNCTION DIAGNOSTIC
DATE CREATED:	JULY 1977
MAINTAINER:	DIAGNOSTIC GROUP

CONTENTS

DESCRIPTION

1. ABSTRACT

THIS DIAGNOSTIC WAS DESIGNED TO TEST RS03,RS03/LA AND RS04 DRIVES.

THIS IS A BASIC FUNCTION DIAGNOSTIC WHICH IS USED TO VERIFY THAT THE (RH11) CONTROLLER AND THE (RS03,RS03/LA OR RS04) DISKS ARE OPERATING CORRECTLY. THIS IS NOT A RELIABILITY DIAGNOSTIC AND THEREFORE SHOULD NOT BE USED AS ONE. THIS PROGRAM CAN TEST UP TO 8 DRIVES. THE DRIVES CAN BE INTERMIXED AND IN ANY ORDER.

IF THE OPERATOR WOULD LIKE TO CHECK THE DISK REGISTERS PRIOR TO ENTERING THIS DIAGNOSTIC, THERE ARE SOME ROUTINES IN THE BACK OF THE DIAGNOSTIC WHICH CAN BE USED. THESE ROUTINES WILL ALLOW THE OPERATOR TO LOAD THE REGISTERS THROUGH THE SWITCHES. PLEASE REFERENCE THE STARTING ADDRESSES THAT WILL TEST THE REGISTERS YOU DESIRE.

2. REQUIREMENTS

2.1 EQUIPMENT

PDP11 STANDARD COMPUTER WITH A MINIMUM OK 8K OF MEMORY, AND AN RH11 CONTROLLER WITH A RS03, RS03/LA OR RS04 DISK.

2.3 PRELIMINARY PROGRAMS

NONE

3. LOADING PROCEDURE

USE STANDARD PROCEDURE FOR ABS TAPES.

4. STARTING PROCEDURE

4.1 CONTROL SWITCH SETTINGS

SEE 5.1.1 (ALL DOWN FOR WORST CASE TESTING)

4.2 STARTING ADDRESS

4.3 PROGRAM AND/OR OPERATOR ACTION

LOAD PROGRAM INTO MEMORY USING ABS LOADER.

1. STARTING ADDRESS 200.

   A. SET SWITCHES (SEE SEC 5.1.1) ALL DOWN FOR WORST CASE. IF SWITCHLESS CPU, SIMPLY
   B. PRESS START.
   C. THE PROGRAM WILL LOOP AND BELL WILL RING ONCE EVERY PASS
   D. THE DISPLAY ON THE 11/45 WILL SHOW THE ITERATION COUNT IN THE LEFT BYTE AND TEST NUMBER IN THE RIGHT. TO USE, SET THE DATA DISPLAY SWITCH TO THE DISPLAY POSITION.
   E. THE PROGRAM WILL TEST ALL RS03, RS03/LA AND RS04 DISKS.

2. STARTING ADDRESSES FOR TESTING THE RH11-RS03/LA/04 REGISTERS USING THE SWITCH REGISTER. ON SWITCH-LESS MACHINES THESE ROUTINES ARE USEFULL FOR SCOPING. SIMPLY STRIKE ↑G ANYTIME AFTER PRESSING START TO ENTER OR CHANGE VALUE DESIRED.

   A. 250 WORD COUNT REGISTER TEST
   B. 254 BUS ADDRESS REG. TEST
   C. 260 DISK ADDRESS REG. TEST
   D. 264 DRIVE STATUS REG. TEST
   E. 270 ERROR REG. TEST
   F. 274 LOOK AHEAD REG. TEST
   G. 300 RSCS2 REG. TEST
   H. 304 ATTENTION SUMMARY REG. TEST
   I. 310 MAINTENANCE REG. TEST
   J. 314 RSCS1 REG TEST

5. OPERATIONAL SWITCH SETTINGS

THIS PROGRAM HAS BEEN MODIFIED TO RUN ON A PROCESSOR WITH OR WITHOUT A HARDWARE SWITCH REGISTER. WHEN FIRST EXECUTED THE PROGRAM TESTS THE EXISTENCE OF A HARDWARE SWITCH REGISTER. IF NOT FOUND A SOFTWARE SWITCH REGISTER LOCATION (SWREG=LOC.176) IS DEFAULTED TO. IF THIS IS THE CASE, UPON EXECUTION THE CONTENTS OF THE SWREG ARE DUMPED IN OCTAL ON THE CONSOLE TTY AND ANY CHANGES ARE REQUESTED

(I.E.) SWR=XXXXXX NEW=

POSSIBLE RESPONSES ARE:

1. <CR> IF NO CHANGES ARE TO BE MADE.
2. 6 DIGITS 0-7 TO REPRESENT IN OCTAL THE NEW SWITCH REGISTER VALUE; LAST DIGIT FOLLOWED BY <CR>.
3. ↑U TO ALLOW REENTERING VALUE IF ERROR IS COMMITTED

KEYING IN SWREG VALUE.

DESCRIPTION

BUILT INTO THE PROGRAM IS THE ABILITY TO DYNAMICALLY CHANGE THE CONTENTS OF SWREG DURING PROGRAM EXECUTION. BY STRIKING ↑G (CNTL G) ON CONSOLE TTY THE OPERATOR SETS A REQUEST FLAG TO CHANGE THE CONTENTS OF SWREG, WHICH IS PROCESSED IN KEY AREAS OF THE PROGRAM CODE (IE) ERROR ROUTINES, AFTER HALTS END OF PASS, AND OTHER APPLICABLE AREAS.

SWITCH SETTINGS ARE:

```
SW<15> = 1 ..... HALT ON ERROR
SW<14> = 1 ..... LOOP ON TEST
SW<13> = 1 ..... INHIBIT TYPEOUTS
SW<12> = 1 ..... INHIBIT OBUFSV FROM CHANGING WHEN LOOKING
                 FOR MEMORY ON -B- PORT
SW<11> = 1 ..... INHIBIT ITERATIONS OF SUBTEST
SW<10> = 1 ..... BELL ON ERROR
         0 ..... BELL ON PASS COMPLETE
SW<09> = 1 ..... LOOP ON ERROR
SW<08> = 1 ..... LOOP ON TEST IN SW<7:0>
```

5.2 SUBROUTINE ABSTRACTS

5.2.1 SCOPE

THIS SUBROUTINE CALL IS PLACED BETWEEN EACH SUBTEST IN THE INSTRUCTION SECTION. IT RECORDS THE STARTING ADDRESS OF EACH SUBTEST AS IT IS BEING ENTERED IN LOCATION "LAD". IF A SCOPE LOOP IS REQUESTED, THE CURRENT SUBTEST WILL BE LOOPED UPON. SW<11> ON A 1 INHIBITS ITERATION OF SUBTESTS. THE CONTENTS OF LAD MAY BE USED TO DETERMINE THE LAST SUBTEST SUCCESSFULLY COMPLETED.

5.2.2 HLT

THIS ROUTINE PRINTS OUT AN ERROR MESSAGE (SEE 6.1). TO INHIBIT TYPEOUTS, PUT SW<13> ON A 1.

5.2.3 TRAPCATCHER

A ".+2" - "HALT" SEQUENCE IS REPEATED FROM 0 - 776 TO CATCH ANY UNEXPECTED TRAPS. THUS ANY UNEXPECTED TRAPS OR INTERUPTS WILL HALT AT THE VECTOR + 2.

6. ERRORS

6.1 ERROR PRINTOUT

THE FORMAT IS AS FOLLOWS:

```
ADR   CS1 = ----- CS2 = ----- ER = -----
GOOD      = ----- BAD = -----
```

WHERE:

```
CS1,CS2,ER ETC.     = RS11 DISK REGISTERS.
GOOD                = EXPECTED DATA.
BAD                 = DATA RECEIVED.
```

TO FIND THE FAILING TEST, LOOK AT THE LISTING ABOVE THE ADDRESS TYPED.

6.2 ERROR RECOVERY

RESTART AT 200

7. RESTRICTIONS

NONE

8. MISCELLANEOUS

8.1 EXECUTION TIME

A BELL WILL RING WITHIN 1 MINUTE WITH ALL SWITCHES DOWN.

8.2 STACK POINTER

STACK IS INITALLY SET TO 500

9. WRITE LOCK TEST

THE WRITE LOCK TEST REQUIRES OPERATOR INTERVENTION. THE STARTING ADDRESS FOR THIS TEST IS 220. THE PROGRAM WILL TELL THE OPERATOR WHICH SWITCHES HAVE TO BE SET.

10. TEST DESCRIPTION

DESCRIPTION

1. TEST RSCS2

   CLEAR ALL READ/WRITE BITS AND CHECK. SET ALL R/W BITS AND CHECK. NOW CLEAR AND RECHECK.

2. TEST FOR ONLINE DRIVES

   SET ERROR BITS IN RSER. THIS CAUSES ATTENTION SUMMARY BITS TO SET IN RSAS. DO FOR ALL DRIVES. RSAS HAS NOT YET BEEN TESTED. SO IN THE CASE OF NO BITS IN RSAS SETTING, DRIVE 0 IS TESTED.

3. RESET TEST FOR REGISTERS

   SET ALL R/W BITS IN RSCS1, RSCS2, RSBA, RSDA, RSER, RSWC, RSDB, AND RSMR. DO A RESET AND TEST ALL R/W BITS TO BE CLEARED.

4. SET AND CLEAR ALL REGISTERS

   SET ALL R/W BITS IN RSCS1, RSCS2, RSBA, RSDA, RSER, RSWC, RSDB AND RSMR AND TEST. SET ALTERNATE BITS AND CHECK TO MAKE SURE BITS ARE NOT TIED TOGETHER. NOW SET ALL BITS AND CLEAR THEM TO MAKE SURE ALL CAN BE CLEARED ONCE SET.

5. RANDOM NUMBER TEST FOR RSWC AND RSDA

   THIS TEST GENERATES RANDOM NUMBERS AND LOADS THEM INTO RSWC, RSDA AND RSBA.

6. TEST "CLEAR BIT" IN RSCS2

   SET ALL R/W BITS IN RSCS1, RSCS2, RSBA, RSDA, RSER, RSWC RSDB, AND RSMR. SET CLEAR BIT IN RSCS2. NOW TEST ALL R/W BITS FOR 0 IN ALL THE ABOVE REGISTERS.

7. TEST DLT AND TRE BITS

   DO A READ FROM THE SILO. THIS SHOULD CAUSE A DLT AND A TRE ERROR BECAUSE THE SILO IS EMPTY.

8. CLEAR DLT AND TRE

   CLEAR BY SETTING TRE IN RSCS1 AND TEST.

9. LOAD RSDB WITH ALL ONES AND ALL ZEROS

   LOAD RSDB WITH A WORD OF ZEROS AND A WORD OF ONES. WAIT FOR "OR" TO SET AND THEN CHECK OUTPUT OF SILO. IF OR DID NOT SET ERROR MESSAGE APPEARS.

10. TEST FOR 66 LOCATIONS IN SILO

THIS IS DONE BY PUTTING A BINARY COUNT IN EVERY LOCATION AND

DESCRIPTION

CHECKING THE OUTPUT FOR 66 WORDS.

11. TEST DLT ERROR

THIS IS DONE BY LOADING THE SILO WITH 67 WORDS WITHOUT READING ANY OUT. THIS SHOULD CAUSE DLT TO SET.

12. FLOAT A "1" AND A "0" THROUGH THE SILO

LOAD THE SILO WITH A WORD OF ZEROS AND FLOAT A "1" THROUGH THE WORD. THEN LOAD THE SILO WITH A WORD OF ALL ONES AND FLOAT A "0" THROUGH THE WORD. CHECK THE OUTPUT OF THE SILO FOR THE CORRECT ANSWER.

13. TEST NO-OP FUNCTION

THE NO-OP FUNCTION IS TESTED WITH AND WITHOUT ERROR BITS SET. ALL THE REGISTERS ARE CHECKED AFTER BOTH CASES.

14. TEST DRIVE CLEAR FUNCTION

FIRST SET ALL R/W BITS IN RSDA, RSWC, RSER, AND RSMR. DO A DRIVE CLEAR FUNCTION. NOW TEST ALL REGISTERS FOR CORRECT DATA.

15. EXECUTE A ONE WORD WRITE FUNCTION

SET RSWC TO -1. MOV -1 INTO OUTBUF. LOAD RSBA WITH OUTBUF. DO A WRITE TEST RDY BIT FOR 0 THEN WAIT FOR IT TO SET. TIME OUT TO ERROR IF RDY BIT DOESN'T SET AND CHECK FOR ERROR CONDITIONS. TEST RSDA FOR CORRECT ADDRESS. TEST WORD COUNT FOR 0. THIS IS TESTED ON -A- AND -B- PORT.

16. EXECUTE A ONE WORD WRITE CHECK

SET UP RSDA, RSBA, RSWC AND OUTBUF AS IN THE WRITE FUNCTION TEST. DO A WRITE CHECK FUNCTION. TEST RDY AS DONE IN THE WRITE TEST. CHECK FOR WRITE CHECK ERROR. THEN TEST RSDA, RSWC AND RSBA FOR CORRECT DATA. THIS IS TESTED ON -A- AND -B- PORT.

17. TEST READ FUNCTION

SETUP RSDA, RSBA, RSWC AND OUTBUF AS IN THE WRITE FUNCTION DO A READ FUNCTION. TEST RDY BIT AS DONE IN THE WRITE FUNCTION. TEST FOR ERRORS. ALSO TEST RSDA, RSWC AND RSBA FOR CORRECT DATA. THIS IS TESTED ON -A- AND -B- PORT.

18. TEST BLOCK SEARCH FUNCTION, PIP AND DRY BITS AND ADDR. CONF. BIT

DO A BLOCK SEARCH FOR SECTOR 32, LOOP ON ADDR. CONF. BIT IN

RSMR. IF IT DOESN'T SET, TIMEOUT. WHEN YOU GET THERE DO A
BLOCK SEARCH FOR SECTOR 0. NOW WE KNOW THAT WE HAVE TIME TO

TEST FOR DRY AND PIP BITS BEFORE FINDING SECTOR 0. FOR PIP SHOULD SET AND DRY SHOULD CLEAR BEFORE FINDING SECTOR 0. ONCE SECTOR 0 IS FOUND PIP SHOULD CLEAR AND DRY SHOULD SET. IF DRY DOES NOT SET A TIME OUT ERROR WILL OCCUR INDICATING SECTOR 0 WAS NOT FOUND. SC IN RSCS1 SHOULD ALSO SET. RSBA AND RSWC SHOULD NOT MOVE, THIS IS ALSO TESTED.

19. ILLEGAL FUNCTION CODE TEST

IN THIS TEST RSBA, RSWC AND RSDA ARE SET UP AS IF TO DO A LEGAL FUNCTION. AN ILLEGAL FUNCTION IS THEN EXECUTED. THE PROGRAM TEST FOR ILF AND ERR BITS TO SET. RSBA, RSWC AND RSDA ARE ALSO TESTED FOR CORRECT DATA. THIS IS DONE FOR ALL THE ILLEGAL FUNCTIONS.

FOR AN AID IN TROUBLE SHOOTING THE ILLEGAL FUNCTION CODE CAN BE LOADED INTO LOCATION ILLTAB OR ILFTB2, DEPENDING ON WHICH ILLEGAL FUNCTION TEST YOU WISH TO LOOP ON. IN THE NEXT LOCATION FOLLOWING THE ILLEGAL FUNCTION, A 0 MUST BE LOADED. NOW BY SETTING SWITCH 14 (LOOP ON TEST), YOU WILL LOOP ON THE ILLEGAL FUNCTION.

20. TEST PAR IN RSER

SET PAR IN RSER AND CHECK. ALSO TEST ERR IN RSDS TO SET BECAUSE OF THE PAR SETTING.

21. TEST DPR AND MOL IN RSDS

BOTH THESE BITS SHOULD BE SET IN RSDS IF THE DRIVE IS ON LINE AND UP TO SPEED.

22. LOOK AHEAD TEST

FIRST CHECK TO SEE IF SECTOR FRACTION BITS ARE MOVING. NOW SET RSDA TO 0 AND INCREMENT IT EVERY TIME THE ADDR.CONF BIT SETS. IF THE ADDR.CONF BIT DOES NOT SET IN A CERTAIN LENGTH OF TIME, A TIME OUT ERROR OCCURS.

23. PARITY TEST

THIS WILL TEST THE PARITY LOGIC ONLY IF THERE IS PARITY MEMORY ON THE SYSTEM IN LESS THAN 28K. IT WILL WRITE BAD PARITY IN A MEMORY LOCATION THEN TRY TO DO A WRITE TO THE DRIVE FROM THAT LOCATION. THIS SHOULD CAUSE A PARITY ERROR.

24. TEST WRITE CHECK ERROR

IN THIS TEST THE PROGRAM WRITES A -1 ON TO THE DISK. A 0 IS NOW FLOATED THROUGH THE WORD IN THE BUS ADDRESS LOCATION, AND A WRITE CHECK FUNCTION IS DONE. THE WCE BIT IN RSCS2 SHOULD SET AND SHOULD CAUSE THE TRE BIT IN RSCS1 TO SET. THESE BITS

ARE THEN CLEARED. A WORD OF 0 IS NOW WRITTEN ON THE DISK AND
A 1 IS FLOATED THROUGH THE WORD IN THE BUS ADDRESS AND THE

WRITE CHECK FUNCTION TEST IS REPEATED.

25. TEST PROGRAM ERROR BIT IN RSCS2

HERE THE PROGRAM ATTEMPTS TO INITIATE A DATA TRANSFER OPERATION WHILE THE CONTROL IS CURRENTLY PERFORMING ONE. THIS SHOULD CAUSE PGE TO SET WHICH SHOULD CAUSE TRE TO SET. THESE BITS ARE THEN CLEARED. RSWC IS ALSO TESTED FOR IT SHOULD NOT BE 0 FOR THE CURRENT OPERATION SHOULD HAVE BEEN ABORTED DUE TO THE PGE ERROR.

26. TEST RMR IN RSER

HERE A WRITE COMMAND IS GIVEN AND DURING ITS EXECUTION THE PROGRAM TRYS TO MODIFY THE RSDA REG. THIS SHOULD CAUSE THE RMR BIT TO SET WHICH CAUSES THE ERR BIT TO SET. THESE BITS ARE THEN CLEARED.

27. TEST DCK IN RSER

HERE A WRITE COMMAND IS GIVEN THEN DURING THIS FUNCTION A DRIVE CLEAR COMMAND IS GIVEN. THIS SHOULD CAUSE THE DCK BIT TO SET WHICH SHOULD CAUSE THE ERR BIT TO SET. THESE BITS ARE THEN CLEARED.

28. TEST DISK ADDRESS REGISTER

LOAD THE LAST DISK ADDRESS (7777) INTO RSDA. DO A ONE WORD WRITE AND CHECK THAT RSDA INCREMENTED TO 10000.

29. TEST IAE ERROR

DO A ONE WORD WRITE BUT FIRST SET RSDA TO AN INVALID ADDRESS SUCH AS 10000. THIS SHOULD CAUSE A IAE ERROR WHICH WILL CAUSE ERR, ATA AND SC BITS TO SET. THESE BITS ARE THEN CLEARED BY LOADING A 1 INTO ATA IN RSAS.

30. TEST FOR NON-EXISTENT DISK ERROR

FIRST FIND A DRIVE THAT IS NOT ON THE SYSTEM OR OFF LINE. NOW TRY TO DO A ONE WORD WRITE TO THAT DRIVE. NED IN RSCS2 SHOULD SET WHICH SHOULD CAUSE TRE TO SET. THESE BITS ARE THEN CLEARED BY MOVING A 1 INTO TRE.

31. TEST DAO IN RSER AND LBT IN RSDS

SET RSDA TO ITS LAST ADDRESS. NOW WRITE ONE SECTOR PLUS ONE WORD. DAO SHOULD SET AND LBT SHOULD SET. THESE SHOULD CAUSE ERR, ATA, TRE AND SC TO SET. THESE ARE CLEARED BY DOING A CLEAR.

32. TEST BAI IN RSCS2

E02

SET BAI IN RSCS2. DO A ONE WORD WRITE AND CHECK RSBA TO SEE

IF IT INCREMENTED.

33. TEST NON-EXISTENT MEMORY ERROR BIT IN RSCS2

SET BITS A16 AND A17 IN RSCS1 FOR 0N 18 BIT ADDRESS. MOV I73000 INTO RSBA. MOV -1000 INTO RSWC AND DO A WRITE FUNCTION. THE NEM BIT SHOULD SET AND SHOULD CAUSE TRE TO SET. CLEAR THESE BITS BY LOADING A 1 INTO TRE.

34. TEST FOR ZERO'S IN A PARTIALLY FILLED SECTOR

FIRST WRITE A COMPLETE SECTOR WITH ALL ONES. THEN DO A ONE WORD WRITE. THE REMAINING 63 WORDS SHOULD BE WRITTEN AS ZERO'S. NOW DO A WRITE CHECK TO COMPARE FOR THESE ZERO'S.

35. PRIORITY INTERRUPT TEST

HERE THE PROGRAM ENABLES THE INTERRUPT AND DOES A ONE WORD WRITE FUNCTION. THE PROGRAM SHOULD NOT TRAP UNTIL THE PROCESSOR IS DROPPED TO PRIORITY 4.

36. DYNAMIC FUNCTION TEST

WHILE ONE DRIVE IS READING, THE UNIT # IN RSCS2 IS MODIFIED. IF THERE IS ANOTHER DRIVE ON THE SYSTEM, A DRIVE SEARCH IS PERFORMED ON IT. THIS IS ALL DONE WHILE THE FIRST DRIVE IS STILL READING.

```
                .TITLE  MAINDEC-11-DZRSB-F      RH11-RS03LA-RS03-RS04 BASIC FUNCTION DIAGNOSTIC
                ;COPYRIGHT 1973,1974,1975,1976,1977 DIGITAL EQUIPMENT CORP., MAYNARD, MASS.
                ;PROGRAM BY STANLEY HARACKIEWICZ

                ;          SWITCH                       USE
                ;          ------                ---------------------
                        SW15=   100000          ;HALT ON ERROR
                        SW14=   40000           ;LOOP ON TEST
                        SW13=   20000           ;INHIBIT ERROR TYPEOUTS
                        SW12=   10000           ;INHIBIT OBUFSV FROM CHANGING FOR -B- PORT ONLY
                        SW11=   4000            ;INHIBIT ITERATIONS
                        SW10=   2000            ;0 - BELL ON PASS COMPLETE
                                                ;1 - BELL ON ERROR
                        SW9=    1000            ;LOOP ON ERROR
                        SW8=    400             ;LOOP ON TEST IN SW<7:0>
                .=      0                       ;TRAP CATCHER FROM 0 - 776
                .=      46                      ;HOOKS FOR ACT 11
000046  $ENDAD:
                .=      52
000052  BIT14:

                .=      174                     ;SOFTWARE SWITCK REGISTER LOCATION
000174  DISPREG:0
```

```
000176  SWREG:  0

                .=      200
000200          JMP     @#STRT

                .=      220
000220          JMP     @#WRTLCK        ;WRITE LOCK TEST

                .=      230
000230  STRT:   BIC     #BIT11,ONCEE    ;CLEAR TKSEL TEST FLAG
000236          JMP     @#BEGIN         ;STARTING ADDRESS IS BEGIN

        ;STARTING ADDRESSES  FOR SWITCH REGISTER TESTING OF RH-RS REGISTERS

                .=      250
000250          JMP     @#SRSWC         ;WORD COUNT REG
000254          JMP     @#SRSBA         ;BUS ADDR REG
000260          JMP     @#SRSDA         ;DISK ADDR REG
000264          JMP     @#SRSDS         ;DRIVE STATUS REG
000270          JMP     @#SRSER         ;ERROR REG
000274          JMP     @#SRSLA         ;LOOK AHEAD REG
000300          JMP     @#SRCS2         ;CS2 REG
000304          JMP     @#SRAS          ;ATTENTION SUMMARY REG
000310          JMP     @#RSMRR         ;MAINTENANCE REG
000314          JMP     @#SRSCS1        ;CS1 REG

                .=      320
000320          BIS     #BIT11,ONCEE    ;SET TKSEL TEST FLAG
000326          JMP     @#BEGIN         ;ENABLES OPERATOR TO DO A
                                        ;WRITE OR READ TO A DESIRED ADDR
                                        ;OPTIONAL WC, DA, AND UNIT #
```

```
                        N=      1               ;INITALIZE FOR NEWISI
                        HLT=    EMT             ;SET HLT TO EMT FOR ERROR TYPEOUTS
                        PS=     177776          ;PROCESSOR STATUS
                        PSW=    PS              ;PROCESSOR STATUS WORD
                        BELL=   7               ;BELL
                        R0=     %0              ;R0 - DEFINE REGISTERS
                        R1=     %1              ;R1
                        R2=     %2              ;R2
                        R3=     %3              ;R3
                        R4=     %4              ;R4
                        R5=     %5              ;R5
                        SP=     %6              ;R6 - STACK POINTER
                        PC=     %7              ;R7 - PROGRAM COUNTER
                        BIT0=   1               ;BIT EQUATES
                        BIT1=   2
                        BIT2=   4
                        BIT3=   10
                        BIT4=   20
                        BIT5=   40
                        BIT6=   100
                        BIT7=   200
                        BIT8=   400
                        BIT9=   1000
                        BIT10=  2000
                        BIT11=  4000
                        BIT12=  10000
                        BIT13=  20000
                        BIT14=  40000
                        BIT15=  100000
                GOOD=   %1              ;FOR GOOD DATA
                BAD=    %0              ;FOR BAD DATA
```

```
                .=      1000

001000  ICNT:   0                       ;LH = ITERATION COUNT  ;RH = TEST NO.
001002  ERRORS: 0                       ;ERROR COUNT
001004  PCNT:   0,0                     ;2 WORD PASS COUNT
001010  LAD:    0                       ;LOOP ADDRESS FOR SCOPE
001012  HLTADR: 0                       ;ADDRESS OF LAST HLT INSTRUCTION  EXECUTED
001014  FILCHR: 1000                    ;FILCHR=0 (CHAR)  ;FILCHR+1=2 (COUNT)
001016  TPS:    177564                  ;OUTPUT STATUS REGISTER
001020  TKS:    177560
001022  TKB:    177562
001024  TPB:    177566                  ;OUTPUT BUFFER
001026  SWR:    177570                  ;SWITCH REGISTER
001030  DISPLAY:177570                  ;DISPLAY REGISTER

                .=      1100
001100  SAVBAD: 0                       ;LOC FOR ILLEGAL FUNCTION CODE
001102  OBUFSV: 0                       ;LOC OF OUTBUF

                ;DISK I/O REGISTERS

001104  RSCS1:  172040                  ;DISK CONTROL + STATUS REGISTER
001106  RSCS2:  172050                  ;DISK CONTROL + STATUS REGISTER
001110  RSWC:   172042                  ;WORD COUNT REGISTER
001112  RSBA:   172044                  ;BUS ADDRESS
001114  RSDA:   172046                  ;DISK ADDRESS (DESIRED ADDRESS)
001116  RSDS:   172052                  ;DRIVE STATUS
001120  RSER:   172054                  ;ERROR REG.
001122  RSAS:   172056                  ;ATTENTION SUMMARY
001124  RSLA:   172060                  ;LOOK AHEAD
001126  RSDB:   172062                  ;DATA BUFFER REGISTER
001130  RSMR:   172064                  ;MAINTENANCE REGISTER
001132  RSDT:   172066                  ;DRIVE TYPE REGISTER
001134  RSVEC:  204                     ;INTERUPT VECTOR
001136  RSVCPS: 206                     ;INTERRUPT PRIO. VECTOR
001140  RSCS1B: 172041                  ;ODD BYTE ADD FOR CS1
001142  RSCS2B: 172051                  ;ODD BYTE ADD FOR CS2
001144  RSWCB:  172043                  ;ODD BYTE ADD FOR CW
001146  RSBAB:  172045                  ;ODD BYTE ADD FOR BA

        ;MEMORY MANAGEMENT REGISTER ASSIGNMENTS

                SR0=177572
                KIPAR0=172340
                KIPAR1=172342
                KIPAR2=172344
                KIPAR7=172356
                KIPDR0=172300
                KIPDR1=172302
                KIPDR2=172304
                KIPDR7=172316
                RW=6
                UP=00
```

```
                ;BIT ASSIGNMENTS FOR ERROR TYPEOUTS
                ;THE RS REGISTERS ARE DIVIDED INTO 3 GROUPS.
                ;CS1,CS2 AND ER ARE IN THE FIRST GROUP.THIS GROUP IS ALWAYS
                ;TYPED WITH EITHER OF THE OTHER GROUPS. AS,BA,DA, WC AND DS
                ;ARE IN THE SECOND GROUP. DT,DB,MR, AND LA ARE IN THE 3RD
                ;GROUP.YOU CAN NOT INTERMIX GROUP 2 OR 3. THEY HAVE
                ;TO BE TYPED SEPERATELY.
                ;EXAMPLE:    HLT !CS1,AS,BA
                ;            HLT !CS1!DT!DB

                CS1=1           ;CONTROL AND STATUS 1
                ER=2            ;CONTROL AND STATUS 2
                DA=4            ;DESIRED ADD
                WC=10           ;WORD COUNT
                BA=20           ;BUS ADDRESS
                DS=40           ;DRIVE STATUS
                AS=100          ;ATTENTION SUMMARY
                CS2=200         ;CONTROL AND STATUS REG
                LA=204          ;LOOK AHEAD
                DB=210          ;DATA BUFFER
                MR=220          ;MAINTENANCE
                DT=240          ;DRIVE TYPE

                ;BIT ASSIGNMENTS FOR THE REGISTER BITS

                TRE=40000       ;TRANSFER ERROR CS1
                SC=100000       ;SPECIAL CONDITIONS CS1
                IR=100          ;INPUT READY CS2
                OR=200          ;OUTPUT READY CS2
                PGE=2000        ;PROGRAM ERROR-CS2
                NED=10000       ;NON-EXISTENT DRIVE CS2
                WCE=40000       ;WRITE CHECK ERROR-CS2
                DLT=100000      ;DATA LATE ERROR CS2
                DRY=200         ;DRIVE READY DS
                PIP=20000       ;POSITIONING IN PROGRESS DS
                LBT=2000        ;LAST BLOCK TRANSFER-DS
                ERR=40000       ;ERROR DS
                ATA=100000      ;ATTENTION ACTIVE-DS
                DAO=1000        ;DISK OVERFLOW ERROR-ER
                DCK=100000      ;DATA CHECK ERROR-ER
                BAI=10          ;BUS ADDR INCREMENT INHIBIT
                IE=100          ;INTERRUPT INABLE CS1
```

```
                ;WORKING LOCATIONS

001150  RANNU:  146723                  ;RANDOM NUMBER PRIME
001152  UNNUM:  0                       ;UNIT CURRENTLY BEING TESTED
001154  UNITSV: 0                       ;SET BIT=UNIT ON BUS
001156  UNCMP:  0                       ;FOR COMPARING FOR # OF DEVICE
001160  ONCEE:  0                       ;DID WE TEST ANY DRIVES
001162  RS04DT: 0                       ;CLR IF RS03 SET IF RS04
001164  TIMSV:  0                       ;SAVE LOC FOR TIME
001166  AOB1:   0                       ;PORT SWITCH
        WWP=4                           ;WRITE WRONG PARITY
        MPR0=172100                     ;PARITY REG
001170  BPORTT: 0                       ;BUFFER ADDR FOR -B- PORT
001172  SAVEE:  0                       ;WORK LOC

                ;DISCRIPTION OF ONCEE BITS
                ;BIT0 MEANS FOUND DRIVE
                ;BIT11 DO TKSEL TEST
                ;BIT12 TYPE COULD NOT FIND NED ONLY ONCE
                ;BIT13 TYPE NO MEM ON B PORT ONLY ONCE
                ;BIT14 0- DO WCE WITH 0 -1 DO WCE WITH 1
                ;BIT15 MEANS ERROR FOUND

                ;RH11 WORK REGISTERS
                ;(CAN BE CHANGED IN ANY ROUTINE)
001174  WORK:   0
001176  WORK1:  0
001200  WORK2:  0

001202  BEGIN:  MOV     #500,SP         ;SET STACK TO  *** 500 ***
001206          MOV     #.POWER,@#24    ;SET UP PF VECTOR
001214          MOV     #340,@#26       ;LOCK OUT THE WORLD
001222          MOV     #.HLT,@#30      ;SET EMT VECTOR
001230          MOV     #340,@#32       ;LOCK UP
001236          MOV     #.TRAP,@#34     ;SET TRAP VECTOR
001244          MOV     #340,@#36       ;LOCK UP
001252          CLR     ICNT            ;INIT ICNT
001256          CLR     LAD             ;INIT LAD
001262          BIC     #143777,ONCEE   ;CLEAR ONCEE
001270          MOV     #OUTBUF,OBUFSV  ;SAVE LOC OF OUTBUFFER
001276          BIT     #BIT11,ONCEE    ;DO TKSEL TEST?
001304          BEQ     .+6             ;NO
001306          JMP     @#TKSEL         ;YES
001312          SUSWR                   ;SIZE FOR HDWR SWR
```

```
                        ;NOW TEST FOR DRIVES
                        ;*************************************************************************
                        ;TEST 1          TEST FOR DRIVES
                        ;*************************************************************************
001314  TST1:   SCOPE

001316  MULTII: MOV     #8.,R1          ;PUT 8 INTO R1 FOR COUNT
001322         CLR     @RSCS2          ;SET DEVICE TO ZERO
001326  TRY:    MOV     #7,@RSER        ;CAUSE AN ERROR +SETS BIT IN RSAS REG
001334         DEC     R1              ;DO A MAXIMUM OF 8 TIMES
001336         BEQ     DVNUM           ;TESTED FOR ALL DRIVES GET OUT
001340         INC     @RSCS2          ;INCREMENT DRIVE UNIT
001344         BR      TRY             ;REPEAT FOR NEXT DRIVE
001346  DVNUM:  MOV     @RSAS,UNITSV    ;SAVE
001354         MOV     #401,UNCMP      ;SETUP TO CMP WITH UNITSV
001362         MOV     #0,UNNUM        ;PUT 0 INTO UNIT NO.
001370         BIT     #BIT13,@SWR     ;INHIBIT TYPE OUT?
001376         BNE     STTEST          ;YES
001400         TYPE    ,.+2            ;.ASCIZ <15><12>"TESTING UNIT "
001424         BIC     #BIT15,ONCEE    ;CLEAR ERROR FLAG
001432  STTEST: BIT     UNCMP,UNITSV    ;IS THIS DRIVE ON THE SYSTEM
001440         BEQ     TRYNX           ;NO
001442         MOV     UNNUM,@RSCS2    ;YES PUT UNIT # INTO CS2
001450         CMP     #4,@RSDT        ;IS THIS A RS03LA?
001456         BNE     7$              ;NO
001460         MOV     #4,RS04DT       ;SETUP DRIVE TYPE FOR A LA DISK
001466         BR      1$              ;GET OUT
001470  7$:    CMP     #0,@RSDT        ;IS THIS A RS03?
001476         BNE     2$              ;NO
001500         CLR     RS04DT          ;YES
001504         BR      1$              ;GET OUT
001506  2$:    CMP     #1,@RSDT        ;IS THIS A RS03 4US?
001514         BNE     3$              ;NO
001516         CLR     RS04DT          ;RS03
001522         BR      1$              ;GET OUT
001524  3$:    CMP     #2,@RSDT        ;IS THIS A RS04?
001532         BEQ     6$              ;YES
001534         CMP     #3,@RSDT        ;IS IT A RS04?
001542         BEQ     6$              ;YES
001544         BIC     UNCMP,UNITSV    ;CLEAR UNWANTED ATA BIT
001552         BR      TRYNX           ;GET A NEW NUMBER
001554  6$:    BIS     #-1,RS04DT      ;YES RS04
001562  1$:    BIT     #BIT13,@SWR     ;INHIBIT TYPE OUT?
001570         BNE     4$              ;YES
001572         BIT     #BIT15,ONCEE    ;ANY ERRORS?
001600         BEQ     5$              ;NO
001602         TYPE    ,.+2            ;.ASCIZ <15><12><12>
001612  5$:
001612         MOV     UNNUM,-(6)      ;PUT UNNUM ON STACK
001616         TYPES                   ;TYPE STACK IN OCTAL - SUPRESS
001620         TYPE    ,40             ;TYPE SPACE
001624         BIC     #BIT15,ONCEE    ;CLEAR ERROR FLAG
001632  4$:    BR      NOWGO           ;NOW TEST
```

```
001634  TRYNX:  ASL     UNCMP           ;CHECK NEXT BIT FOR DRIVE
001640          BCS     CHCKDV          ;DID WE TEST ANY REG?
001642          INC     UNNUM           ;INC UNIT #
001646          BR      STTEST          ;CHECK FOR NEXT DRIVE

001650  CHCKDV: BIT     #BIT0,ONCEE     ;DID WE TEST ANY DRIVES?
001656          BNE     DONEE           ;YES WE DID TEST A DRIVE
001660          MOV     #100000,UNCMP   ;NO DRIVES TESTED, COULD NOT SET
001666          CLR     UNNUM           ;ANY AS BITS, THUS DEFAULTS TO
001672          BIT     #BIT13,@SWR     ;INHIBIT TYPE OUT?
001700          BNE     4$              ;YES
001702          MOV     UNNUM,-(6)      ;PUT UNNUM ON STACK
001706          TYPES                   ;TYPE STACK IN OCTAL - SUPRESS
001710          TYPE    ,40             ;TYPE SPACE
001714          TYPE    ,..+2           ;.ASCIZ <15><12>"COULD NOT FIND DRIVE WILL TEST DRIVE 0 IF YOU CONTINUE"
002012          HALT                    ;WAIT
002014  4$:     BR      NOWGO           ;TEST DRIVE 0
002016  DONEE:  JMP     DONE            ;GET OUT

        ;THIS TEST IS DESIGNED TO TEST THE ABILITY OF RESET
        ;TO CLEAR ALL THE RH AND RS REGISTERS

002022  NOWGO:  MOV     #OUTBUF,OBUFSV  ;SAVE LOC OF OUTBUFFER
002030          BIS     #BIT0,ONCEE     ;SET FOUND DRIVE FLAG
002036          MOV     TIMES,TIMSV     ;SAVE TIME
002044          MOV     #1,TIMES        ;ONLY TEST ONCE
        ;*****************************************************************************
        ;TEST 2          RESET TEST FOR REGISTERS
        ;*****************************************************************************
002052  TST2:   SCOPE
002054          MOV     #340,@#PS       ;LOCK OUT INTERUPTS
002062          MOV     UNNUM,@RSCS2    ;GET UNIT #
002070          MOV     #177776,@RSCS1  ;SET ALL
002076          MOV     #177777,@RSBA   ;POSSIBLE R/W
002104          MOV     #177777,@RSDA   ;BITS IN THESE REGISTERS
002112          MOV     #177777,@RSER
002120          MOV     #177777,@RSMR
002126          MOV     #177777,@RSWC
002134          MOV     #177737,@RSCS2
002142          RESET                   ;CLEAR ALL BITS IN ALL REG.

        ;TEST RSCS2 FOR CLEARED BITS

002144          CMP     #100,@RSCS2     ;DID THESE BITS GET CLEARED?
002152          BEQ     .+4             ;YES
002154          HLT     !CS2            ;(417) SHOULD BE CLEARED IN CS2
002156          MOV     UNNUM,@RSCS2    ;PUT # OF UNIT IN TEST IN CS2
002164          CMP     #10600,@RSDS    ;IS DPR AND MOL SET?
002172          BEQ     .+4             ;YES
002174          HLT     !DS             ;NO WHY NOT?
        ;TEST CONTROL AND STATUS REG 1
002176          CMP     #4200,@RSCS1    ;DID THE READY BIT SET?
002204          BEQ     .+4             ;YES
002206          HLT     !CS1            ;READY SHOULD BE SET
```

```
                ;TEST BUS ADDRESS REGISTER

002210                  TST     @RSBA           ;IS BA REG. CLEARED
002214                  BEQ     .+4             ;YES
002216                  HLT     !BA             ;SHOULD BE 0

                ;TEST DISK ADDRESS REGISTER

002220                  TST     @RSDA           ;IS DA CLEARED
002224                  BEQ     .+4             ;YES
002226                  HLT     !DA             ;SHOULD BE 0

                ;TEST ERROR REG RSER

002230                  TST     @RSER           ;DID RSER CLEAR?
002234                  BEQ     .+4             ;YES
002236                  HLT     !ER             ;BITS(157015) SHOULD BE CLEARED

                ;TEST RS MAINTENANCE REGISTER

002240                  BIT     #77,@RSMR       ;DID THESE BITS GET CLEARED
002246                  BEQ     .+4             ;YES
002250                  HLT     !MR             ;BITS(77) SHOULD BE 0

                ;TEST WC REG IT SHOULD NOT CHANGE

002252                  CMP     #177777,@RSWC   ;DID IT CHANGE?
002260                  BEQ     .+4             ;NO
002262                  HLT     !WC             ;RESET SHOULD NOT MODIFY RSWC

                ;TEST RSAS

002264                  TST     @RSAS           ;IS REG CLEAR
002270                  BEQ     .+4             ;YES
002272                  HLT     !AS             ;NO
```

```
                ;*****************************************************************************
                ;TEST 3          TEST CLEAR BIT IN CS2 ON ALL THE R/W BITS
                ;*****************************************************************************
002274  TST3:   SCOPE

002276  TTAGG:  MOV     #340,@#PS       ;LOCK OUT INTERRUPTS
002304          MOV     UNNUM,@RSCS2    ;GET UNIT #
002312          MOV     #43576,@RSCS1   ;SET ALL
002320          MOV     #177777,@RSBA   ;POSSIBLE
002326          MOV     #177777,@RSDA   ;REGISTERS
002334          MOV     #177777,@RSER
002342          MOV     #177777,@RSDB
002350          MOV     #177777,@RSWC
002356          MOV     #20417,@RSCS2
002364          MOV     #71,@RSMR
002372          MOV     #40,@RSCS2      ;CLEAR ALL BITS
002400          CMP     #100,@RSCS2     ;DID THE RIGHT BITS CLEAR?
002406          BEQ     .+4             ;YES
002410          HLT     !CS2            ;(417) SHOULD BE CLEARED IN CS2
002412          MOV     UNNUM,@RSCS2    ;GET DRIVE NUMBER
002420          BIT     #173577,@RSCS1  ;DID ALL BITS GET CLEARED
002426          BEQ     .+4             ;YES
002430          HLT     !CS1            ;NO, ALL BITS SHOULD BE 0
                ;TEST BUS ADDRESS REGISTER

002432          TST     @RSBA           ;IS BA REG. CLEARED
002436          BEQ     .+4             ;YES
002440          HLT     !BA             ;SHOULD BE 0

                ;TEST DISK ADDRESS REGISTER

002442          TST     @RSDA           ;IS DA CLEARED
002446          BEQ     .+4             ;YES
002450          HLT     !BA             ;SHOULD BE 0

                ;TEST ERROR REG RSER

002452          TST     @RSER           ;DID THESE BITS GET CLEARED
002456          BEQ     .+4             ;YES
002460          HLT     !ER             ;BITS(157015) SHOULD BE CLEARED

                ;TEST RS MAINTENANCE REGISTER
002462          BIT     #77,@RSMR       ;DID THESE BITS GET CLEARED
002470          BEQ     .+4             ;YES
002472          HLT     !MR             ;BITS(77) SHOULD BE 0

                ;TEST WC REG. IT SHOULD NOT CHANGE
002474          CMP     #177777,@RSWC   ;DID WC CHANGE
002502          BEQ     .+4             ;NO
002504          HLT     !WC             ;WHY DID IT CHANGE?
```

```
                ;*****************************************************************************
                ;TEST 4          SET AND CLEAR ALL REGISTERS
                ;*****************************************************************************
002506  TST4:   SCOPE
                ;CAN WE SET THE FUNCTION BITS IN THE RSCS1 REG.
                ;BITS 7,6,5,4,3,2&1

002510          CLRDK                           ;CLEAR ALL RS REG
002512          MOV     TIMSV,TIMES             ;GET TIME
002520          MOV     #43576,@RSCS1           ;SET DISK FUNCTION BITS
002526          CMP     #7776,@RSCS1            ;ARE THESE BITS SET?
002534          BEQ     .+4                     ;NO
002536          HLT     !CS1                    ;SHOULD = 7776
002540          MOV     #6724,@RSCS1            ;SET THESE BITS
002546          CMP     #6724,@RSCS1            ;DID THEY SET
002554          BEQ     .+4                     ;YES
002556          HLT     !CS1                    ;SHOULD BE 6724
002560          MOV     #10052,@RSCS1           ;SET THESE BITS
002566          CMP     #5252,@RSCS1            ;ARE THEY =?
002574          BEQ     .+4                     ;YES
002576          HLT     !CS1                    ;SHOULD = 5252
002600  TST5:   SCOPE
                ;CLEAR THE FUNCTION BITS

002602          MOV     #43576,@RSCS1           ;SET DISK FUNCTION BITS
002610          CLR     @RSCS1
002614          CMP     #4200,@RSCS1            ;IS THE READY BIT SET
002622          BEQ     .+4                     ;YES
002624          HLT     !CS1                    ;RSCS1 SHOULD = 4200

                ;*****************************************************************************
                ;TEST 6          TEST RSCS2
                ;*****************************************************************************
002626  TST6:   SCOPE

002630          RESET                           ;CLEAR WORLD
002632          CMP     #100,@RSCS2             ;DID THEY CLEAR?
002640          BEQ     .+4                     ;YES
002642          HLT     !CS2                    ;NO
002644          MOV     #21037,@RSCS2           ;SET BITS 21017
002652          CMP     #21137,@RSCS2           ;DID THESE BITS GET SET
002660          BEQ     1$                      ;YES
002662          MOV     @RSCS2,BAD
002666          MOV     #21137,GOOD             ;WHAT CS2 SHOULD =
002672          HLT                             ;CS2 = BAD GOOD = CORRECT ANS
```

```
002674  1$:     MOV     #20025,@RSCS2   ;SET THESE BITS
002702          CMP     #20125,@RSCS2   ;DID THESE BITS GET SET
002710          BEQ     .+4             ;YES
002712          HLT     !CS2            ;NO CS2 SHOULD = 20125
002714          MOV     #12,@RSCS2      ;LOAD THESE BITS
002722          CMP     #112,@RSCS2     ;DID THESE BITS GET SET IN CS2
002730          BEQ     .+4             ;YES
002732          HLT     !CS2            ;BAD = CS2 GOOD = CORRECT ANS
002734          MOV     #-1,@RSCS2      ;SET BITS
002742          CLR     @RSCS2          ;CLEAR THEM
002746          CMP     #100,@RSCS2     ;DID CLEAR WORK
002754          BEQ     .+4             ;YES
002756          HLT     !CS2            ;R/W BITS DID NOT CLEAR
002760          MOV     UNNUM,@RSCS2    ;GET UNIT #
002766  TST7:   SCOPE
        ;CAN WE SET ALL THE RSBA BITS

002770          MOV     #177777,@RSBA   ;SET THE BITS
002776          CMP     #177776,@RSBA   ;DID THEY SET
003004          BEQ     .+4             ;YES
003006          HLT     !BA             ;BITS 17776 SHOULD BE SET
003010          MOV     #125252,@RSBA   ;SET THESE BITS
003016          CMP     #125252,@RSBA   ;ARE THEY =
003024          BEQ     .+4             ;YES
003026          HLT     !BA             ;SHOULD BE 125252
003030          MOV     #52524,@RSBA    ;SET THESE BITS
003036          CMP     #52524,@RSBA    ;ARE THEY =
003044          BEQ     .+4             ;YES
003046          HLT     !BA             ;SHOULD BE 52524

003050  TST10:  SCOPE
        ;FLOAT A 1 THROUGH RSBA

003052  FLOTBA: MOV     #2,GOOD         ;GET A 2
003056          CLC                     ;CLEAR CARRY
003060  1$:     MOV     GOOD,@RSBA      ;FLOAT NUMBER
003064          MOV     @RSBA,BAD       ;GET BA
003070          CMP     GOOD,BAD        ;COMPARE BA
003072          BEQ     .+4             ;BA CORRECT
003074          HLT                     ;BAD=BA GOOD=CORRECT ANS
003076          ROL     GOOD            ;ROTATE NUMBER
003100          BCC     1$              ;LOOP TILL DONE
```

```
003102  TST11:  SCOPE

        ;CLEAR THE RSBA REGISTER

003104          MOV     #177777,@RSBA   ;SET RSBA EQUAL TO ALL ONES
003112          CLR     @RSBA
003116          TST     @RSBA           ;TEST FOR BIT0 SET IN RSBA (READ ONLY BIT)
003122          BEQ     .+4             ;YES
003124          HLT     !BA             ;NO
003126  TST12:  SCOPE

        ;CAN WE SET ALL BITS IN RSWC REGISTER

003130          MOV     #177777,@RSWC   ;SET WC BITS
003136          CMP     #177777,@RSWC   ;ARE ALL BITS SET
003144          BEQ     .+4             ;YES
003146          HLT     !WC             ;NO
003150          MOV     #125252,@RSWC   ;SET THESE BITS
003156          CMP     #125252,@RSWC   ;ARE THEY =
003164          BEQ     .+4             ;YES
003166          HLT     !WC             ;SHOULD BE 125252
003170          MOV     #52525,@RSWC    ;SET THESE BITS
003176          CMP     #52525,@RSWC    ;ARE THEY =
003204          BEQ     .+4             ;YES
003206          HLT     !WC             ;SHOULD BE 152525
003210  TST13:  SCOPE

        ;FLOAT A 1 THROUGH RSWC

003212  FLOTWC: MOV     #1,GOOD         ;GET A 1
003216          CLC                     ;CLEAR CARRY
003220  1$:     MOV     GOOD,@RSWC      ;FLOAT NUMBER
003224          MOV     @RSWC,BAD       ;GET WC
003230          CMP     GOOD,BAD        ;COMPARE WC
003232          BEQ     .+4             ;WC CORRECT
003234          HLT                     ;BAD=WC GOOD=CORRECT ANS
003236          ROL     GOOD            ;ROTATE NUMBER
003240          BCC     1$              ;LOOP TILL DONE
```

```
                ;CLEAR THE WORD COUNT REGISTER
003242  TST14:  SCOPE

003244          MOV     #177777,@RSWC   ;SET RSWC REGISTER EQUAL TO ALL ONES
003252          CLR     @RSWC
003256          TST     @RSWC           ;DID ALL BITS GET CLEARED
003262          BEQ     .+4             ;YES
003264          HLT     !WC             ;NO
003266  TST15:  SCOPE

                ;CAN WE SET ALL THE BITS IN THE RSDA REGISTER.

003270          MOV     #177777,@RSDA   ;SET ALL BITS
003276          CMP     #177777,@RSDA   ;ARE THE BITS SET
003304          BEQ     .+4             ;YES
003306          HLT     !DA             ;NO
003310          MOV     #125252,@RSDA   ;SET THESE BITS
003316          CMP     #125252,@RSDA   ;ARE THEY =
003324          BEQ     .+4             ;YES
003326          HLT     !DA             ;SHOULD BE 125252
003330          MOV     #52525,@RSDA    ;SET THESE BITS
003336          CMP     #52525,@RSDA    ;ARE THEY =
003344          BEQ     .+4             ;YES
003346          HLT     !DA             ;SHOULD BE 52525
003350  TST16:  SCOPE

                ;FLOAT A 1 THROUGH RSDA

003352  FLOTDA: MOV     #1,GOOD         ;GET A 1
003356          CLC                     ;CLEAR CARRY
003360  1$:     MOV     GOOD,@RSDA      ;FLOAT NUMBER
003364          MOV     @RSDA,BAD       ;GET DA
003370          CMP     GOOD,BAD        ;COMPARE DA
003372          BEQ     .+4             ;DA CORRECT
003374          HLT                     ;BAD=DA GOOD=CORRECT ANS
003376          ROL     GOOD            ;ROTATE NUMBER
003400          BCC     1$              ;LOOP TILL DONE
```

```
                ;CAN WE CLEAR THE RSDA REG.
003402  TST17:  SCOPE

003404          MOV     #177777,@RSDA   ;SET RSDA TO ALL ONES
003412          CLR     @RSDA
003416          TST     @RSDA           ;TEST FOR ZERO RSDA
003422          BEQ     .+4             ;YES
003424          HLT     !DA             ;ANS SHOULD BE 0
003426  TST20:  SCOPE

                ;SET AND CLEAR THE RSER REG.

003430          MOV     #177777,@RSER   ;SET THESE BITS
003436          CMP     #177017,@RSER   ;DID THEY SET
003444          BEQ     .+4             ;YES
003446          HLT     !ER             ;RSER SHOULD = 157017
003450          MOVB    #1,@RSER        ;A MOVB INST
003456          CMP     #1,@RSER        ;SHOULD MODIFY COMPLETE WD
003464          BEQ     .+4             ;OK
003466          HLT     !ER

003470  TST21:  SCOPE

003472          MOV     #52005,@RSER    ;SET THESE BITS
003500          CMP     #52005,@RSER    ;DID THEY SET
003506          BEQ     .+4             ;YES
003510          HLT     !ER             ;ER SHOULD = 52005
003512  TST22:  SCOPE

003514          MOV     #125012,@RSER   ;SET THESE BITS
003522          CMP     #125012,@RSER   ;DID THEY SET
003530          BEQ     .+4             ;YES
003532          HLT     !ER             ;ER SHOULD = 105012
```

```
003534  TST23:  SCOPE

003536          MOV     #177017,@RSER   ;SET THESE BITS
003544          CLR     @RSER           ;CLEAR THEM
003550          TST     @RSER           ;DID THEY CLEAR
003554          BEQ     .+4             ;YES
003556          HLT     !ER             ;SHOULD = 0
003560  TST24:  SCOPE

        ;SET AND CLEAR RSMR

003562          MOV     #70,@RSMR       ;SET THESE BITS
003570          MOV     @RSMR,WORK      ;PUT INTO WORKABLE REG
003576          BIC     #177700,WORK    ;CLEAR JUNK
003604          CMP     #70,WORK        ;DID THEY SET
003612          BEQ     .+4             ;YES
003614          HLT     !MR             ;SHOULD = 70
003616  TST25:  SCOPE

003620          MOV     #70,@RSMR       ;SET BITS
003626          CLR     @RSMR           ;CLEAR THEM
003632          BIT     #77,@RSMR       ;DID THEY CLEAR
003640          BEQ     .+4             ;YES
003642          HLT     !MR             ;BITS (77) SHOULD = 0
003644  TST26:  SCOPE

003646          MOV     #50,@RSMR       ;SET BITS
003654          MOV     @RSMR,WORK      ;PUT IN WORKABLE REG
003662          BIC     #177700,WORK    ;CLEAR JUNK
003670          CMP     #50,WORK        ;DID THESE BITS SET
003676          BEQ     .+4             ;YES
003700          HLT     !MR             ;BITS (50) SHOULD BE SET
003702  TST27:  SCOPE

003704          MOV     #20,@RSMR       ;SET BITS
003712          MOV     @RSMR,WORK      ;PUT INTO WORKABLE REG
003720          BIC     #177700,WORK    ;CLEAR JUNK
003726          CMP     #20,WORK        ;DID THEY SET
003734          BEQ     .+4             ;YES
003736          HLT     !MR             ;MR SHOULD AT LEAST HAVE A (21)
```

```
                ;*************************************************************************
                ;TEST 30                 LOAD RANDOM NUMBERS INTO RSWC, RSDA AND RSBA
                ;*************************************************************************
003740  TST30:  SCOPE

003742  RANTS:  MOV     #1000,WORK      ;MAKE TABLE 1000 WDS LONG
003750          MOV     #OUTBUF,R1      ;GET SRARTING LOC OF TABLE
003754          JSR     R5,RANDOM       ;GENERATE #
003760          MOV     #OUTBUF,R4      ;SETUP FOR COMPARE
003764          MOV     #LOP1,LAD       ;SETUP LOOP ADDR
003772  LOP1:   MOV     #1000,R3        ;LOAD TEST COUNTER
003776  4$:     DEC     R3              ;DONE WITH COMPARE?
004000          BEQ     1$              ;YES
004002          MOV     RSWC,R5         ;GET WC ADDRESS
004006          MOV     (R4),(R5)       ;LOAD WC
004010          CMP     (R5),(R4)+      ;IS IT CORRECT?
004012          BEQ     4$              ;YES
004014          MOV     @RSWC,BAD       ;GET BAD WC
004020          MOV     -(R4),GOOD      ;GET GOOD ANS
004022          HLT                     ;TYPE THEM OUT
004024          TST     (R4)+           ;UPDATE RANDOM NUMBER
004026          BR      4$              ;CONT
004030  1$:     MOV     #OUTBUF,R4      ;GET STARTING LOC OF TABLE
004034          MOV     #LOP2,LAD       ;SETUP LOOP ADDR
004042  LOP2:   MOV     #1000,R3        ;SETUP TEST COUNTER
004046  3$:     DEC     R3              ;DONE YET?
004050          BEQ     1$              ;YES
004052          MOV     RSDA,R5         ;LOAD DA ADDRESS INTO R5
004056          MOV     (R4),(R5)       ;LOAD DA
004060          CMP     (R5),(R4)+      ;IS IT CORRECT?
004062          BEQ     3$              ;YES
004064          MOV     @RSDA,BAD       ;GET BAD DATA
004070          MOV     -(R4),GOOD      ;GET GOOD DATA
004072          HLT                     ;TYPE IT OUT
004074          TST     (R4)+           ;UPDATE RANDOM NUMBER
004076          BR      3$              ;CONTINUE
004100  1$:     MOV     #OUTBUF,R4      ;GET STARTING LOC OF TABLE
004104          MOV     #LOP3,LAD       ;SETUP LOOP ADDR
004112  LOP3:   MOV     #1000,R3        ;SETUP TEST COUNTER
004116  3$:     DEC     R3              ;DONE YET?
004120          BEQ     2$              ;YES
004122          MOV     RSBA,R5         ;LOAD ADDRESS OF BA INTO R5
004126          MOV     (R4),(R5)       ;LOAD BA
004130          BIC     #BIT0,(R4)      ;CLEAR BIT 0
004134          CMP     (R5),(R4)       ;IS IT CORRECT?
004136          BEQ     3$              ;YES
004140          MOV     @RSBA,BAD       ;GET BAD DATA
004144          MOV     (R4),GOOD       ;GET GOOD DATA
004146          HLT                     ;TYPE IT OUT
004150          BR      1$              ;GET OUT
004152  1$:     TST     (R4)+           ;GET NEW NUMBER
004154          BR      3$              ;CONTINUE
004156  2$:     NOP
```

```
                ;*****************************************************************************
                ;TEST 31                 TEST ODD BYTE INSTRUCTIONS ON CS1, CS2, WC AND BA
                ;*****************************************************************************
004160  TST31:  SCOPE

004162  BITST:  CLRDK                           ;CLEAR ALL RS REG
004164          MOV     #3566,@RSCS1            ;LOAD CS1
004172          MOVB    #5,@RSCS1B              ;LOAD BIT
004200          CMP     #6766,@RSCS1            ;DID IT LOAD?
004206          BEQ     .+4                     ;YES
004210          HLT     !CS1
004212          MOVB    #32,@RSCS1
004220          CMP     #6632,@RSCS1
004226          BEQ     .+4
004230          HLT     !CS1                    ;CS1 SHOULD = 6632

004232  TST32:  SCOPE

004234  BITCS2: MOV     UNNUM,@RSCS2            ;LOAD UNIT NUMBER
004242          BIS     #177400,@RSCS2          ;LOAD ALL BITS
004250          CLRB    @RSCS2B                 ;CLR UPPER BYTE
004254          MOV     UNNUM,GOOD              ;GET UNIT NO.
004260          BIS     #100,GOOD               ;SET OR BIT
004264          MOV     @RSCS2,BAD              ;GET CS2
004270          CMP     BAD,GOOD                ;IS CS2 CORRECT?
004272          BEQ     .+4                     ;YES
004274          HLT                             ;LOAD BYTE DID NOT WORK

004276  TST33:  SCOPE

004300  BITWC:  MOV     #25252,@RSWC            ;LOAD WC
004306          MOVB    #377,@RSWCB             ;LOAD BIT
004314          CMP     #177652,@RSWC           ;DID IT LOAD?
004322          BEQ     .+4                     ;YES
004324          HLT     !WC                     ;NO WC SHOULD =177652
004326          MOVB    #123,@RSWC
004334          CMP     #177523,@RSWC
004342          BEQ     .+4
004344          HLT     !WC                     ;WC SHOULD = 177523

004346  TST34:  SCOPE

004350  BITBA:  MOV     #25252,@RSBA            ;LOAB DA
004356          MOVB    #377,@RSBAB             ;LOAD BIT
004364          CMP     #177652,@RSBA           ;DID IT LOAD?
004372          BEQ     .+4                     ;YES
004374          HLT     !BA                     ;DA SHOULD =177652
004376          MOVB    #125,@RSBA
004404          CMP     #177524,@RSBA
004412          BEQ     .+4
004414          HLT     !BA                     ;BA SHOULD = 177525
004416          CLRDK                           ;CLEAR ALL RS REG
```

```
                ;*****************************************************************************
                ;TEST 35                 TEST DATA LATE IN CS2
                ;*****************************************************************************
004420  TST35:  SCOPE

                ;DO A READ FROM SILO: SHOULD GET DLT + TRE ERROR BECAUSE SILO IS EMPTY

004422  SILOB:  CLRDK                           ;CLEAR ALL RS REG
004424          MOV     @RSDB,BAD               ;READ FROM EMPTY SILO
004430          MOV     @RSCS2,BAD              ;GET CS2
004434          MOV     #100100,GOOD            ;GET CORRECT ANS
004440          BIS     UNNUM,GOOD              ;FOR CS2
004444          CMP     BAD,GOOD                ;IS CS2 CORRECT?
004446          BEQ     .+4                     ;YES
004450          HLT     !CS2                    ;SHOULD HAVE DLT ERROR
004452          CMP     #144200,@RSCS1          ;DID SC AND TRE SET?
004460          BEQ     .+4                     ;YES
004462          HLT     !CS1                    ;SC AND TRE SHOULD BE SET
004464          MOV     #TRE,@RSCS1             ;CLEARS ERROR BIT
004472          BIT     #140000,@RSCS1          ;DID SC + TRE CLEAR
004500          BEQ     .+4                     ;YES
004502          HLT     !CS1                    ;TRE AND SC SHOULD BE 0
004504          MOV     @RSCS2,BAD              ;GET CS2
004510          BIC     #BIT15,GOOD             ;GET CORRECT ANS
004514          CMP     GOOD,BAD                ;IS CS2 CORRECT?
004516          BEQ     .+4                     ;YES
004520          HLT     !CS2                    ;DLT SHOULD BE 0
                ;*****************************************************************************
                ;TEST 36                 LOAD RSDB WITH ALL ONES AND ALL ZEROS
                ;*****************************************************************************
004522  TST36:  SCOPE

004524  ZERONE: CLRDK                           ;CLEAR ALL RS REG
004526          CLR     @RSDB                   ;LOAD DB WITH ALL 0
004532          MOV     #177777,@RSDB           ;LOAD DB WITH ALL ONES
004540          MOV     #2000,WORK              ;TIME OUT ROUTINE
004546          MOV     #300,GOOD               ;GET CORRECT FOR CS2
004552          BIS     UNNUM,GOOD
004556  2$:     MOV     @RSCS2,BAD              ;GET CS2
004562          CMP     GOOD,BAD                ;IS IT CORRECT?
004564          BEQ     3$                      ;YES
004566          DEC     WORK                    ;TO WAIT FOR OR
004572          BNE     2$                      ;TO SET
004574          HLT     !CS2                    ;OR SHOULD BE SET
004576  3$:     CLR     GOOD
004600          MOV     @RSDB,BAD               ;LOAD BAD WITH DB
004604          CMP     GOOD,BAD                ;IS BAD CORRECT
004606          BEQ     .+4                     ;YES
004610          HLT                             ;COULD NOT FLOAT 0 THROUGH DB
004612          MOV     #-1,GOOD                ;LOAD GOOD WITH ANS
004616          MOV     @RSDB,BAD               ;GET DATA FROM DB
004622          CMP     GOOD,BAD                ;IS DB CORRECT
004624          BEQ     .+4                     ;YES
004626          HLT                             ;BAD SHOULD = 1777777
```

```
004630  TST37:  SCOPE
                ;TEST FOR 66 LOCATIONS IN SILO PUT COUNT IN EVERY LOCATION

004632  SILO:   CLRDK                           ;CLEAR ALL RS REG
004634          CLR     R1                      ;CLEAR COUNTER
004636  1$:     INC     R1                      ;INCREMENT COUNTER
004640          MOV     R1,@RSDB                ;LOAD SILO
004644          CMP     #66.,R1                 ;LAST LOC. YET?
004650          BNE     1$                      ;NO LOOP AGAIN
004652          MOV     #200,GOOD               ;GET CORRECT ANS FOR CS2
004656          BIS     UNNUM,GOOD
004662          MOV     @RSCS2,BAD              ;GET CS2
004666          CMP     GOOD,BAD                ;IS CS2 CORRECT?
004670          BEQ     .+4                     ;YES
004672          HLT     !CS2                    ;OR SHOULD BE 1
004674          CLR     GOOD                    ;CLEAR LOCATION COUNTER
004676  2$:     INC     GOOD                    ;ADD 1 TO IT
004700          CMP     #67.,GOOD               ;LAST LOC YET?
004704          BEQ     3$                      ;YES
004706          MOV     @RSDB,BAD               ;GET LOC FROM DB
004712          CMP     GOOD,BAD                ;DO LOCATIONS MATCH?
004714          BEQ     2$                      ;YES
004716          HLT                             ;CAN NOT MATCH 66 LOCATIONS
004720  3$:     BIT     #OR,@RSCS2              ;IS OR 0
004726          BEQ     .+4                     ;YES
004730          HLT     !CS2                    ;OR SHOULD BE 0

                ;NOW PUT 67 WORDS INTO SILO AND CHECK FOR DLT ERROR

004732          CLR     R1                      ;CLEAR COUNTER
004734  4$:     INC     R1                      ;ADD 1 TO COUNT
004736          MOV     R1,@RSDB                ;PUT INTO COUNTER
004742          CMP     #67.,R1                 ;DONE YET?
004746          BEQ     .+4                     ;YES
004750          BR      4$                      ;NO DO AGAIN
004752          BIT     #DLT,@RSCS2             ;DID DATA LATE SET?
004760          BNE     .+4                     ;YES
004762          HLT     !CS2                    ;DLT DID NOT SET

                ;DOES SILO CHANGE WITH 67TH WORD: IT SHOULD NOT

004764          MOV     @RSDB,BAD               ;GET 1ST WD FORM SILO
004770          MOV     #1,GOOD                 ;CORRECT ANS OF SILO
004774          CMP     GOOD,BAD                ;IS SILO GOOD
004776          BEQ     .+4                     ;YES
005000          HLT                             ;SILO SHOULD NOT HAVE MOVED
005002  TST40:  SCOPE
```

```
                ;FLOAT A 1 AND A 0 THROUGH THE SILO

005004  SILOFL: CLRDK                   ;CLEAR ALL RS REG
005006          CLC                     ;CLEAR CARRY TO FLOAT A 0
005010          MOV     #1,GOOD         ;GET UP DATA FOR INPUT TO SILO
005014  1$:     MOV     GOOD,@RSDB      ;LOAD DB
005020          ROL     GOOD            ;SHIFT BIT
005022          BCS     .+4             ;DONE YET SHIFTING?
005024          BR      1$              ;NO
005026          MOV     #-2,GOOD        ;SET ALL ONES
005032          SEC                     ;SET CARRY TO ROL
005034  3$:     MOV     GOOD,@RSDB      ;LOAD SILO
005040          ROL     GOOD            ;SHILT 0
005042          BCS     3$              ;LOOP TILL DONE

                ;NOW TEST OUTPUT

005044          CLC                     ;CLEAR CARRY
005046          MOV     #1,GOOD         ;CORRECT ANS
005052  2$:     MOV     @RSDB,BAD       ;GET DATA FROM DB
005056          CMP     GOOD,BAD        ;IS DB DATA GOOD?
005060          BEQ     .+4             ;YES
005062          HLT                     ;DB COULD NOT BUBBLE CORRECTLY
005064          ROL     GOOD            ;SETUP FOR NEXT ANS
005066          BCS     .+4             ;DONE YET?
005070          BR      2$              ;NO
005072          MOV     #-2,GOOD        ;SETUP FOR ANS
005076  4$:     MOV     @RSDB,BAD       ;GET DATA FROM DB
005102          CMP     GOOD,BAD        ;IS IT CORRECT?
005104          BEQ     .+4             ;YES
005106          HLT                     ;DB WRONG
005110          SEC                     ;SET CARRY TO ROL
005112          ROL     GOOD            ;SETUP FOR NEXT ANS
005114          BCS     4$              ;LOOP TILL DONE
```

```
                ;*****************************************************************************
                ;TEST 41                 TEST NO-OP FUNCTION
                ;*****************************************************************************
005116  TST41:  SCOPE

005120  NOOP:   CLRDK                           ;CLEAR ALL RS REG
005122          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
005130          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
005136          MOV     #-1,@RSWC               ;LOAD WC WITH -1
005144          MOV     #1,@RSCS1               ;DO NO-OP FUNCTION
005152          BIT     #1,@RSCS1               ;DID GO BIT CLEAR
005160          BEQ     .+4                     ;YES
005162          HLT     !CS1                    ;GO BIT SHOULD BE CLEARED
005164          TST     @RSER                   ;DID ANY ERRORS OCCURR?
005170          BEQ     .+4                     ;NO
005172          HLT     !ER                     ;ALL ERROR BITS SHOULD BE 0
005174          CMP     #-1,@RSWC               ;DID WC MOVE?
005202          BEQ     .+4                     ;NO
005204          HLT     !WC                     ;WC SHOULD = 1777777
005206          TST     @RSDA                   ;DID DA MOV
005212          BEQ     .+4                     ;NO
005214          HLT     !DA                     ;DA SHOULD =0
005216          CMP     @#OBUFSV,@RSBA          ;DID BA MOVE
005224          BEQ     .+4                     ;NO
005226          HLT     !BA                     ;BA MOVED
005230          BIT     UNCMP,@RSAS             ;AS SHOULD NOT SET ON
005236          BEQ     .+4                     ;A NO-OP FUNCTION
005240          HLT     !AS                     ;AS SET WHY?
```

```
                ;*****************************************************************************
                ;TEST 42                 TEST NO-OP FUNCTION WITH ERROR BITS SET
                ;*****************************************************************************
005242  TST42:  SCOPE

005244  NNOOP:  CLRDK                           ;CLEAR ALL RS REG
005246          MOV     #7,@RSER                ;LOAD ER
005254          BIT     UNCMP,@RSAS             ;IS ATA BIT SET?
005262          BNE     .+4                     ;YES
005264          HLT     !AS                     ;AS BIT SHOULD BE SET
005270          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
005274          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
005302          MOV     #-1,@RSWC               ;LOAD WC WITH -1
005310          MOV     #1,@RSCSI               ;DO NO-OP FUNCTION
005316          BIT     #1,@RSCSI               ;DID GO BIT CLEAR
005324          BEQ     .+4                     ;YES
005326          HLT     !CSI                    ;GO BIT SHOULD BE CLEARED
005330          CMP     #150600,@RSDS           ;DID ERR BITS SET?
005336          BEQ     .+4                     ;NO
005340          HLT     !DS                     ;ERR BIT SHOULD BE 0
005342          CMP     #-1,@RSWC               ;DID WC MOVE?
005350          BEQ     .+4                     ;NO
005352          HLT     !WC                     ;WC SHOULD = 1777777
005354          TST     @RSDA                   ;DID DA MOV
005360          BEQ     .+4                     ;NO
005362          HLT     !DA                     ;DA SHOULD =0
005364          CMP     @#OBUFSV,@RSBA          ;DID BA MOVE
005372          BEQ     .+4                     ;NO
005374          HLT     !BA                     ;BA MOVED
005376          BIT     UNCMP,@RSAS             ;AS SHOULD BE SET
005404          BNE     .+4                     ;IS IT?
005406          HLT     !AS                     ;NO
005410          CMP     #7,@RSER                ;DID ER CHANGE?
005416          BEQ     .+4                     ;NO
005420          HLT     !ER                     ;ER SHOULD NOT CHANGE
```

```
                ;*****************************************************************************
                ;TEST 43                 TEST NO-OP FUNCTION CODE 21
                ;*****************************************************************************
005422  TST43:  SCOPE

005424  NOOP21: CLRDK                           ;CLEAR ALL RS REG
005426          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
005434          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
005442          MOV     #-1,@RSWC               ;LOAD WC WITH -1
005450          MOV     #21,@RSCS1              ;DO NO-OP FUNCTION
005456          BIT     #1,@RSCS1               ;DID GO BIT CLEAR
005464          BEQ     .+4                     ;YES
005466          HLT     ;CS1                    ;GO BIT SHOULD BE CLEARED
005470          TST     @RSER                   ;DID ANY ERRORS OCCURR?
005474          BEQ     .+4                     ;NO
005476          HLT     ;ER                     ;ALL ERROR BITS SHOULD BE 0
005500          CMP     #-1,@RSWC               ;DID WC MOVE?
005506          BEQ     .+4                     ;NO
005510          HLT     ;WC                     ;WC SHOULD = 1777777
005512          TST     @RSDA                   ;DID DA MOV
005516          BEQ     .+4                     ;NO
005520          HLT     ;DA                     ;DA SHOULD =0
005522          CMP     @#OBUFSV,@RSBA          ;DID BA MOVE
005530          BEQ     .+4                     ;NO
005532          HLT     ;BA                     ;BA MOVED
005534          BIT     UNCMP,@RSAS             ;AS SHOULD NOT SET ON
005542          BEQ     .+4                     ;A NO-OP FUNCTION
005544          HLT     ;AS                     ;AS SET WHY?
005546          CMP     #4220,@RSCS1            ;IS CS1 CORRECT?
005554          BEQ     .+4                     ;YES
005556          HLT     ;DS                     ;CS1 SHOULD = 4220
```

```
                ;*****************************************************************************
                ;TEST 44                 TEST NO-OP FUNCTION CODE 21 WITH ERROR BITS SET
                ;*****************************************************************************
005560  TST44:  SCOPE

005562  NNOP21: CLRDK                           ;CLEAR ALL RS REG
005564          MOV     #7,@RSER                ;LOAD ER
005572          BIT     UNCMP,@RSAS             ;IS ATA BIT SET?
005600          BNE     .+4                     ;YES
005602          HLT     !AS                     ;AS BIT SHOULD BE SET
005604          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
005612          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
005620          MOV     #-1,@RSWC               ;LOAD WC WITH -1
005626          MOV     #21,@RSCS1              ;DO NO-OP FUNCTION
005634          BIT     #1,@RSCS1               ;DID GO BIT CLEAR
005642          BEQ     .+4                     ;YES
005644          HLT     !CS1                    ;GO BIT SHOULD BE CLEARED
005646          CMP     #150600,@RSDS           ;DID ERR BITS SET?
005654          BEQ     .+4                     ;NO
005656          HLT     !DS                     ;ERR BIT SHOULD BE 0
005660          CMP     #-1,@RSWC               ;DID WC MOVE?
005666          BEQ     .+4                     ;NO
005670          HLT     !WC                     ;WC SHOULD = 1777777
005672          TST     @RSDA                   ;DID DA MOV
005676          BEQ     .+4                     ;NO
005700          HLT     !DA                     ;DA SHOULD =0
005702          CMP     @#OBUFSV,@RSBA          ;DID BA MOVE
005710          BEQ     .+4                     ;NO
005712          HLT     !BA                     ;BA MOVED
005714          BIT     UNCMP,@RSAS             ;AS SHOULD BE SET
005722          BNE     .+4                     ;IS IT?
005724          HLT     !AS                     ;NO
005726          CMP     #7,@RSER                ;DID ER CHANGE?
005734          BEQ     .+4                     ;NO
005736          HLT     !ER                     ;ER SHOULD NOT CHANGE
005740          CMP     #104220,@RSCS1          ;IS CS1 CORRECT?
005746          BEQ     .+4                     ;YES
005750          HLT     !DS                     ;CS1 SHOULD = 104220
```

```
                ;*****************************************************************************
                ;TEST 45                 TEST DRIVE CLEAR FUNCTION WITH ERRORS SET
                ;*****************************************************************************
005752  TST45:  SCOPE
                ;FIRST SET ALL R/W BITS IN DISK REG
                ;DO DRIVE CLEAR-ALL R/W BITS SHOULD BE CLEARED

005754  DRCLR:  CLRDK                           ;CLEAR ALL RS REG
005756          MOV     #177777,@RSWC           ;LOAD RSWC
005764          MOV     #177777,@RSDA           ;SET ALL POSSIBLE
005772          MOV     #177017,@RSER           ;BITS IN DISK REG
006000          MOV     #70,@RSMR               ;SET THESE BITS
006006          MOV     #11,@RSCS1              ;SET DRIVE CLEAR
006014          MOV     @RSCS2,BAD              ;GET CS2 DATA
006020          BIC     #177640,BAD             ;CLEAR JUNK
006024          MOV     UNNUM,GOOD              ;GET DRIVE UNIT
006030          BIS     #100,GOOD               ;SET IR BIT
006034          CMP     GOOD,BAD                ;IS UNIT # THE SAME
006036          BEQ     .+4                     ;YES
006040          HLT                             ;UNIT # IN CS2 GOT MODIFIED
006042          TST     @RSDA                   ;DID DA CLEAR
006046          BEQ     .+4                     ;YES
006050          HLT     !DA                     ;DA SHOULD BE 0
006052          TST     @RSER                   ;DID ER CLEAR
006056          BEQ     .+4                     ;YES
006060          HLT     !ER                     ;ER SHOULD BE CLEARED
006062          MOV     @RSMR,WORK              ;GET MR REG
006070          BIC     #177707,WORK            ;CLEAR JUNK
006076          CMP     #70,WORK                ;IS 70 STILL SET IN MR?
006104          BEQ     .+4                     ;YES
006106          HLT     !MR                     ;BITS 70 SHOULD NOT CLEAR
006110          CMP     #4210,@RSCS1            ;DID THESE BITS CLEAR?
006116          BEQ     .+4                     ;YES
006120          HLT     !CS1                    ;CS1 SHOULD =4210
006122          BIT     UNCMP,@RSAS             ;AS SHOULD NOT SET
006130          BEQ     .+4                     ;ON A DRIVE CLEAR FUN
006132          HLT     !AS                     ;WHY DID AS SET?
006134          CMP     #177777,@RSWC           ;DID RSWC CHANGE?
006142          BEQ     .+4                     ;NO
006144          HLT     !WC
```

```
                ;DO ONE WORD WRITE
                ;*****************************************************************************
                ;TEST 46                 EXECUTE THE ONE WORD WRITE
                ;*****************************************************************************
006146  TST46:  SCOPE

006150  WRTST:  CLRDK                            ;CLEAR ALL RS REG
006152          MOV     #177777,OUTBUF          ;DATA TO BE X-FERED
006160          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
006166          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
006174  1$:     MOV     #60,@RSCS1              ;SET FUNCTION WITH NO GO BIT
006202          CMP     #-1,@RSWC               ;DID WC MOVE?
006210          BEQ     .+4                     ;NO
006212          HLT     !WC                     ;WC MOVED
006214          CMP     @#OBUFSV,@RSBA          ;DID RSBA MOVE?
006222          BEQ     .+4                     ;NO
006224          HLT     !BA                     ;BA MOVED
006226          BIS     #BIT0,@RSCS1            ;SET GO BIT
006234  2$:     TSTB    @RSCS1                  ;TEST FOR RDY=0
006240          BPL     .+4                     ;RDY=0
006242          HLT     !CS1                    ;RDY SHOULD = 0
006244          JSR     PC,WAITRY               ;WAIT FOR READY
006250          HLT     !CS1                    ;SHOULD = 260 RDY NEVER CAME UP
006252          CMP     #1,@RSDA                ;IS RSDA CORRECT
006260          BEQ     .+4                     ;RSDA OK
006262          HLT     !DA                     ;SHOULD = 1 SHOULD INCREMENT
006264  3$:     CMP     #4260,@RSCS1            ;IS ERROR FLAG SET?
006272          BEQ     .+4                     ;NO! X-FER OK
006274          HLT     !CS1!ER!DS!DA           ;ERROR DURING X-FER
006276  4$:     TST     @RSWC                   ;FETCH WORD COUNT
006302          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
006304          HLT     !WC                     ;SHOULD = 0 FAILED TO INCREMENT
006306          CMP     #10600,@RSDS            ;IS RSDS OK?
006314          BEQ     .+4                     ;YES
006316          HLT     !DS!DA                  ;NO
006320          MOV     UNNUM,GOOD              ;GET UNIT #
006324          BIS     #100,GOOD               ;SET IR BIT
006330          MOV     @RSCS2,BAD              ;GET CS2
006334          CMP     GOOD,BAD                ;IS CS2 CORRECT?
006336          BEQ     .+4                     ;YES
006340          HLT                             ;BAD = CS2 GOOD IS CORRECT ANS
006342          MOV     @RSBA,BAD               ;GET BA DATA
006346          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
006352          ADD     #2,GOOD                 ;UPDATE OUTBUFFER
006356          CMP     GOOD,BAD                ;IS RSBA CORRECT
006360          BEQ     .+4                     ;YES
006362          HLT                             ;BA FAILED TO INCREMENT
006364          TST     @RSER                   ;DID ANY ERRORS SET?
006370          BEQ     .+4                     ;NO
006372          HLT     !DS
```

```
                ;TEST READ FUNCTION

                ;*****************************************************************************
                ;TEST 47                 EXECUTE THE ONE WORD READ
                ;*****************************************************************************
006374  TST47:  SCOPE

006376  RDTST:  CLRDK                           ;CLEAR ALL RS REG
006400          CLR     OUTBUF                  ;CLR TO READ INTO
006404          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
006412          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
006420  1$:     MOV     #71,@RSCS1              ;GO READ
006426  2$:     TSTB    @RSCS1                  ;TEST FOR BUSY=1
006432          BPL     .+4                     ;BUSY SET
006434          HLT     !CS1                    ;BUSY NOT SET
006436          JSR     PC,WAITRY               ;WAIT FOR READY
006442          HLT     !CS1                    ;TIMEOUT RDY DID NOT SET
006444          CMP     #BIT0,@RSDA             ;WAS RSDA INCREMENTED BY 1
006452          BEQ     .+4                     ;RSDA OK
006454          HLT     !DA!ER!DS               ;RSDA SHOULD CONTAIN A 1
006456  3$:     CMP     #4270,@RSCS1            ;IS ERROR FLAG SET?
006464          BEQ     .+4                     ;NO! X-FER OK
006466          HLT     !CS1!ER!DS              ;RSCS1 SHOULD = 270
006470  4$:     TST     @RSWC                   ;TEST WC
006474          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
006476          HLT     !WC                     ;SHOULD = 0
006500          MOV     UNNUM,GOOD              ;GET CORRECT
006504          BIS     #100,GOOD               ;ANS OF CS2
006510          MOV     @RSCS2,BAD              ;GET CS2
006514          CMP     GOOD,BAD                ;IS CS2 CORRECT?
006516          BEQ     .+4                     ;YES
006520          HLT                             ;GOOD = CORRECT ANS FOR CS2
006522          MOV     @RSBA,BAD               ;FETCH CURRENT ADDRESS
006526          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
006532          ADD     #2,GOOD                 ;UPDATE IT
006536          CMP     BAD,GOOD                ;IS RSBA CORRECT
006540          BEQ     .+4                     ;YES EXECUTE CONTINUE
006542          HLT                             ;RSBA FAILED TO INCREMENT
006544          MOV     OUTBUF,BAD              ;GET DATA READ FROM DISK
006550          MOV     #-1,GOOD                ;GET CORRECT ANS
006554          CMP     GOOD,BAD                ;IS OUTBUF CORRECT
006556          BEQ     .+4                     ;YES
006560          HLT                             ;GOOD=CORRECT ANS BAD=DATA READ FROM DISK
```

```
                ;*******************************************************************************
                ;TEST 50                 TEST WRITE CHECK
                ;*******************************************************************************
006562          TST50:  SCOPE
                ;DO A ONE WORD WRITE CHECK

                ;* * *EXECUTE THE ONE WORD WRITE CHECK* * *

006564  WRCKT:  CLRDK                           ;CLEAR ALL RS REG
006566          MOV     #177777,OUTBUF          ;DATA TO BE X-FERED
006574          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
006602          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
006610  1$:     MOV     #51,@RSCS1              ;GO WRITE CHECK
006616  2$:     TSTB    @RSCS1                  ;TEST FOR READY
006622          BPL     .+4                     ;NOT READY
006624          HLT     !CS1                    ;BUSY FAILED TO SET
006626  RSWCWT: JSR     PC,WAITRY               ;WAIT FOR READY
006632          HLT     !CS1                    ;BUSY FAILED TO CLEAR
006634          MOV     UNNUM,GOOD              ;GET UNIT #
006640          BIS     #100,GOOD               ;SET BIT IR
006644          MOV     @RSCS2,BAD              ;GET CS2
006650          CMP     GOOD,BAD                ;IS CS2 CORRECT?
006652          BEQ     .+4                     ;YES
006654          HLT                             ;GOOD = CORRECT ANS FOR CS2
006656  2$:     CMP     #4250,@RSCS1            ;ANY ERRORS?
006664          BEQ     .+4                     ;X-FER OK
006666          HLT     !DA!ER!DS               ;ERROR DUR X-FER
006670  3$:     CMP     #BIT0,@RSDA             ;WAS DAR INCREMENTED BY 1
006676          BEQ     .+4                     ;RSDA OK
006700          HLT     !DA                     ;DAR SHOULD = 1
006702          TST     @RSWC                   ;TEST FOR OVERFLOW
006706          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
006710          HLT     !WC                     ;SHOULD = 0
006712          MOV     @RSBA,BAD               ;FETCH CURRENT ADDRESS
006716          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
006722          ADD     #2,GOOD                 ;UPDATE IT
006726          CMP     BAD,GOOD                ;IS RSBA CORRECT
006730          BEQ     .+4                     ;YES EXECUTE CONTINUE
006732          HLT                             ;RSBA FAILED TO INCREMENT
```

```
                ;DO ONE WORD WRITE ON -B- PORT
                ;IF A 1 WD TRANSFER KEEPS SETTING NEM PROGAM WILL GO AND UPDATE
                ;ADDRESS (OBUFSV) ON -B- PORT BY 4K AND TRY TRANSFER AGAIN UNTILL IT
                ;REACHES 28K, IF NO TRANSFER IT THEN SKIPS WRITE,
                ;READ AND WRITE CHECK ON -B- PORT
                ;TO INHIBIT OBUFSV FROM CHANGING SET BIT 12

                ;*************************************************************************
                ;TEST 51                 EXECUTE THE ONE WORD WRITE ON -B- PORT
                ;*************************************************************************
006734  TST51:  SCOPE

006736  WRTSTB: CLRDK                           ;CLEAR ALL RS REG
006740          MOV     @#OBUFSV,WORK           ;GET LOC OF RSBA TO LOAD
006746          MOV     #177777,@WORK           ;DATA TO BE X-FERED
006754          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
006762          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
006770          MOV     #2061,@RSCS1            ;TEST B PORT
006776  2$:     TSTB    @RSCS1                  ;TEST FOR RDY=0
007002          BPL     .+4                     ;RDY=0
007004          HLT     !CS1                    ;RDY SHOULD = 0
007006          JSR     PC,WAITRY               ;WAIT FOR READY
007012          HLT     !CS1                    ;SHOULD = 260 RDY NEVER CAME UP
007014          BIT     #BIT12,@SWR             ;INHIBIT ADDRESS?
007022          BNE     3$                      ;YES
007024          BIT     #BIT11,@RSCS2           ;DID NEM SET?
007032          BEQ     3$                      ;NO
007034          JMP     FINDM                   ;GO FIND MEMORY ON PORT B
007040  3$:     CMP     #1,@RSDA                ;IS RSDA CORRECT
007046          BEQ     .+4                     ;RSDA OK
007050          HLT     !DA                     ;SHOULD = 1 SHOULD INCREMENT
007052          CMP     #6260,@RSCS1            ;IS CS1 CORRECT?
007060          BEQ     4$                      ;YES
007062          HLT     !CS1
007064  4$:     TST     @RSWC                   ;FETCH WORD COUNT
007070          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
007072          HLT     !WC                     ;SHOULD = 0 FAILED TO INCREMENT
007074          CMP     #10600,@RSDS            ;IS RSDS OK?
007102          BEQ     .+4                     ;YES
007104          HLT     !DS!DA                  ;NO
007106          MOV     UNNUM,GOOD              ;GET UNIT #
007112          BIS     #100,GOOD               ;SET IR BIT
007116          MOV     @RSCS2,BAD              ;GET CS2
007122          CMP     GOOD,BAD                ;IS CS2 CORRECT?
007124          BEQ     .+4                     ;YES
007126          HLT                             ;BAD = CS2 GOOD IS CORRECT ANS
007130          MOV     @RSBA,BAD               ;GET BA DATA
007134          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
007140          ADD     #2,GOOD                 ;UPDATE OUTBUFFER
007144          CMP     GOOD,BAD                ;IS RSBA CORRECT
007146          BEQ     .+4                     ;YES
007150          HLT                             ;BA FAILED TO INCREMENT
```

```
                ;*******************************************************************************
                ;TEST 52                 EXECUTE THE ONE WORD READ ON -B- PORT
                ;*******************************************************************************
007152  TST52:  SCOPE

007154  RDTSTB: CLRDK                           ;CLEAR ALL RS REG
007156          CLR     WORK                    ;CLR TO READ INTO
007162          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
007170          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
007176          MOV     #2071,@RSCS1            ;B PORT
007204  2$:     TSTB    @RSCS1                  ;TEST FOR BUSY=1
007210          BPL     .+4                     ;BUSY SET
007212          HLT     !CS1                    ;BUSY NOT SET
007214          JSR     PC,WAITRY               ;WAIT FOR READY
007220          HLT     !CS1                    ;TIMEOUT RDY DID NOT SET
007222          CMP     #BIT0,@RSDA             ;WAS RSDA INCREMENTED BY 1
007230          BEQ     .+4                     ;RSDA OK
007232          HLT     !DA!ER!DS               ;RSDA SHOULD CONTAIN A 1
007234          CMP     #6270,@RSCS1            ;TST B PORT
007242          BEQ     4$                      ;OK
007244          HLT     !CS1                    ;CS1 SHOULD = 6270
007246  4$:     TST     @RSWC                   ;TEST WC
007252          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
007254          HLT     !WC                     ;SHOULD = 0
007256          MOV     UNNUM,GOOD              ;GET CORRECT
007262          BIS     #100,GOOD               ;ANS OF CS2
007266          MOV     @RSCS2,BAD              ;GET CS2
007272          CMP     GOOD,BAD                ;IS CS2 CORRECT?
007274          BEQ     .+4                     ;YES
007276          HLT                             ;GOOD = CORRECT ANS FOR CS2
007300          MOV     @RSBA,BAD               ;FETCH CURRENT ADDRESS
007304          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
007310          ADD     #2,GOOD                 ;UPDATE IT
007314          CMP     BAD,GOOD                ;IS RSBA CORRECT
007316          BEQ     .+4                     ;YES EXECUTE CONTINUE
007320          HLT                             ;RSBA FAILED TO INCREMENT
007322          MOV     @#OBUFSV,WORK           ;GET DATA READ FROM DISK
007330          MOV     @WORK,BAD
007334          MOV     #-1,GOOD                ;GET CORRECT ANS
007340          CMP     GOOD,BAD                ;IS OUTBUF CORRECT
007342          BEQ     .+4                     ;YES
007344          HLT                             ;GOOD=CORRECT ANS BAD=DATA READ FROM DISK
```

```
                ;*****************************************************************
                ;TEST 53                 TEST WRITE CHECK ON -B- PORT
                ;*****************************************************************
007346  TST53:  SCOPE


007350  WRCKTB: CLRDK                           ;CLEAR ALL RS REG
007352          MOV     @#OBUFSV,WORK           ;GET LOC FOR
007360          MOV     #177777,@WORK           ;DATA TO BE X-FERED
007366          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
007374          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
007402          MOV     #2051,@RSCS1            ;B PORT
007410  2$:     TSTB    @RSCS1                  ;TEST FOR READY
007414          BPL     .+4                     ;NOT READY
007416          HLT     ;CS1                    ;BUSY FAILED TO SET
007420          JSR     PC,WAITRY               ;WAIT FOR READY
007424          HLT     !CS1                    ;BUSY FAILED TO CLEAR
007426          MOV     UNNUM,GOOD              ;GET UNIT #
007432          BIS     #100,GOOD               ;SET BIT IR
007436          MOV     @RSCS2,BAD              ;GET CS2
007442          CMP     GOOD,BAD                ;IS CS2 CORRECT?
007444          BEQ     .+4                     ;YES
007446          HLT                             ;GOOD = CORRECT ANS FOR CS2
007450          CMP     #6250,@RSCS1            ;IS CS1 CORRECT?
007456          BEQ     3$                      ;YES
007460          HLT     !CS1                    ;CS1 SHOULD = 6250
007462  3$:     CMP     #BIT0,@RSDA             ;WAS DAR INCREMENTED BY 1
007470          BEQ     .+4                     ;RSDA OK
007472          HLT     !DA                     ;DAR SHOULD = 1
007474          TST     @RSWC                   ;TEST FOR OVERFLOW
007500          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
007502          HLT     ;WC                     ;SHOULD = 0
007504          MOV     @RSBA,BAD               ;FETCH CURRENT ADDRESS
007510          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
007514          ADD     #2,GOOD                 ;UPDATE IT
007520          CMP     BAD,GOOD                ;IS RSBA CORRECT
007522          BEQ     .+4                     ;YES EXECUTE CONTINUE
007524          HLT                             ;RSBA FAILED TO INCREMENT
```

```
007526  NXM:    MOV     OBUFSV,BPORTT   ;SAVE -B- PORT BUFFER
007534          MOV     #OUTBUF,OBUFSV  ;RESTORE OBUFSV

        ;DESELECT THEN SELECT UNIT NUMBER IN RSCS2 CHECK TIMING
        ;*************************************************************************
        ;TEST 54                 DESELECT THEN SELECT UNIT NUMBER TIMING TEST
        ;*************************************************************************
007542  TST54:  SCOPE

007544  UNITST: CLRDK                           ;CLEAR ALL RS REG
007546          CLR     R4                      ;CLEAR R4
007550          CMP     R4,UNNUM                ;IS THIS CORRECT UNIT #?
007554          BNE     3$                      ;NO THEN USE IT
007556          INC     R4                      ;GET WRONG DRIVE
007560  3$:     MOV     #177777,OUTBUF          ;DATA TO BE X-FERED
007566          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
007574          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
007602          MOV     #61,R3                  ;GET WRITE FUNCTION
007606          MOV     UNNUM,R5                ;GET CORRECT UNIT #
007612          MOV     #172040,R1              ;GET CS1 REG
007616          MOV     R4,10(R1)               ;LOAD WRONG UNIT # INTO CS2
007622          NOP                             ;WAIT FOR DRIVE TO SETTLE
007624          MOV     R5,10(R1)               ;LOAD CORRECT UNIT #
007630  1$:     MOV     R3,(R1)                 ;LOAD FUNCTION IN CS1
007632          JSR     PC,WAITRY               ;WAIT FOR READY
007636          HLT     !CS1                    ;SHOULD = 260 RDY NEVER CAME UP
007640          CMP     #4260,@RSCS1            ;IS ERROR FLAG SET?
007646          BEQ     .+4                     ;NO! X-FER OK
007650          HLT     !CS1!ER!DS!DA           ;ERROR DURING X-FER
007652          CMP     #1,@RSDA                ;IS RSDA CORRECT
007660          BEQ     .+4                     ;RSDA OK
007662          HLT     !DA                     ;SHOULD = 1 SHOULD INCREMENT
007664          TST     @RSWC                   ;FETCH WORD COUNT
007670          BEQ     .+4                     ;WORD COUNT DID OVERFLOW
007672          HLT     !WC                     ;SHOULD = 0 FAILED TO INCREMENT
007674          CMP     #10600,@RSDS            ;IS RSDS OK?
007702          BEQ     .+4                     ;YES
007704          HLT     !DS!DA                  ;NO
007706          MOV     UNNUM,GOOD              ;GET UNIT #
007712          BIS     #100,GOOD               ;SET IR BIT
007716          MOV     @RSCS2,BAD              ;GET CS2
007722          CMP     GOOD,BAD                ;IS CS2 CORRECT?
007724          BEQ     .+4                     ;YES
007726          HLT                             ;BAD = CS2 GOOD IS CORRECT ANS
007730          MOV     @RSBA,BAD               ;GET BA DATA
007734          MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD EQUAL
007740          ADD     #2,GOOD                 ;UPDATE OUTBUFFER
007744          CMP     GOOD,BAD                ;IS RSBA CORRECT
007746          BEQ     .+4                     ;YES
007750          HLT                             ;BA FAILED TO INCREMENT
```

```
                ;TEST CURRENT ADDRESS INHIBT-BAI IN RSCS2
                ;DO A ONE WORD WRITE AND SEE
                ;IF RSBA INCREMENTED AFTER THE X-FER

                ;*****************************************************************************
                ;TEST 55                 TEST BAI IN RSCS2
                ;*****************************************************************************
007752  TST55:  SCOPE

007754  BAITST: CLRDK                           ;CLEAR ALL RS REG
007756          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDR
007764          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
007772          BIS     #BAI,@RSCS2             ;SET BAI BIT
010000          MOV     #61,@RSCS1              ;WRITE
010006          JSR     PC,WAITRY               ;WAIT FOR READY
010012          HLT     !CS1                    ;RDY DID NOT SET
010014  1$:     MOV     @#OBUFSV,GOOD           ;WHAT RSBA SHOULD BE
010020          MOV     @RSBA,BAD               ;WHAT RSBA IS
010024          CMP     GOOD,BAD                ;COMPARE
010026          BEQ     .+4                     ;YES
010030          HLT                             ;BAD=OUTBUF GOOD = CORRECT ANS
010032          TST     @RSER                   ;ANY ERRORS?
010036          BEQ     .+4                     ;NO
010040          HLT     !DS                     ;YES
010042          CLRDK                           ;CLEAR ALL RS REG
010044          BIT     #BAI,@RSCS2             ;DID BAI CLEAR?
010052          BEQ     .+4                     ;YES
010054          HLT     !ER                     ;BAI DID NOT SET
```

```
                ;*****************************************************************************
                ;TEST 56                 TEST NON-EXISTENT MEMORY ERROR BIT IN CS2
                ;*****************************************************************************
010056  TST56:  SCOPE

010060  NXMTSM: CLRDK                           ;CLEAR ALL RS REG
010062          BIS     #BAI,@RSCS2             ;SET BAI BIT
010070          MOV     #-200,@RSWC             ;SET UP WORD COUNT
010076          MOV     #173000,@RSBA           ;SET UP CURRENT ADDRESS
010104          MOV     #1471,@RSCS1            ;READ AND LOAD A16 +A17 FOR 18 BIT ADDRESS
010112          JSR     PC,WAITRY               ;WAIT FOR READY
010116          HLT     !DS                     ;READY NEVER CAME UP
010120  TSTNEM: MOV     UNNUM,GOOD              ;GET UNIT NO.
010124          BIS     #4310,GOOD              ;SET BAI+OR BITS
010130          MOV     @RSCS2,BAD              ;GET CS2
010134          CMP     GOOD,BAD                ;IS CS2 CORRECT?
010136          BEQ     .+4                     ;YES
010140          HLT                             ;BAD=CS2 GOOD=CORRECT ANS FOR CS2
010142          CMP     #145670,@RSCS1          ;DID TRE SET?
010150          BEQ     .+4                     ;YES
010152          HLT     !CS1                    ;TRE SHOULD SET BECAUSE OF NEM
010154          MOV     #TRE,@RSCS1             ;CLEAR TRE
010162          MOV     @RSCS2,BAD              ;GET CS2
010166          MOV     UNNUM,GOOD              ;GET DRIVE
010172          BIS     #310,GOOD               ;SET IR
010176          CMP     GOOD,BAD                ;IS CS2 CORRECT?
010200          BEQ     .+4                     ;YES
010202          HLT     !CS2                    ;CS2=BAD GOOD IS CORRECT ANS FOR CS2

                ;*****************************************************************************
                ;TEST 57                 TEST BLOCK SEARCH FUNCTION, PIP AND DRY BIT AND ADDR. CONF BIT
                ;*****************************************************************************
010204  TST57:  SCOPE

010206  BLOCK:  CLRDK                           ;CLEAR ALL RS REG
010210          MOV     #32,@RSDA               ;DO A SEARCH FOR SECTOR 32
010216          MOV     @#OBUFSV,@RSBA          ;LOAD REGS. TO MAKE
010224          MOV     #-1,@RSWC               ;SURE THEY DO NOT CHANGE
010232          CLR     WORK                    ;SETUP FOR TIMEOUT ROUTINE
010236  4$:     BIT     #1000,@RSMR             ;WAIT FOR DISK TO
010244          BNE     3$                      ;REACH SECTOR 32
010246          DEC     WORK                    ;TIME OUT
010252          BNE     4$                      ;ROUTINE
010254          HLT     !MR                     ;COULD NOT FIND SECTOR 32
```

```
010256  3$:     CLR     @RSDA           ;NOW SEARCH FOR 0
010262          MOV     #31,@RSCS1      ;DO A BLOCK SEARCH FUNCTION
010270          BIT     #DRY,@RSDS      ;IS DRY CLEARED?
010276          BEQ     1$              ;YES
010300          HLT     !DS             ;DRY SHOULD BE CLEARED DURING A BLOCK SEARCH
010302          BR      OOUT            ;GET OUT BECAUSE OF TIMING
010304  1$:     BIT     #20000,@RSDS    ;IS PIP SET?
010312          BNE     .+4             ;YES
010314          HLT     !DS             ;PIP SHOULD BE SET
010316          MOV     #20000,GOOD     ;SETUP FOR TIMEOUT ROUTINE
010322  2$:     DEC     GOOD            ;DO TIMEOUT
010324          BEQ     TTMOUT          ;TIMED OUT
010326          BIT     #DRY,@RSDS      ;DID DRY SET?
010334          BEQ     2$              ;NO
010336          CMP     #110600,@RSDS   ;DID PIP CLEAR?
010344          BEQ     .+4             ;YES
010346          HLT     !DS             ;PIP BIT DID NOT CLEAR
010350          CMP     #104230,@RSCS1  ;DID SC SET?
010356          BEQ     .+4             ;YES
010360          HLT     !CS1!DS         ;SC DID NOT SET
010362          MOV     UNNUM,WORK      ;GET CORRECT AS BIT
010370          CLR     GOOD            ;IN RSAS REG
010372          SEC                     ;THAT SHOULD
010374  5$:     ROL     GOOD            ;BE SET
010376          TST     WORK
010402          BEQ     6$
010404          DEC     WORK
010410          BR      5$
010412  6$:     CMP     GOOD,@RSAS      ;IS RSAS CORRECT?
010416          BEQ     7$              ;YES
010420          MOV     @RSAS,BAD       ;NO
010424          HLT
010426  7$:     MOV     GOOD,@RSAS      ;CLEAR AS REG
010432          TST     @RSAS           ;DID IT CLEAR?
010436          BEQ     .+4             ;YES
010440          HLT     !AS             ;NO
010442          CMP     #10600,@RSDS    ;DID ATA CLEAR?
010450          BEQ     .+4             ;YES
010452          HLT     !DS             ;NO
010454          CMP     @#OBUFSV,@RSBA  ;DID BA MOVE?
010462          BEQ     .+4             ;NO
010464          HLT     !CS1!BA         ;BA MOVED WHY?
010466          CMP     #-1,@RSWC       ;DID WC MOVE?
010474          BEQ     .+4             ;NO
010476          HLT     !WC             ;WC MOVED WHY?
010500          BR      OOUT            ;DONE GET OUT
010502  TTMOUT: HLT     !DS             ;DYR NEVER CAME UP
010504  OOUT:                           ;DONE
```

```
                ;*****************************************************************************
                ;TEST 60                 ILLEGAL FUNCTION CODE TEST CODE 3 TO 51
                ;*****************************************************************************
010504          TST60:  SCOPE

                ;TEST ILF BIT IN RSER AND ERR BIT IN RSDS
                ;ALSO CHECKS TO SEE IF WC, BA, OR DA GOT MODIFIED
                ;IF WISHING TO LOOP ON ONE FUNCTION ONLY, LOAD
                ;FUNCTION INTO LOCATION ILLTAB: AND 0 IN FOLLOWING LOCATION

010506  ILL51:  MOV     TIMES,TIMSV     ;SAVE LOOP COUNT
010514          MOV     #10,TIMES       ;LOOP TEN TIMES
010522          CLRDK                   ;CLEAR ALL RS REG
010524  1$:     MOV     #ILLTAB,R3      ;GET STARTING ADD OF TABLE
010530  3$:     MOV     (R3)+,BAD       ;GET ILL FUN
010532          BEQ     ILFDN           ;DONE GET OUT
010534          MOV     @#OBUFSV,@RSBA  ;SET UP REGS,
010542          MOV     #-1,@RSWC       ;TO CHECK FOR CHANGE
010550  2$:     MOV     BAD,@RSCS1      ;DO ILLEGAL FUNCTION
010554          BIC     #BIT0,BAD       ;CLEAR GO BIT
010560          MOV     BAD,GOOD        ;MOV ILLEGAL FUN INTO GOOD
010562  6$:     TSTB    @RSCS1          ;RDY SET?
010566          BPL     6$              ;NO
010570          BIS     #104200,GOOD    ;SET ERROR BITS
010574  4$:     MOV     @RSCS1,BAD      ;PUT CS1 INTO BAD
010600          CMP     GOOD,BAD        ;IS CS1 CORRECT?
010602          BEQ     .+4             ;YES
010604          HLT                     ;GOOD IS WHAT CS1 SHOULD =BAD=CS1
010606          CMP     #1,@RSER        ;DID ILF SET?
010614          BEQ     .+4             ;YES
010616          HLT     !CS1!ER!DS      ;ILF DID NOT SET
010620          CMP     #150600,@RSDS   ;IS DS GOOD?
010626          BEQ     .+4             ;YES
010630          HLT     !CS1!ER!DS      ;ERR DID NOT SET
010632          MOV     @RSCS2,BAD      ;GET CS2
010636          MOV     UNNUM,GOOD      ;GET UNIT #
010642          BIS     #100,GOOD       ;SET IR BIT
010646          CMP     GOOD,BAD        ;IS CS2 CORRECT?
010650          BEQ     .+4             ;YES
010652          HLT                     ;GOOD = CORRECT ANS FOR CS2
010654          MOV     UNCMP,GOOD      ;GET CORRECT DRIVE
010660          BIC     #177400,GOOD    ;CLEAR UNWANTED BITS
010664          MOV     @RSAS,BAD       ;GET RSAS REG
010670          CMP     BAD,GOOD        ;DID CORRECT UNIT ANSWER?
010672          BEQ     .+4             ;YES
010674          HLT     !AS             ;NO WRONG DRIVE ANSWERED
```

```
010676                  CMP     @#OBUFSV,@RSBA  ;DID BA MOVE
010704                  BEQ     .+4             ;NO
010706                  HLT     !CS1!BA         ;BA MOVED ON AN ILLEGAL FUNCTION
010710                  CMP     #-1,@RSWC       ;DID WC MOVE?
010716                  BEQ     .+4             ;NO
010720                  HLT     !CS1!WC         ;WC MOVED
010722                  TST     @RSDA           ;DID DA MOVE
010726                  BEQ     .+4             ;NO
010730                  HLT     !CS1!DA         ;DA MOVED
010732                  CLRDK                   ;CLEAR ALL ERRORS
010734                  TST     @RSER           ;DID ERRORS CLEAR
010740                  BEQ     .+4             ;YES
010742                  HLT     !DS             ;ILF DID NOT CLEAR
010744                  CMP     #4200,@RSCS1    ;DID ERRORS IN CS1 CLEAR
010752                  BEQ     .+4             ;YES
010754                  HLT     !DS
010756                  JMP     3$              ;CONTINUE UNTIL DONE
010762  ILFDN:                                  ;DONE WITH ILLEGAL FUNCTION TEST
        ;*****************************************************************************
        ;TEST 61                 ILLEGAL FUNCTION CODE TEST CODE 53 TO 77
        ;*****************************************************************************
010762  TST61:  SCOPE

        ;TEST ILF BIT IN RSER AND ERR BIT IN RSDS
        ;ALSO CHECKS TO SEE IF WC,BA, OR DA GOT MODIFIED
        ;IF WISHING TO LOOP ON ONE FUNCTION ONLY, LOAD
        ;FUNCTION INTO LOCATION ILFTB2: AND 0 IN FOLLOWING LOCATION

010764  ILLFUN: CLRDK                           ;CLEAR ALL RS REG
010766  1$:     MOV     #ILFTB2,R3              ;GET TABLE OF ILL FUNS.
010772  3$:     CLR     WORK                    ;CLEAR WORK
010776          MOV     (R3)+,BAD               ;GET ILL FUN
011000          BEQ     ILFDN                   ;DONE GET OUT
011002          MOV     @#OBUFSV,@RSBA          ;SET UP REGS.
011010          MOV     #-1,@RSWC               ;TO CHECK FOR CHANGE
011016          MOV     BAD,WORK1               ;SHOULD WE TEST
011022          BIC     #177707,WORK1           ;BA AND WC
011030          CMP     #60,WORK1               ;TO INC
011036          BNE     2$                      ;NO
011040          MOV     #7,WORK                 ;YES
011046  2$:     MOV     BAD,@RSCS1              ;DO ILLEGAL FUNCTION
011052  10$:    BIC     #BIT0,BAD               ;CLEAR GO BIT
011056          MOV     BAD,GOOD                ;MOV ILLEGAL FUN INTO GOOD
```

```
011060  6$:     TSTB    @RSCS1          ;RDY SET?
011064          BPL     6$              ;NO
011066          BIS     #144200,GOOD    ;SET ERROR BITS
011072          MOV     @RSCS1,BAD      ;PUT CS1 INTO BAD
011076          CMP     GOOD,BAD        ;IS CS1 CORRECT?
011100          BEQ     .+4             ;YES
011102          HLT                     ;GOOD IS WHAT CS1 SHOULD =BAD=CS1
011104          CMP     #1,@RSER        ;DID ILF SET?
011112          BEQ     .+4             ;YES
011114          HLT     !CS1!ER!DS      ;ILF DID NOT SET
011116          CMP     #150600,@RSDS   ;IS DS GOOD?
011124          BEQ     .+4             ;YES
011126          HLT     !CS1!ER!DS      ;ERR DID NOT SET
011130          TST     @RSDA           ;DID DA MOVE?
011134          BEQ     .+4             ;NO
011136          HLT     !CS1!DA         ;DA MOVED
011140          TST     WORK            ;IS THIS AN ILL WRITE FUN?
011144          BNE     11$             ;YES
011146          MOV     @RSCS2,BAD      ;GET CS2
011152          MOV     UNNUM,GOOD      ;GET UNIT #
011156          BIS     #1100,GOOD      ;SET IR BIT
011162          CMP     GOOD,BAD        ;IS CS2 CORRECT?
011164          BEQ     .+4             ;YES
011166          HLT                     ;GOOD = CORRECT ANS FOR CS2
011170          CMP     @#OBUFSV,@RSBA  ;DID BA MOVE
011176          BEQ     .+4             ;NO
011200          HLT     !CS1!BA         ;BA MOVED ON AN ILLEGAL FUNCTION
011202          CMP     #-1,@RSWC       ;DID WC MOVE?
011210          BEQ     .+4             ;NO
011212          HLT     !CS1!WC         ;WC MOVED
011214          JMP     4$              ;CONTINUE UNTIL DONE
011220  11$:    MOV     @RSCS2,BAD      ;GET CS2
011224          MOV     UNNUM,GOOD      ;GET UNIT #
011230          BIS     #1300,GOOD      ;SET IR BIT
011234          CMP     GOOD,BAD        ;IS CS2 CORRECT?
011236          BEQ     .+4             ;YES
011240          HLT                     ;GOOD = CORRECT ANS FOR CS2
011242          MOV     @#OBUFSV,WORK   ;GET BUFFER ADDR.
011250          ADD     #2,WORK         ;UPDATE IT
011256          CMP     WORK,@RSBA      ;DID BA MOVE
011264          BEQ     .+4             ;YES
011266          HLT     !CS1!BA         ;BA MOVED ON AN ILLEGAL FUNCTION
011270          CMP     #0,@RSWC        ;DID WC MOVE?
011276          BEQ     .+4             ;NO
011300          HLT     !CS1!WC         ;WC MOVED
011302  4$:     CLRDK                   ;CLEAR ALL ERRORS
011304          CMP     #4200,@RSCS1    ;DID ERRORS CLEAR
011312          BEQ     .+4             ;YES
011314          HLT     !DS             ;NO
011316          TST     @RSER           ;DID ERROR CLEAR
011322          BEQ     .+4             ;NO
011324          HLT     !DS             ;YES
011326          JMP     3$              ;CONTINUE UNTIL DONE
011332  ILFDNE:                         ;DONE WITH ILLEGAL FUNCTION TEST
```

```
                ;*****************************************************************************
                ;TEST 62                 TEST ILLEGAL FUNCTION CODE 67
                ;*****************************************************************************
011332  TST62:  SCOPE

011334  ILF67:  CLRDK                           ;CLEAR ALL RS REG
011336          MOV     #-1,@RSWC               ;SET WC TO -1
011344          MOV     @#OBUFSV,WORK           ;GET OUTBUF ADD.
011352          ADD     #2,WORK                 ;FOR TEST
011360          MOV     WORK,@RSBA              ;LOAD ADDR.
011366          MOV     #67,@RSCS1              ;DO FUNCTION 67
011374  1$:     TSTB    @RSCS1                  ;DONE YET?
011400          BPL     1$                      ;NO
011402          MOV     @RSBA,BAD               ;GET BA REG
011406          MOV     @#OBUFSV,GOOD           ;GET CORRECT ANS FOR RSBA
011412          CMP     GOOD,BAD                ;IS RSBA CORRECT?
011414          BEQ     .+4                     ;YES
011416          HLT                             ;BAD=RSBA GOOD=CORRECT ANS.
011420          MOV     UNNUM,GOOD              ;GET UNIT NUMBER
011424          BIS     #1300,GOOD              ;SET IR AND OR BITS
011430          MOV     @RSCS2,BAD              ;GET CS2
011434          CMP     GOOD,BAD                ;IS CS2 CORRECT?
011436          BEQ     .+4                     ;YES
011440          HLT                             ;BAD=CS2 GOOD=CORRECT ANS
011442          CMP     #1,@RSER                ;IS RSER CORRECT?
011450          BEQ     .+4                     ;YES
011452          HLT     !ER                     ;ER IS WRONG
011454          CLRDK                           ;CLEAR ALL RS REG
011456          TST     @RSER                   ;DID ERROR CLEAR
011462          BEQ     .+4                     ;YES
011464          HLT     !DS                     ;NO
011466          MOV     #-100,@RSWC             ;SET WC TO -100
011474          MOV     @#OBUFSV,WORK           ;GET OUTBUF ADD.
011502          ADD     #200,WORK               ;FOR TEST
011510          MOV     WORK,@RSBA              ;LOAD ADDR
011516          MOV     #67,@RSCS1              ;DO FUNCTION 67
011524  2$:     TSTB    @RSCS1                  ;DONE YET?
011530          BPL     2$                      ;NO
```

```
011532  3$:     MOV     @#OBUFSV,GOOD   ;GET CORRECT ANS.
011536          MOV     @RSBA,BAD       ;GET BA REG
011542          CMP     GOOD,BAD        ;IS RSBA CORRECT?
011544          BEQ     .+4             ;YES
011546          HLT                     ;BAD=RSBA GOOD=CORRECT ANS.
011550          MOV     UNNUM,GOOD      ;GET UNIT NUMBER
011554          BIS     #1300,GOOD      ;SET IR AND OR BITS
011560          MOV     @RSCS2,BAD      ;GET CS2
011564          CMP     GOOD,BAD        ;IS CS2 CORRECT?
011566          BEQ     .+4             ;YES
011570          HLT                     ;BAD=CS2 GOOD=CORRECT ANS
011572          CMP     #1,@RSER        ;IS RSER CORRECT?
011600          BEQ     .+4             ;YES
011602          HLT     !ER             ;ER IS WRONG
011604          MOV     #40011,@RSCS1   ;CLEAR ERRORS
011612          CMP     #4210,@RSCS1    ;DID THEY CLEAR IN CS1
011620          BEQ     .+4             ;YES
011622          HLT     !DS             ;NO
011624          TST     @RSER           ;DID RSER CLEAR
011630          BEQ     .+4             ;YES
011632          HLT     !DS             ;NO
011634          TST     @RSAS           ;DID RSAS CLEAR
011640          BEQ     .+4             ;YES
011642          HLT     !AS             ;NO

                ;*****************************************************************
                ;TEST 63                 TEST PAR IN RSER
                ;*****************************************************************
011644  TST63:  SCOPE

011646  PARTST: MOV     TIMSV,TIMES     ;RESTORE LOOP #
011654          CLRDK                   ;CLEAR ALL RS REG
011656  1$:     MOV     #10,@RSER       ;SET PAR
011664          CMP     #150600,@RSDS   ;DID ERR,ATA AND DRY SET?
011672          BEQ     .+4             ;YES
011674          HLT     !DS!ER          ;ER SHOULD SET IF PAR SETS IN RSER
011676          CLRDK                   ;CLEAR ALL RS REG
011700          TST     @RSER           ;DID PAR CLEAR?
011704          BEQ     .+4             ;YES
011706          HLT     !ER             ;PAR DID NOT CLEAR BY CLEAR  BIT
011710          CMP     #10600,@RSDS    ;DID ERROR BITS CLEAR
011716          BEQ     .+4             ;YES
011720          HLT     !DS             ;NO
```

```
                ;CHECK BITS 12 TO 15 FOR 0
                ;CHECK SECTOR FRACTION TO WATCH FOR MOVEMENT
                ;CHECK CS BITS IN LA AND ADDRESS CONFIRM IN MR REG

                ;*************************************************************************
                ;TEST 64                 LOOK AHEAD TEST
                ;*************************************************************************
011722  TST64:  SCOPE

011724  LATST:  BIT     #170000,@RSLA   ;ARE BITS 12 TO 15 CLEARED?
011732          BEQ     .+4             ;YES
011734          HLT     !LA             ;BITS 12 TO 15 SHOULD BE CLEARED
011736  TST65:  SCOPE

                ;NOW TEST MOVEMENT IN SF BITS

011740          MOV     #171005,WORK    ;SET UP FOR TIME OUT ROUTIME
011746          MOV     @RSLA,GOOD      ;GET READING FROM LA
011752          BIC     #7700,GOOD      ;GET RID OF CS BITS
011756  1$:     DEC     WORK            ;WAIT FOR DISK
011762          BEQ     ERRR            ;TYPE ERROR
011764          MOV     @RSLA,BAD       ;READ LA
011770          BIC     #7700,BAD       ;CLEAR CS BITS
011774          CMP     GOOD,BAD        ;DID SF BITS CHANGE?
011776          BEQ     1$              ;WAIT FOR TIME OUT
012000          BR      LATDON          ;LA OK CONT
012002  ERRR:
012002          TYPE    .+2             ;.ASCIZ <15><12>"SECTOR FRACTIONS NOT MOVING"
012044          HLT     !LA             ;TYPE LOOK AHEAD REG
012046  LATDON:                         ;DONE CONT.
```

```
                ;*************************************************************************
                ;TEST 66                 CHECK CS BITS TO INCREMENT AND  ADDRESS CONFIRM BIT IN MR
                ;*************************************************************************
012046  TST66:  SCOPE

012050  CSTST:  MOV     TIMES,TIMSV     ;SAVE LOOP CT
012056          MOV     #10,TIMES       ;LOOP 10 TIMES
012064          CLRDK                   ;CLEAR ALL RS REG.
012066          MOV     #1000,GOOD      ;LOAD COUNTER
012072          BIT     #BIT9,@RSMR     ;IS ADD CONFIRM BIT 0?
012100          BEQ     ADDCF           ;YES CONTINUE
012102          DEC     GOOD            ;WAIT FOR
012104          BNE     .-2             ;DISK TO MOVE
012106          BIT     #BIT9,@RSMR     ;IS AADD. CON. BIT BIT 0?
012114          BEQ     .+4             ;YES
012116          HLT     !MR             ;ADD. CONF. BIT ALWAYS A 1

                ;NOW TEST TA BITS AND ADD. CON. BIT IN MR

012120  ADDCF:  MOV     #-1,@RSDA       ;INIT RSDA
012126  1$:     MOV     #-1,WORK        ;SETUP TIMEOUT COUNTER
012134          INC     @RSDA           ;GET NEXT SECTOR
012140          CMP     #10000,@RSDA    ;DONE ALL YET?
012146          BEQ     DONCS           ;YES
012150  2$:     DEC     WORK            ;DO TIMEOUT ROUTINE
012154          BEQ     TMEOUT          ;ADD. CON. NEVER CAME UP
012156          BIT     #1000,@RSMR     ;DID ADD CONFIRM BIT SET?
012164          BEQ     2$              ;YES
012166          MOV     @RSLA,BAD       ;GET LA
012172          BIC     #77,BAD         ;CLEAR SF BITS
012176          MOV     #6,WORK1        ;SET UP COUNTER
012204  3$:     ROR     BAD             ;MOV SA BITS RIGHT
012206          DEC     WORK1           ;DO 6 TIMES
012212          BNE     3$              ;DONE YET?
012214          MOV     @RSDA,GOOD      ;GET DA
012220          BIC     #177700,GOOD    ;CLEAR JUNK
012224          CMP     GOOD,BAD        ;ARE SA BITS = IN DA AND LA REG.?
012226          BEQ     .+4             ;OK
012230          HLT                     ;GOOD =DA BAD = LA
012232          BR      1$              ;NO WAIT

012234  TMEOUT: HLT     !MR!ER!DS       ;ADDRESS CONFIRM BIT NEVER SET COULD BE BAD OR
                                        ;BAD LA OR BAD COMPARE BETWEEN LA AND DA
012236  DONCS:                          ;TEST DONE CONTINUE
```

```
                ;*****************************************************************************
                ;TEST 67                 PARITY TEST
                ;*****************************************************************************
012236  TST67:  SCOPE

012240  PART:   MOV     TIMSV,TIMES     ;RESTORE LOOP COUNTER
012246          MOV     #PRTP,@#4       ;SETUP TIME OUT VECTOR
012254          MOV     #340,@#6
012262          MOV     #MPR0,R2        ;GET PAR REG
012266  TSTAGN: TST     (R2)            ;DOES IT EXIST
012270          MOV     #WWP,@R2        ;YES SET WRITE WRONG PARITY
012274          MOV     #PARITY,R1      ;GET TEST LOCATION
012300  1$:     MOV     @R1,@R1         ;WRITE WRONG PARITY
012302          TST     @R1             ;READ IT
012304          TST     @R2             ;DID PARITY ERROR SET?
012306          BMI     2$              ;YES
012310          CLR     @R2             ;CLEAR PARITY REG
012312          BR      PRTP1           ;GET NEXT PARITY REG
012314  2$:     BIC     #100005,@R2     ;TURN OFF WWP,ENABLE BAD PARITY, ACTION ENABLE
012320          TST     @R2     ;PARITY ERROR?
012322          BEQ     NOPAR   ;IF NO BR.
012324          MOV     #1,@R2          ;CLEAR WWP AND ENABLE BAD PARITY AND ACTION ENABLE

012330          CLRDK                   ;CLEAR ALL RS REG
012332          MOV     #PARITY,@RSBA   ;SET UP CURRENT ADDRESS
012340          MOV     #-1,@RSWC       ;SET WORD COUNT TO -1
012346          MOV     #61,@RSCS1      ;GO WRITE
012354  3$:     TSTB    @RSCS1          ;DONE YET?
012360          BPL     3$              ;NO WAIT
012362          MOV     @RSCS2,BAD      ;GET CS2
012366          MOV     #20100,GOOD
012372          BIS     UNNUM,GOOD      ;GET CORRECT AND FOR CS2
012376          CMP     GOOD,BAD        ;IS CS2 CORRECT?
012400          BEQ     .+4             ;YES
012402          HLT                     ;CS2 SHOULD = GOOD
012404          CMP     #144260,@RSCS1  ;IS CS1 CORRECT?
012412          BEQ     .+4             ;YES
012414          HLT     !DS
012416          JMP     NOPAR           ;GET OUT

        ;TRAPOUT ROUTINE

012422  PRTP:   CMP     (6)+,(6)+       ;CLEAR STACK
012424  PRTP1:  CMP     #172136,R2      ;DONE YET?
012430          BEQ     NOPAR           ;YES NO PAR REG
012432          ADD     #2,R2           ;NO TRY AGAIN
012436          JMP     TSTAGN          ;RETRY

012442  NOPAR:  MOV     #6,@#4
012450          CLR     @#6
012454          MOV     @R1,@R1         ;WRITE GOOD PARITY
                ;*****************************************************************************
                ;TEST 70                 TEST WRITE CHECK ERROR
                ;*****************************************************************************
012456  TST70:  SCOPE
```

```
                        ;WRITE A WORD OF 0 AND FLOAT A 1 TRSOUGH IT TO CAUSE WCE
                        ;SET BIT14 IN ONCEE AND WRITE A WD OF -1 AND FLOAT 0
                        ;TO CAUSE WCE

012460  WCETST: CLRDK                           ;CLEAR ALL RS REG
012462         CLR     OUTBUF                  ;WRITE A WD OF 0
012466  WCETT:  MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
012474         MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
012502         MOV     #61,@RSCS1              ;GO WRITE
012510  3$:    TSTB    @RSCS1                  ;DONE YET?
012514         BPL     3$                      ;NO WAIT
012516         BIT     #BIT14,ONCEE            ;WRITE A 1 OR 0?
012524         BEQ     2$                      ;WRITE A 0
012526         MOV     #-1,OUTBUF              ;WRITE A 1
012534         CLC                             ;CLEAR CARRY
012536  6$:    ROL     OUTBUF                  ;FLOAT A 0 THROUGH BAD WD
012542         BCC     WCEDON                  ;DONE GET OUT
012544         BR      5$                      ;CHECK WCE
012546  2$:    CLR     OUTBUF                  ;WRITE A 0
012552         SEC                             ;SET CARRY
012554  1$:    ROL     OUTBUF                  ;FLOAT A 1
012560         BCS     WCEDNE                  ;GET OUT WHEN DONE
012562  5$:    MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
012570         MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
012576         CLR     @RSDA
012602         MOV     #51,@RSCS1              ;GO WRITE CHECK
012610  4$:    TSTB    @RSCS1                  ;READY YET?
012614         BPL     4$                      ;NO WAIT
012616         MOV     @RSCS2,BAD              ;GET CS2
012622         MOV     UNNUM,GOOD              ;SET UNIT #
012626         BIS     #40300,GOOD             ;SET BITS
012632         CMP     GOOD,BAD                ;IS CS2 CORRECT?
012634         BEQ     7$                      ;YES
012636         HLT                             ;BAD=CS2 GOOD=CORRECT ANS
012640         MOV     OUTBUF,BAD              ;GET BAD WD THAT SHOULD CAUSE WCE
012644         CLR     GOOD                    ;GET GOOD WD IF WRITING 0
012646         BIT     #BIT14,ONCEE            ;ARE WE WRITING 1 OR 0
012654         BEQ     8$                      ;0
012656         MOV     #-1,GOOD                ;GET GOOD WD FOR 1
012662  8$:    HLT                             ;GOOD = CORRECT WD WRITTEN
                                               ;BAD = INCORRECT WD THAT WCE DID NOT CATCH
```

```
012664  7$:     CMP     #144250,@RSCS1  ;DID TRE SET?
012672          BEQ     .+4             ;YES
012674          HLT     ;CS1!ER!DS      ;TRE SHOULD SET IF WCE SETS
012676          MOV     @RSBA,BAD       ;FETCH CURRENT ADDRESS
012702          MOV     @#OBUFSV,GOOD   ;WHAT RSBA SHOULD EQUAL
012706          ADD     #2,GOOD         ;UPDATE IT
012712          CMP     BAD,GOOD        ;IS RSBA CORRECT
012714          BEQ     .+4             ;YES EXECUTE CONTINUE
012716          HLT                     ;RSBA FAILED TO INCREMENT
012720          CLRDK                   ;CLEAR ALL RS REG
012722          MOV     UNNUM,GOOD      ;PUT DRIVE IN GOOD
012726          BIS     #100,GOOD       ;SET IR BIT
012732          MOV     @RSCS2,BAD      ;GET CS2
012736          CMP     GOOD,BAD        ;IS CS2 CORRECT
012740          BEQ     .+4             ;YES
012742          HLT                     ;BAD =CS2 GOOD IS CORRECT ANS
012744          CMP     #4200,@RSCS1    ;DID TRE CLEAR?
012752          BEQ     .+4             ;YES
012754          HLT     ;CS1            ;TRE DID NOT CLEAR WITH CLEAR
012756          BIT     #BIT14,ONCEE    ;FLOATION A 1 OR 0?
012764          BEQ     1$              ;FLOAT 1
012766          BR      6$              ;FLOAT 0
012770  WCEDNE: BIS     #BIT14,ONCEE    ;SET BIT14
012776          CLRDK
013000          MOV     #-1,OUTBUFF
013006          JMP     WCETT           ;NOW WRITE -1 IN OUTBUF
013012  WCEDON: BIC     #BIT14,ONCEE    ;CLEAR TEST FLAG
```

```
                ;*****************************************************************************
                ;TEST 71                 TEST WRITE CHECK ERROR ON -B- PORT
                ;*****************************************************************************
013020  TST71:  SCOPE

                ;WRITE A WORD OF 0 AND FLOAT A 1 TRSOUGH IT TO CAUSE WCE
                ;SET BIT14 IN ONCEE AND WRITE A WD OF -1 AND FLOAT 0
                ;TO CAUSE WCE

013022  WCETSB: BIT     #BIT13,ONCEE    ;-B- PORT?
013030          BEQ     1$              ;YES
013032          JMP     WCEDOS          ;NO GET OUT
013036  1$:     MOV     BPORTT,OBUFSV   ;GET -B- PORT BUFFER
013044          CLRDK                   ;CLEAR ALL RS REG
013046          CLR     @BPORTT         ;WRITE A WD OF 0
013052  WCETB:  MOV     @#OBUFSV,@RSBA  ;SET UP CURRENT ADDRESS
013060          MOV     #-1,@RSWC       ;SET WORD COUNT TO -1
013066          MOV     #2061,@RSCS1    ;GO WRITE
013074  3$:     TSTB    @RSCS1          ;DONE YET?
013100          BPL     3$              ;NO WAIT
013102          BIT     #BIT14,ONCEE    ;WRITE A 1 OR 0?
013110          BEQ     2$              ;WRITE A 0
013112          MOV     #-1,@BPORTT     ;WRITE A 1
013120          CLC                     ;CLEAR CARRY
013122  6$:     ROL     OUTBUF          ;FLOAT A 0 THROUGH BAD WD
013126          BCC     WCEDOS          ;DONE GET OUT
013130          BR      5$              ;CHECK WCE
013132  2$:     CLR     @BPORTT         ;WRITE A 0
013136          SEC                     ;SET CARRY
013140  1$:     ROL     @BPORTT         ;FLOAT A 1
013144          BCS     WCEDNB          ;GET OUT WHEN DONE
013146  5$:     MOV     @#OBUFSV,@RSBA  ;SET UP CURRENT ADDRESS
013154          MOV     #-1,@RSWC       ;SET WORD COUNT TO -1
013162          CLR     @RSDA
013166          MOV     #2051,@RSCS1    ;GO WRITE CHECK
013174  4$:     TSTB    @RSCS1          ;READY YET?
013200          BPL     4$              ;NO WAIT
013202          MOV     @RSCS2,BAD      ;GET CS2
013206          MOV     UNNUM,GOOD      ;SET UNIT #
013212          BIS     #40300,GOOD     ;SET BITS
013216          CMP     GOOD,BAD        ;IS CS2 CORRECT?
013220          BEQ     7$              ;YES
013222          HLT                     ;CS2=BAD GOOD=CORRECT ANS
013224          MOV     @BPORTT,BAD     ;GET BAD WD THAT SHOULD CAUSE WCE
013230          CLR     GOOD            ;GET GOOD WD IF WRITING 0
013232          BIT     #BIT14,ONCEE    ;ARE WE WRITING 1 OR 0
013240          BEQ     8$              ;0
013242          MOV     #-1,GOOD        ;GET GOOD WD FOR 1
013246  8$:     HLT                     ;GOOD = CORRECT WD WRITTEN
                                        ;BAD = INCORRECT WD THAT WCE DID NOT CATCH
```

```
013250  7$:     CMP     #146250,@RSCS1  ;DID TRE SET?
013256          BEQ     .+4             ;YES
013260          HLT     !CS1!ER!DS      ;TRE SHOULD SET IF WCE SETS
013262          MOV     @RSBA,BAD       ;FETCH CURRENT ADDRESS
013266          MOV     @#OBUFSV,GOOD   ;WHAT RSBA SHOULD EQUAL
013272          ADD     #2,GOOD         ;UPDATE IT
013276          CMP     BAD,GOOD        ;IS RSBA CORRECT
013300          BEQ     .+4             ;YES EXECUTE CONTINUE
013302          HLT                     ;RSBA FAILED TO INCREMENT
013304          CLRDK                   ;CLEAR ALL RS REG
013306          MOV     UNNUM,GOOD      ;PUT DRIVE IN GOOD
013312          BIS     #100,GOOD       ;SET IR BIT
013316          MOV     @RSCS2,BAD      ;GET CS2
013322          CMP     GOOD,BAD        ;IS CS2 CORRECT
013324          BEQ     .+4             ;YES
013326          HLT                     ;BAD =CS2 GOOD IS CORRECT ANS
013330          CMP     #4200,@RSCS1    ;DID TRE CLEAR?
013336          BEQ     .+4             ;YES
013340          HLT     !CS1            ;TRE DID NOT CLEAR WITH CLEAR
013342          BIT     #BIT14,ONCEE    ;FLOATION A 1 OR 0?
013350          BEQ     1$              ;FLOAT 1
013352          BR      6$              ;FLOAT 0
013354  WCEDNB: BIS     #BIT14,ONCEE    ;SET BIT14
013362          CLRDK
013364          MOV     #-1,@BPORTT
013372          JMP     WCETB           ;NOW WRITE -1 IN OUTBUF
013376  WCEDOS: MOV     #OUTBUF,OBUFSV  ;RESTORE OBUFSV
013404          BIC     #BIT14,ONCEE    ;CLEAR TEST FLAG
```

```
                ;**********************************************************************
                ;TEST 72                 TEST PROGRAM ERROR BIT IN RSCS2
                ;**********************************************************************
013412  TST72:  SCOPE

013414  PGETST: CLRDK
013416          MOV     #177777,OUTBUF  ;DATA TO BE X-FERED
013424          MOV     #OBUFSV,@RSBA   ;SET UP CURRENT ADDRESS
013432          MOV     #177000,@RSWC   ;SET WORD COUNT
013440          MOV     #61,@RSCS1      ;GO WRITE
013446  2$:     TSTB    @RSCS1          ;IS RDY CLEARED YET?
013452          BMI     2$              ;NO WAIT
013454          MOV     #71,@RSCS1      ;GO READ
013462          JSR     PC,WAITRY       ;WAIT FOR READY
013466          HLT     !CS1            ;RDY NEVER CAME UP
013470          CMP     #144260,@RSCS1  ;IS CS1 CORRECT?
013476          BEQ     .+4             ;YES
013500          HLT     !CS1            ;TRE SHOULD SET BY SETTING PGE
013502          TST     @RSAS           ;AS SHOULD = 0
013506          BEQ     .+4             ;YES
013510          HLT     !AS             ;RSAS SHOULD = 0
013512          MOV     UNNUM,GOOD      ;GET UNIT #
013516          BIS     #2300,GOOD      ;SET PGE, IR, AND OR
013524          MOV     @RSCS2,BAD      ;GET CS2
013530          CMP     GOOD,BAD        ;IS IT CORRECT?
013534          BEQ     .+4             ;YES
013536          HLT                     ;BAD = CS2
013540          TSI     @RSWC           ;SHOULD NOT BE 0
013542          BNE     .+4             ;BECAUSE PGE SHOULD ABORT
013544          HLT     !WC!CS1         ;CURRENT OPERATION
013550          TST     @RSER           ;DID ANY ERRORS SET?
013554          BEQ     .+4             ;NO
013556          HLT     !DS             ;RMR SHOULD BE SET
013560          BIS     #TRE,@RSCS1     ;CLEAR ERRORS
013566          BIC     #PGE,GOOD       ;CLEAR PGE ERROR
013572          MOV     @RSCS2,BAD      ;GET CS2
013576          CMP     GOOD,BAD        ;IS CS2 CORRECT?
013600          BEQ     .+4             ;YES
013602          HLT     !CS2            ;PGE DID NOT CLEAR BY CLEARING TRE BAD = CS2
013606          CMP     #4260,@RSCS1    ;DID SC CLEAR
013614          BEQ     .+4             ;YES
013616          HLT     !DS             ;DID NOT CLEAR BY CLEARING TRE
```

```
                ;*****************************************************************************
                ;TEST 73                 TEST RMR IN RSER REGISTER TRYING TO WRITE INTO RSDA
                ;*****************************************************************************
013612  TST73:  SCOPE

013614  RMRT1:  CLRDK                           ;CLEAR ALL RS REG
013616          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
013624          MOV     #177700,@RSWC           ;SET WORD COUNT
013632          MOV     #172060,R3              ;GET RSLA REG
013636  1$:     MOV     @R3,R4                  ;WAIT FOR
013640          BIC     #17,R4                  ;THE MIDDLE
013644          CMP     #20,R4                  ;OF SECTOR 0
013650          BNE     1$                      ;BEFORE DOING A SEARCH
013652          MOV     #31,@RSCS1              ;SEARCH
013660          MOV     #7777,@RSDA             ;CAUSE ERROR
013666          JSR     PC,WAITRY               ;WAIT FOR READY
013672          HLT     !CS1                    ;RDY NEVER CAME UP
013674          CMP     #4,@RSER                ;DID RMR SET?
013702          BEQ     .+4                     ;YES
013704          HLT     !ER                     ;ER SHOULD = 4
013706          CMP     #7777,@RSDA             ;DID DA GET MODIFIED?
013714          BNE     .+4                     ;NO
013716          HLT     !DA
013720          CMP     #150600,@RSDS           ;DID ERR SET?
013726          BEQ     .+4                     ;YES
013730          HLT     !DS!ER                  ;ER DID NOT SET BECAUSE OF RMR
013732          CMP     #104230,@RSCS1          ;IS CS1 CORRECT?
013740          BEQ     .+4                     ;YES
013742          HLT     !DS                     ;CS1 SHOULD = 144260
013744          CLRDK                           ;CLEAR ALL RS REG
013746          TST     @RSER                   ;DID RMR CLEAR?
013752          BEQ     .+4                     ;YES
013754          HLT     !ER                     ;RMR DID NOT CLEAR WITH A CLEAR
013756          CMP     #4200,@RSCS1            ;IS CS1 CORRECT?
013764          BEQ     .+4                     ;YES
013766          HLT     !DS                     ;NO

                ;*****************************************************************************
                ;TEST 74                 TEST RMR IN RSER REGISTER TRYING TO WRITE INTO RSER
                ;*****************************************************************************
013770  TST74:  SCOPE

013772  RMRT2:  CLRDK                           ;CLEAR ALL RS REG
013774          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
014002          MOV     #177700,@RSWC           ;SET WORD COUNT
014010          MOV     #61,@RSCS1              ;GO WRITE
014016  2$:     TSTB    @RSCS1                  ;IS RDY SET?
014022          BMI     2$                      ;YES WAIT FOR IT TO CLEAR
014024          MOV     #177773,@RSER           ;CAUSE ERROR
```

```
014032          JSR     PC,WAITRY
014036          HLT     !CS1                    ;RDY NEVER CAME UP
014040          CMP     #4,@RSER                ;DID RMR SET?
014046          BEQ     .+4                     ;YES
014050          HLT     !ER                     ;ER SHOULD = 4
014052          CMP     #150600,@RSDS           ;DID ERR SET?
014060          BEQ     .+4                     ;YES
014062          HLT     !DS!ER                  ;ERR DID NOT SET BECAUSE OF RMR
014064          CMP     #144260,@RSCS1          ;IS CS1 CORRECT?
014072          BEQ     .+4                     ;YES
014074          HLT     !DS                     ;CS1 SHOULD = 144260
014076          CLRDK                           ;CLEAR ALL RS REG

        ;*****************************************************************************
        ;TEST 75                 TEST RMR IN RSER REGISTER TRYING TO WRITE INTO RSCS1
        ;*****************************************************************************
014100  TST75:  SCOPE

014102  RMRT3:  CLRDK                           ;CLEAR ALL RS REG
014104          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
014112          MOV     #177700,@RSWC           ;SET WORD COUNT
014120          MOV     #61,@RSCS1              ;GO WRITE
014126  2$:     TSTB    @RSCS1                  ;IS RDY SET?
014132          BMI     2$                      ;YES WAIT FOR IT TO CLEAR
014134          MOV     #30,@RSCS1              ;CAUSE ERROR
014142          JSR     PC,WAITRY               ;WAIT FOR READY
014146          HLT     !CS1                    ;RDY NEVER CAME UP
014150          CMP     #4,@RSER                ;DID RMR SET?
014156          BEQ     .+4                     ;YES
014160          HLT     !ER                     ;ER SHOULD = 4
014162          CMP     #150600,@RSDS           ;DID ERR SET?
014170          BEQ     .+4                     ;YES
014172          HLT     !DS!ER                  ;ERID NOT SET BECAUSE OF RMR
014174          CMP     #144260,@RSCS1          ;IS CS1 CORRECT?
014202          BEQ     .+4                     ;YES
014204          HLT     !DS                     ;CS1 SHOULD = 144260
014206          CLRDK                           ;CLEAR ALL RS REG
```

```
                ;*****************************************************************************
                ;TEST 76                 TEST THAT RMR DOES NOT SET BY WRITTING INTO RSAS
                ;*****************************************************************************
014210  TST76:  SCOPE

014212  RMRT4:  CLRDK                           ;CLEAR ALL RS REG
014214          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
014222          MOV     #177700,@RSWC           ;SET WORD COUNT
014230          MOV     #172060,R3              ;GET RSLA REG
014234  1$:     MOV     @R3,R4                  ;WAIT FOR
014236          BIC     #17,R4                  ;THE MIDDLE
014242          CMP     #20,R4                  ;OF SECTOR 0
014246          BNE     1$                      ;BEFORE DOING A SEARCH
014250          MOV     #31,@RSCS1              ;SEARCH
014256          MOV     #0,@RSAS                ;TRY TO CAUSE ERROR
014264          CLR     WORK                    ;CLEAR COUNTER
014270  2$:     BIT     #BIT7,@RSDS             ;WAIT FOR DRY
014276          BNE     3$                      ;READY CONT
014300          INC     WORK                    ;COUNT
014304          BNE     2$                      ;RETRY
014306          HLT     !CS1                    ;RDY NEVER CAME UP
014310  3$:     TST     @RSER                   ;DID RMR SET?
014314          BEQ     .+4                     ;NO
014316          HLT     !ER                     ;ER SHOULD = 0
014320          CMP     #110600,@RSDS           ;DID ERR SET?
014326          BEQ     .+4                     ;NO
014330          HLT     !DS!ER                  ;DS SHOULD = 110600
014332          CMP     #104230,@RSCS1          ;IS CS1 CORRECT?
014340          BEQ     .+4                     ;YES
014342          HLT     !DS                     ;CS1 SHOULD = 144260
014344          CLRDK                           ;CLEAR ALL RS REG
014346          CMP     #4200,@RSCS1            ;IS CS1 CORRECT?
014354          BEQ     .+4                     ;YES
014356          HLT     !DS                     ;NO
```

```
                ;*****************************************************************************
                ;TEST 77                 TEST DCK IN RSER
                ;*****************************************************************************
014360  TST77:  SCOPE

                ;DO A WRITE AND THEN A CLEAR FUNCTION THAT SHOULD CAUSE DCK TO SET

014362  DCKTST: CLRDK                           ;CLEAR ALL RS REG
014364          CMP     #4,RS04DT               ;IS THIS A LA DISK?
014372          BNE     7$                      ;NO
014374          MOV     #177640,WORK2           ;GET WC FOR LA DISK
014402          BR      1$                      ;CONTINUE
014404  7$:     MOV     #177500,WORK2           ;GET WC FOR RS04
014412          TST     RS04DT                  ;IS THIS A RS04?
014416          BNE     1$                      ;YES
014420          MOV     #177600,WORK2           ;NO
014426  1$:     MOV     WORK2,@RSWC             ;LOAD WC
014434          MOV     #-1,OUTBUF              ;WRITE -1
014442          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
014450  4$:     BIS     #10,@RSCS2              ;SET BAI BIT
014456          MOV     #61,@RSCS1              ;GO WRITE
014464  5$:     TSTB    @RSCS1                  ;IS RDY SET?
014470          BPL     5$                      ;WAIT FOR WRITE TO FINISH
014472  2$:     CLR     @RSDA                   ;SET DSK ADDRESS TO 0
014476          CLR     OUTBUF                  ;WRITE 0
014502          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
014510          MOV     #-1,@RSWC               ;LOAD WC
014516          MOV     #172060,R2              ;PUT RSLA ADDR INTO R2
014522  3$:     MOV     (R2),R3                 ;GET LA AND WAIT FOR
014524          BIC     #77,R3                  ;SECTOR 40
014530          CMP     #4000,R3                ;BEFORE
014534          BNE     3$                      ;WRITING
014536          MOV     #61,@RSCS1              ;GO WRITE
014544  6$:     MOV     (R2),R3                 ;GET RSLA AND WAIT FOR
014546          BIC     #17,R3                  ;MIDDLE OF SECTOR
014552          CMP     #20,R3                  ;0 BEFORE EXECUTING
014556          BNE     6$                      ;A CLEAR FUNCTION
014560          MOV     #40,@RSCS2              ;CLEAR ALL REG. DO IT THIS WAY
014566          MOV     UNNUM,@RSCS2            ;DO NOT USE TRAP
```

```
014574  INCW:   TSTB    @RSCS1          ;IS BUSY CLEARED
014600          BMI     6$              ;FLAG CLEARED
014602          HLT     !CS1            ;RDY NEVER CAME UP
014604  6$:     MOV     @#OBUFSV,@RSBA  ;SET UP CURRENT ADDRESS
014612          MOV     WORK2,@RSWC     ;LOAD WC
014620          MOV     #71,@RSCS1      ;GO READ
014626  5$:     TSTB    @RSCS1          ;IS RDY SET?
014632          BPL     5$              ;WAIT FOR READ TO FINISH
014634          CMP     #100000,@RSER   ;DID DCK SET?
014642          BEQ     .+4             ;YES
014644          HLT     !ER             ;DCK DID NOT SET
014646          CMP     #150600,@RSDS   ;DID ERR SET?
014654          BEQ     .+4             ;YES
014656          HLT     !DS             ;ER DID NOT SET BY DCK
014660          CMP     #144270,@RSCS1  ;IS CS1 CORRECT?
014666          BEQ     .+4             ;YES
014670          HLT     !DS!DA
014672          MOV     @RSCS2,BAD      ;GET CS2
014676          MOV     UNNUM,GOOD      ;GET UNIT #
014702          BIS     #100,GOOD       ;SET IR
014706          CMP     GOOD,BAD        ;IS CS2 CORRECT?
014710          BEQ     .+4             ;YES
014712          HLT
014714          MOV     #177700,GOOD    ;NO
014720  1$:     MOV     @RSWC,BAD       ;DID TRANSFER STOP AT END OF SECTOR?
014724          CMP     GOOD,BAD
014726          BEQ     .+4             ;YES
014730          HLT                     ;NO
014732          MOV     #OUTBUF,GOOD    ;GET BA
014736          CMP     #4,RS04DT       ;LA DISK?
014744          BNE     7$              ;NO
014746          ADD     #100,GOOD       ;YES
014752          BR      3$              ;CONTINUE
014754  7$:     TST     RS04DT          ;RS04?
014760          BNE     2$              ;YES
014762          ADD     #200,GOOD       ;RS03
014766          BR      3$
014770  2$:     ADD     #400,GOOD       ;GET CORRECT ANS FOR BA
014774  3$:     MOV     @RSBA,BAD       ;GET BA
015000          CMP     BAD,GOOD        ;IS BA CORRECT?
015002          BEQ     .+4             ;YES
015004          HLT                     ;NO
015006          CLRDK                   ;CLEAR ALL RS REG
015010          TST     @RSER           ;DID DCK CLEAR?
015014          BEQ     .+4             ;YES
015016          HLT     !ER             ;DCK DID NOT CLEAR WITH CLEAR
015020          MOV     #177500,@RSWC   ;CLEAR DCK ON
015026          MOV     @#OBUFSV,@RSBA  ;DRIVE BY WRITING
015034          MOV     #61,@RSCS1      ;GOOD DATA
015042  4$:     TSTB    @RSCS1          ;ON DRIVE
015046          BPL     4$
```

```
                ;TEST THE ABILITY OF THE DISK CONTROL TO
                ;INCREMENT THE TRACK REGISTER.

                ;A ONE WORD WRITE WILL BE EXECUTED
                ;RSDA=7777 RSWC = -1
                ;AT THE COMPLETION OF THE WRITE RSDA = 10000
                ;*************************************************************************
                ;TEST 100                TEST DISK ADDRESS REGISTER
                ;*************************************************************************
015050  TST100: SCOPE

015052  DKADR:  CLRDK                           ;CLEAR ALL RS REG
015054          MOV     #177777,@RSWC           ;SET WORD COUNT TO -1
015062          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
015070          MOV     #7777,@RSDA             ;SET RSDA TO ALL ONES
015076          MOV     #61,@RSCS1              ;GO WRITE ONE WORD
015104          JSR     PC,WAITRY               ;WAIT FOR READY
015110          HLT     !C$1                    ;RDY DID NOT COME UP
015112  5$:     CMP     @RSDA,#10000            ;DOES RSDA=0
015120          BEQ     .+4                     ;RSDA OK
015122          HLT     !DA                     ;DA DID NOT INCREMENT

                ;*************************************************************************
                ;TEST 101                TEST IAE ERROR
                ;*************************************************************************
015124  TST101: SCOPE

                ;IAE ERROR SHOULD SET ERR,ATA AND SC BITS

015126  IAERR:  CLRDK                           ;CLEAR ALL RS REG
015130          MOV     #177777,@RSWC           ;SET WC TO -1
015136          MOV     @#OBUFSV,@RSBA          ;SET UP BUS ADDRESS
015144          MOV     #17777,@RSDA            ;SET DA TO RECEIVE ERROR
015152          MOV     #61,@RSCS1              ;GO WRITE ONE WD
015160  7$:     TSTB    @RSCS1                  ;TEST FOR ERR OR RDY
015164          BMI     .+4                     ;OK CONT.
015166          BR      7$                      ;WAIT
015170          CMP     #2000,@RSER             ;DID IAE SET?
015176          BEQ     .+4                     ;YES
015200          HLT     !ER                     ;IAE SHOULD BE SET
015202          CMP     #150600,@RSDS           ;DID ERR SET?
015210          BEQ     .+4                     ;YES
015212          HLT     !DS!AS                  ;ERR SHOULD BE SET
015214          CMP     #144260,@RSCS1          ;DID SC SET?
015222          BEQ     .+4                     ;YES
015224          HLT     !CS1                    ;SC SHOULD BE SET
015226          CLRDK                           ;CLEAR ALL RS REG
015230          TST     @RSER                   ;CLR ERRORS?
015234          BEQ     .+4                     ;YES
015236          HLT     !ER                     ;ERR DID NOT CLR WITH 40 IN CS2
```

```
                ;IN THIS ROUTINE THE PROGRAM WILL GENERATE A
                ;NON-EXISTENT DISK ERROR

                ;*************************************************************************
                ;TEST 102                TEST FOR NON=EXISTENT DISK ERROR
                ;*************************************************************************
015240  TST102: SCOPE

015242  NEDTST: CLRDK                           ;CLEAR ALL RS REG
015244          MOV     #401,WORK               ;SET UP FOR N.E.D. NUMBER
015252          CLR     GOOD                    ;LOOK FOR NON EXISTENT DRIVES
015254  1$:     BIT     WORK,UNITSV             ;ON THE SYSTEM
015262          BEQ     3$                      ;FOUND NON EXISTENT DRIVE
015264          INC     GOOD                    ;CONTAINS UNIT #
015266          ROL     WORK                    ;KEEP LOOKING
015272          BCS     NEDDON                  ;COULD NOT FIND ANY NON EXISTENT DRIVES
015274          BR      1$                      ;LOOK FOR NED
015276  3$:     MOV     GOOD,@RSCS2             ;LOAD NED IN CS2
015302          CLR     @RSDA                   ;WRITE DRIVE REG
015306          TST     @RSER                   ;DID ANY BITS SET IN RSER?
015312          BEQ     .+4                     ;NO
015314          HLT     !DS                     ;WHY DID RSER CHANGE?
015316          MOV     @RSCS2,BAD              ;GET CS2
015322          BIS     #10100,GOOD             ;SET NED AND IR
015326          CMP     GOOD,BAD                ;IS CS2 CORRECT?
015330          BEQ     .+4                     ;YES
015332          HLT                             ;GOOD=CORRECT CS2 BAD=CS2
015334          CMP     #160200,@RSCS1          ;IS CS1 CORRECT?
015342          BEQ     .+4                     ;YES
015344          HLT     !CS2                    ;TRE SHOULD SET BY NED ERROR
015346          TST     @RSAS                   ;DID ANY BITS SET?
015352          BEQ     .+4                     ;NO
015354          HLT     !AS                     ;WHY DID AT BITS SET?
015356          MOVB    #100,@RSCS1B            ;CLEAR TRE
015364          BIT     #NED,@RSCS2             ;DID NED CLEAR
015372          BEQ     .+4                     ;YES
015374          HLT     !CS2                    ;NED DID NOT CLEAR
015376          MOV     @RSDA,WORK              ;READ DRIVE REG
015404          BIT     #NED,@RSCS2             ;DID NED SET?
015412          BNE     .+4
015414          HLT     !DS                     ;NED DID NOT SET
015416          BR      NNDD                    ;GET OUT
015420  NEDDON: BIT     #BIT12,ONCEE            ;DWAS THIS TYPED BEFORE?
015426          BNE     NNDD                    ;YES
015430          TYPE    .+2                     ;.ASCIZ <15><12>"COULD NOT FIND A NON-EXISTENT DRIVE"
015502  NNDD:   BIS     #BIT12,ONCEE            ;SET TYPED FLAG
```

```
                        ;*****************************************************************************
                        ;TEST 103                TEST THAT DAO IN RSER AND LBT IN RSDS DO SET
                        ;*****************************************************************************
015510                  TST103: SCOPE

015512                  DAOTST: CLRDK                           ;CLEAR ALL RS REG
015514                          CMP     #4,RS04DT               ;RS03LA?
015522                          BNE     3$                      ;NO
015524                          MOV     #-41,@RSWC              ;LOAD WORD COUNT
015532                          BR      1$                      ;CONT
015534                  3$:     MOV     #-201,@RSWC             ;LOAD WC FOR RS04
015542                          TST     RS04DT                  ;IS THIS A RS04?
015546                          BNE     1$                      ;YES
015550                          MOV     #-101,@RSWC             ;NO
015556                  1$:     MOV     #7777,@RSDA             ;SET RSDA=TO ALL ONES
015564                  2$:     MOV     @#OBUFSV,@RSBA          ;CURRENT ADDRESS=OUTBUF
015572                          MOV     #61,@RSCS1              ;WRITE
015600                          JSR     PC,@WAITRY              ;WAIT FOR READY
015604                          HLT     !CS1                    ;RDY DID NOT SET
015606                          CMP     #1000,@RSER             ;DID DAO SET?
015614                          BEQ     .+4                     ;YES
015616                          HLT     !ER                     ;DAO DID NOT SET
015620                          CMP     #152600,@RSDS           ;DID LBT SET?
015626                          BEQ     .+4                     ;YES
015630                          HLT     !DS                     ;LBT DID NOT SET
015632                          TST     @RSCS1                  ;IS ERROR FLAG SET
015636                          BMI     .+4                     ;ERROR IS SET
015640                          HLT     !CS1                    ;SC DID NOT SET
015642                          CLRDK                           ;CLEAR ALL RS REG
015644                          CMP     #10600,@RSDS            ;DID ATA +LBT CLEAR
015652                          BEQ     .+4                     ;YES
015654                          HLT     !DS                     ;ATA DID NOT CLEAR BY CLR BIT
015656                          TST     @RSER                   ;DID DAO CLEAR?
015662                          BEQ     .+4                     ;YES
015664                          HLT     !ER                     ;DAO DID NOT CLEAR WITH CLEAR
```

```
                ;*****************************************************************************
                ;TEST 104                TEST THAT LBT DOES SET AND DAO DOES NOT
                ;*****************************************************************************
015666  TST104: SCOPE

015670  DAOTT:  CLRDK                           ;CLEAR ALL RS REG
015672          CMP     #4,RS04DT               ;RS03LA?
015700          BNE     3$                      ;NO
015702          MOV     #-37,@RSWC              ;LOAD WORD COUNT
015710          BR      1$                      ;CONT
015712  3$:     MOV     #-177,@RSWC             ;LOAD WC FOR RS04
015720          TST     RS04DT                  ;IS THIS A RS04?
015724          BNE     1$                      ;YES
015726          MOV     #-77,@RSWC              ;NO
015734  1$:     MOV     #7777,@RSDA             ;SET RSDA=TO ALL ONES
015742  2$:     MOV     @#OBUFSV,@RSBA          ;CURRENT ADDRESS=OUTBUF
015750          MOV     #61,@RSCS1              ;WRITE
015756          JSR     PC,WAITRY               ;WAIT FOR READY
015762          HLT     !CS1                    ;RDY DID NOT SET
015764          TST     @RSER                   ;ANY ERRORS?
015770          BEQ     .+4                     ;NO
015772          HLT     !ER                     ;YES
015774          CMP     #12600,@RSDS            ;DID LBT SET?
016002          BEQ     .+4                     ;YES
016004          HLT     !DS                     ;LBT DID NOT SET
016006          TST     @RSCS1                  ;IS ERROR FLAG SET
016012          BPL     .+4                     ;NO
016014          HLT     !CS1                    ;ERROR
016016          CLRDK                           ;CLEAR ALL RS REG
016020          CMP     #10600,@RSDS            ;DID LBT CLEAR
016026          BEQ     .+4                     ;YES
016030          HLT     !DS                     ;ATA DID NOT CLEAR BY CLR BIT
```

```
                ;*****************************************************************************
                ;TEST 105                EXECUTE FUNCTION WITH ERROR BITS SET
                ;*****************************************************************************
016032  TST105: SCOPE

016034  ERTST:  CLRDK                           ;CLEAR ALL RS REG
016036          MOV     #177017,@RSER           ;LOAD ER
016044          MOV     @RSAS,BAD               ;GET AS REG
016050          MOV     UNCMP,GOOD              ;GET UNIT ATA BIT
016054          BIC     #177400,GOOD            ;CLEAR JUNK
016060          CMP     GOOD,BAD                ;IS AS REG CORRECT?
016062          BEQ     .+4                     ;YES
016064          HLT     !AS                     ;AS BIT SHOULD BE SET
016066          CMP     #104200,@RSCS1          ;DID ERRS SET IN CS1?
016074          BEQ     .+4                     ;YES
016076          HLT     !DS                     ;CS1 SHOULD =104200
016100          MOV     UNCMP,@RSAS             ;CLEAR ATA BIT
016106          TST     @RSAS                   ;DID IT CLEAR?
016112          BEQ     .+4                     ;YES
016114          HLT     !AS                     ;COULD NOT CLEAR AS BIT
                                                ;BY LOADING A 1 INTO IT
016116          CMP     #4200,@RSCS1            ;DID SC CLEAR BY
016124          BEQ     .+4                     ;CLEARING ATA
016126          HLT     !ER                     ;NO
016130          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
016136          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
016144          MOV     #-1,@RSWC               ;LOAD WC WITH -1
016152          MOV     #71,@RSCS1              ;DO READ FUNCTION
016160          BIT     #1,@RSCS1               ;DID GO BIT CLEAR
016166          BEQ     .+4                     ;YES
016170          HLT     !CS1                    ;GO BIT SHOULD BE CLEARED
016172  1$:     TSTB    @RSCS1                  ;WAIT FOR READY
016176          BPL     1$                      ;WAIT
016200          CMP     #144270,@RSCS1          ;DID ERRS CLEAR BY SETTING GO BIT?
016206          BEQ     .+4                     ;YES
016210          HLT     !ER                     ;NO
```

```
016212          MOV     @RSCS2,BAD      ;GET CS2
016216          MOV     #1100,GOOD      ;GET CORRECT ANS
016222          BIS     UNNUM,GOOD      ;GET UNIT #
016226          CMP     GOOD,BAD        ;IS CS2 CORRECT?
016230          BEQ     .+4             ;YES
016232          HLT                     ;GOOD = WHAT CS2 SHOULD =
016234          CMP     #150600,@RSDS   ;DID ERR BITS SET?
016242          BEQ     .+4             ;NO
016244          HLT     !DS             ;ERR BIT SHOULD BE 1
016246          CMP     #-1,@RSWC       ;DID WC MOVE?
016254          BEQ     .+4             ;NO
016256          HLT     !WC             ;WC SHOULD = 1777777
016260          TST     @RSDA           ;DID DA MOV
016264          BEQ     .+4             ;NO
016266          HLT     !DA             ;DA SHOULD =0
016270          CMP     @#OBUFSV,@RSBA  ;DID BA MOVE
016276          BEQ     .+4             ;NO
016300          HLT     !BA             ;BA MOVED
016302          BIT     #NCMP,@RSAS     ;AS SHOULD BE SET
016310          BNE     .+4             ;IS IT?
016312          HLT     !AS             ;NO
016314          CMP     #177017,@RSER   ;DID ER CHANGE?
016322          BEQ     .+4             ;NO
016324          HLT     !ER             ;ER SHOULD NOT CHANGE
```

```
                ;*****************************************************************************
                ;TEST 106                PAT AND MCPE TEST
                ;*****************************************************************************
016326  TST106: SCOPE

016330  PATST:  CLRDK                           ;CLEAR ALL RS REG
016332          BIS     #BIT4,@RSCS2            ;SET PAT
016340          TST     @RSMR                   ;READ DRIVE REG
016344          MOV     @RSCS2,BAD              ;GET CS2
016350          MOV     #120,GOOD               ;MDPE SHOULD
016354          BIS     UNNUM,GOOD              ;NOT SET
016360          CMP     GOOD,BAD                ;IS CS2 CORRECT?
016362          BEQ     .+4                     ;YES
016364          HLT                             ;BAD = CS2 GOOD = CORRECT ANS
016366          MOV     #10,@RSMR               ;CAUSE PAR TO SET IN RSER
016374          CMP     #10,@RSER               ;DID PAR SET?
016402          BEQ     .+4                     ;YES
016404          HLT     !AS!DS
016406          MOV     @RSAS,BAD               ;GET AS REG
016412          MOV     UNCMP,GOOD              ;GET UNIT ATA BIT
016416          BIC     #177400,GOOD            ;CLEAR JUNK
016422          CMP     GOOD,BAD                ;IS AS REG CORRECT?
016424          BEQ     .+4                     ;YES
016426          HLT     !AS                     ;AS BIT SHOULD BE SET
016430          CMP     #104200,@RSCS1          ;DID ERRS SET IN CS1?
016436          BEQ     .+4                     ;YES
016440          HLT     !DS                     ;CS1 SHOULD =104200
016442          CLRDK                           ;CLEAR RS REG
016444          CMP     #4200,@RSCS1            ;IS CS1 CORRECT?
016452          BEQ     .+4                     ;CLEARING ATA
016454          HLT     !ER                     ;NO
016456          MOV     @RSCS2,BAD              ;CHECK TO SEE
016462          MOV     UNNUM,GOOD              ;IF PAT CLEARS
016466          BIS     #100,GOOD
016472          CMP     GOOD,BAD
016474          BEQ     .+4
016476          HLT                             ;PAT DID NOT CLEAR
```

```
                ;*****************************************************************************
                ;TEST 107                SET PAT BIT AND LOAD FUNCTION
                ;*****************************************************************************
016500  TST107: SCOPE

016502  SETPAT: CLRDK                           ;CLEAR ALL REG
016504          BIS     #BAI,@RSCS2             ;SET BAI
016512          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
016520          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
016526          MOV     #-1000,@RSWC            ;LOAD WC WITH -1
016534          BIS     #BIT4,@RSCS2            ;SET PAT BIT
016542          MOV     #71,@RSCS1              ;DO READ FUNCTION
016550  1$:     TSTB    @RSCS1                  ;WAIT FOR READY
016554          BPL     1$                      ;WAIT
016556          CMP     #144270,@RSCS1          ;DID CS1 GET LOADED?
016564          BEQ     .+4                     ;NO
016566          HLT     !DS                     ;IT SHOULD NOT
016570          CMP     @#OBUFSV,@RSBA          ;DID BA MOVE?
016576          BEQ     .+4                     ;NO
016600          HLT     !BA                     ;YES
016602          CMP     #-1000,@RSWC            ;DID WC MOVE?
016610          BEQ     .+4                     ;NO
016612          HLT     !WC                     ;YES WHY?

                ;*****************************************************************************
                ;TEST 110                DO FUNCTION THEN SET PAT BIT
                ;*****************************************************************************
016614  TST110: SCOPE
016616  FUNDO:  CLRDK                           ;CLEAR ALL REG
016620          BIS     #BAI,@RSCS2             ;SET BAI
016626          MOV     #177777,OUTBUF          ;DATA TO BE XFERED
016634          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDRESS
016642          MOV     #-1000,@RSWC            ;LOAD WC WITH -1
016650  3$:     MOV     #71,@RSCS1              ;DO A READ
016656          BMI     3$                      ;WAIT FOR BUSY
016660          BIS     #BIT4,@RSCS2            ;SET PAT
016666  2$:     TSTB    @RSCS1                  ;WAIT FOR READY
016672          BPL     2$
016674          CMP     #144270,@RSCS1          ;DID MCPE SET?
016702          BEQ     .+4                     ;NO
016704          HLT     !ER                     ;YES
016706          MOV     @RSCS2,BAD              ;GET CS2
016712          MOV     #730,GOOD               ;GET CORRECT ANS
016716          BIS     UNNUM,GOOD              ;GET UNIT #
016722          CMP     GOOD,BAD                ;IS CS2 CORRECT?
016724          BEQ     .+4                     ;YES
016726          HLT                             ;GOOD = WHAT CS2 SHOULD =
```

```
016730          CMP     #10600,@RSDS    ;DID ERR BITS SET?
016736          BEQ     .+4             ;NO
016740          HLT     !DS             ;ERR BIT SHOULD BE 1
016742          TST     @RSER           ;IS ER CLEAR?
016746          BEQ     .+4             ;YES
016750          HLT     !DS!DA          ;NO ERRORS SHOULD BE SET
016752          CLRDK                   ;CLEAR ALL RS REG
016754          CMP     #4200,@RSCS1    ;IS CS1 CORRECT?
016762          BEQ     .+4             ;YES
016764          HLT     !DS
                ;*************************************************************************
                ;TEST 111                TEST PAR BY SETTING PAT
                ;*************************************************************************
016766  TST111: SCOPE

016770  PATTST: CLRDK                   ;CLEAR ALL RS REG
016772          BIS     #BAI,@RSCS2     ;SET BAI
017000          MOV     #177777,OUTBUF  ;DATA TO BE XFERED
017006          MOV     @#OBUFSV,@RSBA  ;SET UP CURRENT ADDRESS
017014          MOV     #-1000,@RSWC    ;LOAD WC WITH -1
017022          MOV     #61,@RSCS1      ;DO WRITE FUNCTION
017030  1$:     TSTB    @RSCS1          ;WAIT FOR READY
017034          BMI     1$              ;WAIT
017036          BIS     #BIT4,@RSCS2    ;SET PAT
017044  2$:     TSTB    @RSCS1          ;WAIT FOR READY
017050          BPL     2$
017052          CMP     #144260,@RSCS1  ;DID MCPE SET?
017060          BEQ     .+4             ;NO
017062          HLT     !ER             ;YES
017064          MOV     @RSCS2,BAD      ;GET CS2
017070          MOV     #230,GOOD       ;GET CORRECT ANS-- DO NOT CHECK IR - REASON SO CYCLE
017074          BIS     UNNUM,GOOD      ;GET UNIT #
017100          BIC     #BIT6,BAD       ;CLEAR IR BIT FOR CS2 COMPARE
017104          CMP     GOOD,BAD        ;IS CS2 CORRECT?
017106          BEQ     .+4             ;YES
017110          HLT                     ;GOOD = WHAT CS2 SHOULD =
017112          CMP     #150600,@RSDS   ;DID ERR BITS SET?
017120          BEQ     .+4             ;NO
017122          HLT     !DS             ;ERR BIT SHOULD BE 1
017124          CMP     #10,@RSER       ;DID PAR SET?
017132          BEQ     .+4             ;YES
017134          HLT     !DS!DA          ;NO
017136          CLRDK                   ;CLEAR ALL RS REG
017140          CMP     #4200,@RSCS1    ;IS CS1 CORRECT?
017146          BEQ     .+4             ;YES
017150          HLT     !DS
017152          TST     @RSER           ;DID PAR CLEAR?
017156          BEQ     .+4             ;YES
017160          HLT     !DS
```

```
                ;*****************************************************************************
                ;TEST 112                TEST THE ABILITY TO FILL THE LAST SECTOR
                ;*****************************************************************************
017162  TST112: SCOPE

017164  LASTSC: CLRDK                           ;CLEAR ALL RS REG
017166          MOV     #7777,@RSDA             ;SET RSDA=TO ALL ONES
017174          CMP     #4,RS04DT               ;LA DISK?
017202          BNE     2$                      ;NO
017204          MOV     #-40,@RSWC              ;LOAD WORD COUNT
017212          BR      1$                      ;CONTINUE
017214  2$:     MOV     #-100,@RSWC             ;WORD COUNT=-100
017222          TST     RS04DT                  ;IS THIS A RS04?
017226          BEQ     1$                      ;NO
017230          MOV     #-200,@RSWC             ;YES
017236  1$:     MOV     #OBUFSV,@RSBA           ;CURRENT ADDRESS=OUTBUF
017244          MOV     #61,@RSCS1              ;WRITE
017252          JSR     PC,WAITRY               ;WAIT FOR READY
017256          HLT     !CS1                    ;RDY DID NOT SET
017260          TST     @RSER                   ;DID ANY ERROR BITS SET?
017264          BEQ     .+4                     ;NO
017266          HLT     !ER                     ;GOT AN ERROR
017270          CMP     #12600,@RSDS            ;DID LBT SET?
017276          BEQ     .+4                     ;YES
017300          HLT     !DS                     ;LBT DID NOT SET
017302          TST     @RSCS1                  ;IS ERROR FLAG SET
017306          BPL     .+4                     ;ERROR IS SET
017310          HLT     !CS1                    ;SC DID NOT SET
017312          CLRDK                           ;CLEAR ALL RS REG
017314          CMP     #10600,@RSDS            ;DID ATA +LBT CLEAR
017322          BEQ     .+4                     ;YES
017324          HLT     !DS                     ;ATA DID NOT CLEAR BY CLR BIT
```

```
                ;FILL SECTOR WITH ALL ONES.
                ;NOW WRITE 1ST WORD IN SECTOR
                ;TEST REMAINING 63 WORDS FOR 0

                ;*****************************************************************************
                ;TEST 113                TEST FOR ZERO'S IN PARTIAL FILLED SECTOR
                ;*****************************************************************************
017326  TST113: SCOPE
017330  SECT:   CLRDK                           ;CLEAR ALL RS REG
017332          MOV     #-1,OUTBUF              ;PUT -1 INTO OUTBUF
017340          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDR
017346          CMP     #4,RS04DT               ;RS03LA DISK?
017354          BNE     4$                      ;NO
017356          MOV     #-40,@RSWC              ;LOAD WORD COUNT
017364          BR      5$                      ;CONTINUE
017366  4$:     MOV     #-200,@RSWC             ;LOAD WC FOR RS04
017374          TST     RS04DT                  ;RS04?
017400          BNE     5$                      ;YES
017402          MOV     #-100,@RSWC             ;SET WORD COUNT TO -100
017410  5$:     BIS     #BAI,@RSCS2             ;SET BAI BIT
017416          MOV     #61,@RSCS1              ;WRITE
017424  3$:     TSTB    @RSCS1                  ;IS RDY SET?
017430          BPL     3$                      ;NO
017432          CLR     @RSDA                   ;SET DSK ADDRESS TO 0
017436          MOV     #-1,OUTBUF              ;PUT 177777 INTO OUTBUF
017444          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDR
017452          MOV     #-1,@RSWC               ;SET WORD COUNT TO -1
017460          BIS     #10,@RSCS2              ;SET BAI BIT
017466          MOV     #61,@RSCS1              ;WRITE
017474  1$:     TSTB    @RSCS1                  ;IS RDY SET?
017500          BPL     1$                      ;NO
017502          BIC     #10,@RSCS2              ;CLEAR BAI BIT
017510          TST     RS04DT                  ;RS04?
017514          BEQ     7$                      ;NO
017516          MOV     #200,WORK               ;YES
017524          BR      8$                      ;CONT
017526  7$:     MOV     #100,WORK               ;SET UP BUFFER
017534  8$:     MOV     @#OBUFSV,R1             ;GET STARTING ADD OF BUF
017540          MOV     #-1,(R1)+               ;LOAD FIRST WD WITH -1
017544  6$:     CLR     (R1)+                   ;LOAD REST WITH 0
017546          DEC     WORK                    ;DONE YET?
017552          BNE     6$                      ;NO
017554          CLR     @RSDA                   ;SET DSK ADDRESS TO 0
017560          MOV     @#OBUFSV,@RSBA          ;SET UP CURRENT ADDR
017566          CMP     #4,RS04DT               ;RS03LA DISK?
017574          BNE     11$                     ;NO
017576          MOV     #-40,@RSWC              ;LOAD WORD COUNT
017604          BR      10$                     ;CONTINUE
017606  11$:    TST     RS04DT                  ;RS04?
017612          BEQ     9$                      ;NO
017614          MOV     #-200,@RSWC             ;YES
017622          BR      10$                     ;CONT
017624  9$:     MOV     #-100,@RSWC             ;SET WORD COUNT TO -100
017632  10$:    MOV     #51,@RSCS1              ;WRITE CHECK
```

```
017640  2$:     BIT     #200,@RSCS1     ;IS RDY SET?
017646          BEQ     2$              ;NO
017650          MOV     UNNUM,GOOD      ;GET UNIT #
017654          BIS     #100,GOOD       ;SET IR BIT
017660          MOV     @RSCS2,BAD      ;GET CS2
017664          CMP     GOOD,BAD        ;IS CS2 CORRECT?
017666          BEQ     .+4             ;YES
017670          HLT     !ER             ;THERE WAS A WRITE CHECK ERROR

                ;*************************************************************************
                ;TEST 114                IF MEMORY MANAGEMENT IS AVAILABLE CHECK THE EXTENDED MEMORY ADDRESS BITS
                ;*************************************************************************
017672  TST114: SCOPE

017674  EXTTST: CLRDK                   ;CLEAR ALL RS REG.
017676          MOV     TIMES,TIMSV     ;SAVE LOOP #
017704          MOV     #10,TIMES       ;LOOP 10 TIMES
017712          MOV     #EXTTRP,4       ;SETUP TIMEOUT TRAP
017720          MOV     #340,6
017726          TST     @#SR0           ;IF MEMORY MANAGEMENT IS NOT
                                        ;AVAILABLE THE PROGRAM WILL TRAP
                                        ;AND TRANSFER TO END OF THE TEST
017732          MOV     #EXTRP,4
017740          MOV     #7600,@#KIPAR7  ;OPEN I/O REGISTERS
017746          CLR     @#KIPAR0        ;FREE FIRST 4K
017752          MOV     #200,@#KIPAR1   ;ENABLE SECOND 4K
017760          MOV     #2000,@#KIPAR2
017766          MOV     #400*256.-400+UP+RW,@#KIPDR0    ;SET KIPDR0=RW UP 400 BLOCKS
017774          MOV     #400*256.-400+UP+RW,@#KIPDR1    ;SET KIPDR1=RW UP 400 BLOCKS
020002          MOV     #400*256.-400+UP+RW,@#KIPDR2    ;SET KIPDR2=RW UP 400 BLOCKS
020010          MOV     #400*256.-400+UP+RW,@#KIPDR7    ;SET KIPDR7=RW UP 400 BLOCKS
020016          MOV     #1,@#SR0        ;TURN ON MEMORY MANAGEMENT
020024          MOV     #40000,R2       ;R2 EQUALS BASE ADDR
```

```
020030  7$:     MOV     #177777,(R2)    ;INSERT PATTERN INTO 200000
020034          MOV     #-2,@RSWC       ;SETUP WORDCOUNT
020042          MOV     #177777,@RSBA   ;SETUP BUS ADDR
020050          MOV     #61,@RSCS1      ;WRITE TWO WORDS ON DISK.  RSBA
                                        ;STARTS AT 177777 TO FORCE CARRY
                                        ;TO SET A16
020056          TSTB    @RSCS1          ;WAIT FOR READY
020062          BPL     .-4
020064          TST     @RSCS1
020070          BPL     1$
020072          HLT     !ER!DA!DS       ;STATUS ERROR AFTER 2 WORD WRITE
020074          BR      2$              ;USING MEX0
020076  1$:     CMP     #4660,@RSCS1    ;IS CS1 CORRECT
020104          BEQ     3$              ;YES
020106          HLT     !ER             ;CS2 DID NOT COMPARE
020110          BR      2$
020112  3$:     CLR     (R2)            ;CLEAR LOCATION 200000
020114          CLR     @RSDA           ;SETUP DA
020120          MOV     #177777,@RSBA   ;SETUP BA
020126          MOV     #-2,@RSWC       ;SETUP WC
020134          MOV     #71,@RSCS1      ;READ TWO WORDS INTO LOCATIONS
                                        ;177777 AND 200000.
020142          TSTB    @RSCS1          ;WAIT FOR READY
020146          BPL     .-4
020150          TST     @RSCS1          ;ANY ERRORS?
020154          BPL     4$              ;BRANCH IF NO
020156          HLT     !ER             ;ERROR OFTER READING 2 WORDS
020160          BR      2$
020162  4$:     CMP     #4670,@RSCS1    ;IS CS1 CORRECT?
020170          BEQ     5$              ;YES
020172          HLT     !ER             ;CS1 DID NOT COMPARE
020174          BR      2$              ;READ STARTING AT 177777
020176  5$:     CMP     #177777,(R2)    ;WAS DATA READ INTO LOCATION
020202          BEQ     2$              ;200000 CORRECTLY? - BRANCH IF YES
020204          MOV     #177777,GOOD
020210          MOV     (R2),BAD
020212          HLT                     ;DATA COMPARE ERROR AT 200000
020214  2$:     NOP
```

```
020216  EXTT1:  CLRDK                   ;CLEAR ALL REG
020220          MOV     #4000,@#KIPAR2
020226          MOV     #40000,R2       ;R2 EQUALS THE BASE ADDR
020232  7$:     MOV     #177777,(R2)    ;INSERT PATTERN INTO 400000
020236          MOV     #177777,@RSBA   ;SETUP BUS ADDR
020244          MOV     #-2,@RSWC       ;LOAD WC
020252          MOV     #461,@RSCS1     ;SET BIT A16 AND WRITE
020260          TSTB    @RSCS1          ;WAIT FOR READY
020264          BPL     .-4
020266          TST     @RSCS1          ;ANY ERRORS?
020272          BPL     4$              ;BRANCH IF NO
020274          HLT     !ER             ;ERROR AFTER READING 2 WORDS
020276  4$:     CMP     #5260,@RSCS1    ;IS CS1 CORRECT?
020304          BEQ     10$             ;BRANCH IF YES
020306          HLT     !ER             ;NO CS1 DID NOT COMPARE
                                        ;READ STARTING AT 377777
020310  10$:    CLR     (R2)            ;CLEAR LOCATION 400000
                                        ;READ TWO WORDS STARTING AT 377777
020312          MOV     #-2,@RSWC       ;SETUP WC
020320          CLR     @RSDA           ;SETUP DA
020324          MOV     #177777,@RSBA
020332          MOV     #471,@RSCS1     ;CLEAR A 17 SET A16,READ
020340          TSTB    @RSCS1          ;WAIT FOR READY
020344          BPL     .-4
020346          TST     @RSCS1          ;ANY ERRORS?
020352          BPL     11$             ;BRANCH IF NO
020354          HLT     !ER             ;ERROR WHILE READING TWO WORDS
020356          BR      EXTRP
020360  11$:    CMP     #5270,@RSCS1    ;IS CS1 CORRECT?
020366          BEQ     12$             ;BRANCH IF YES
020370          HLT     !ER             ;CS1 DID NOT COMPARE
                                        ;READ STARTING AT 377777
020372  12$:    CMP     #177777,(R2)    ;WAS DATA READ INTO LOCATION 400000
020376          BEQ     EXTRP           ;CORRECTLY? - BRANCH IF YES
020400          MOV     #177777,GOOD
020404          MOV     (R2),BAD
020406          HLT

                                        ;DATA COMPARE ERROR AT 400000 IF
                                        ;RECEIVED=0 - LOCATION WASN'T ACCESSED
020410  EXTRP:  CLR     @#SR0           ;TURN OFF MEMORY MANAGEMENT
020414          BR      EXT1
020416  EXTTRP: NOP                     ;UPDATE TEST NUMBERS
020420  EXT1:   MOV     #500,SP         ;RESTORE STACK
020424  MEMOUT: MOV     #6,4
020432          CLR     6
```

```
                ;*************************************************************************
                ;TEST 115                TEST PROGRAM INTERRUPT BY MOVING 300 INTO RSCS1
                ;*************************************************************************
020436  TST115: SCOPE

020440  QES:    CLRDK                           ;CLEAR ALL DRIVES
020442          MOV     #500,SP                 ;SETUP STACK
020446          MOV     #PGTRAP,@RSVEC          ;SET UP VECTOR
020454          MOV     #340,@RSVCPS            ;SET TRAP PS
020462          MOV     #200,@#PS               ;SET PS AT PRIORITY 4
020470          MOV     #300,@RSCS1             ;THIS SHOULD CAUSE A TRAP
020476          MOV     #500,WORK               ;SETUP LOOP
020504  1$:     DEC     WORK                    ;DEC LOOP SHOULD
020510          BNE     1$                      ;INTERRUPE BEFORE LOOP IS DONE
020512          HLT     !CS1                    ;SHOULD NEVER GET HERE
020514          JMP     QESDON                  ;GET OUT

020520  PGTRAP: CMP     (6)+,(6)+               ;TRAP OK
020522          CMP     #4200,@RSCS1            ;DID IE CLEAR?
020530          BEQ     .+4                     ;YES
020532          HLT     !CS1                    ;IE SHOULD BE CLEARED
020534  QESDON:

                ;*************************************************************************
                ;TEST 116                TEST THAT DISK DOES NOT INTERRUPT WHEN PS IS AT 5
                ;*************************************************************************
020534  TST116: SCOPE

020536  INTR5:  MOV     #500,SP                 ;SETUP STACK
020542          MOV     TIMSV,TIMES             ;RESTORE LOOP COUNTER
020550          CLRDK                           ;CLEAR ALL RS REG
020552          MOV     #INT112,@RSVEC          ;SET UP INTERRUPT VECTOR
020560          MOV     #340,@RSVCPS            ;SET PRIO.
020566          MOV     #240,@#PS               ;LOCK OUT ALL INTERRUPTS ABOVE
020574          MOV     @#PS,BAD                ;GET PS
020600          MOV     #177777,@RSWC           ;SET WORD COUNT TO -1
020606          MOV     @#OBUFSV,@RSBA          ;LOAD CURRENT ADDRESS
020614          MOV     #161,@RSCS1             ;GO WRITE (INTERRUPT ENABLED)
020622          JSR     PC,WAITRY               ;WAIT FOR READY
020626          HLT     !CS1                    ;NO RDY NEVER CAME UP
020630          BR      INTDON                  ;RESTART ROUTINE
        ;PROCESSOR SHOULD NOT TRAP TO INT112

020632  INT112: MOV     #240,GOOD               ;WHAT PS SHOULD HAVE
020636          HLT                             ;GOOD = CORRECT ANS FOR PS
020640  INTDON:                                 ;DONE GET OUT
```

```
                ;*****************************************************************************
                ;TEST 117                TEST THAT DISK DOES INTERRUPT WHEN PS IS AT 4
                ;*****************************************************************************
020640  TST117: SCOPE

020642  INTR4:  MOV     #500,SP         ;SETUP STACK
020646          CLRDK                   ;CLEAR ALL RS REG
020650          MOV     #INT114,@RSVEC  ;SET UP DISK TRAP VECTOR
020656          MOV     #340,@RSVCPS    ;SET PRIO.
020664          MOV     #200,@#PS       ;SET PROCESSOR TO PRIORITY 4
020672          MOV     @#PS,BAD        ;GET PS
020676          MOV     #200,GOOD       ;GET CORRECT PS
020702          MOV     #177777,@RSWC   ;SET WORD COUNT TO -1
020710          MOV     @#OBUFSV,@RSBA  ;LOAD CURRENT ADDRESS
020716          MOV     #161,@RSCS1     ;WRITE (INTERRUPT ENABLE
020724          CLR     WORK
020730          INC     WORK            ;WAIT FOR INTERRUPT TO OCCUR
020734          BNE     .-4
020736          HLT                     ;GOOD=CORRECT PS BAD=WRONG PS
020740          HLT     !ER!DS
020742          BR      DONINT          ;CONT
020744  INT114: CMP     #4260,@RSCS1    ;DID IE CLEAR?
020752          BEQ     .+4             ;YES
020754          HLT     !CS1            ;WHY DID NOT IE CLEAR
020756  DONINT:

                ;*****************************************************************************
                ;TEST 120                TEST INTERRUPT ON ERROR
                ;*****************************************************************************
020756  TST120: SCOPE

020760  ERINT:  MOV     #500,SP         ;SETUP STACK
020764          MOV     #200,@#PS       ;SET PS AT PRI 4
020772          MOV     #ERRINT,@RSVEC  ;SET UPINTERRUPT ADD.
021000          CLRDK                   ;CLEAR ALL RS REG
021002          MOV     #340,@RSVCPS    ;SET PRIO.
021010          MOV     #177777,@RSDA   ;SET RSDA=TO ALL ONES
021016          MOV     #177600,@RSWC   ;WORD COUNT=-200
021024          MOV     @#OBUFSV,@RSBA  ;CURRENT ADDRESS=OUTBUF
021032          MOV     #161,@RSCS1     ;WRITE
021040          JSR     PC,WAITRY       ;WAIT FOR READY
021044  1$:     HLT     !ER!DS          ;Y DIDN'T PGM INTERRUPT IS RDY SET?
021046          BR      FINTST          ;GET OUT
021050  ERRINT: CMP     #144260,@RSCS1  ;IS CS1 RIGHT?
021056          BEQ     .+4             ;YES
021060          HLT     !ER!DS
021062          CMP     (6)+,(6)+       ;CLEAR STACK
021064  FINTST:
```

```
                ;******************************************************************************
                ;TEST 121                DYNAMIC FUNCTION TEST
                ;******************************************************************************
021064          TST121: SCOPE
                ;EXECUTE FUNCTION MODIFY UNIT # AND DO A DRIVE SEARCH
                ;DRIVE SEARCH WILL ONLY BE DONE IF THERE ARE AT LEAST 2 DRIVES
                ;2ND DRIVE MAY NOT BE TESTED YET SO IF THIS TEST FAILS CHECK 2ND DRIVE
                ;BEFORE TRYING TO DEBUG THIS TEST

021066  MODNUM: CLRDK
021070          MOV     TIMES,TIMSV     ;SAVE LOOP COUNT
021076          MOV     #10,TIMES       ;LOOP ONLY 10 TIMES
021104          CLR     WORK1           ;CLEAR WORK LOC.
021110          CLR     R3
021112          CLR     R4
021114          MOV     #DVTAB,R2       ;SETUP TABLE
021120          MOV     #401,WORK       ;SETUP TO TEST FOR MORE DRIVES
021126  7$:     BIT     WORK,UNITSV     ;IS DRIVE ON SYSTEM?
021134          BEQ     6$              ;NO
021136          CMP     R4,UNNUM        ;IS THIS THE SAME DRIVE?
021142          BNE     8$              ;NO
021144  6$:     INC     R4              ;UPDATE 2ND UNIT #
021146          CLC
021150          ROL     WORK            ;CHECK FOR NEXT DRIVE
021154          BCC     7$              ;NOT DONE YET
021156          BIT     #BIT3,WORK1     ;MULTI DRIVE?
021164          BNE     12$             ;YES
021166          MOV     UNNUM,R5        ;LOAD UNIT NO
021172          INC     R5              ;CHANGE IT
021174          BIC     #177770,R5      ;CLEAR JUNK
021200          BR      12$
021202  8$:     BIS     #BIT3,WORK1     ;SET FOUND MULTI DRIVE
021210          MOV     R4,(R2)+        ;LOAD UNT # INTO TABLE
021212          INC     R3              ;COUNT # OF DRIVES
021214          MOV     R3,SAVEE        ;SAVE IT
021220          BR      6$
021222  12$:    MOV     #TSTVEC,@RSVEC  ;SETUP INT. TRAP
021230          MOV     #340,@RSVCPS    ;SETUP PRIO.
021236          CLR     OUTBUF          ;CLR TO READ INTO
021242          MOV     @#OBUFSV,@RSBA  ;SET UP CURRENT ADDRESS
021250          MOV     #-1000,@RSWC    ;SET WORD COUNT
021256  1$:     MOV     #60,@RSDA       ;LOAD DA
021264          MOV     #DVTAB,R2       ;GET TABLE
021270          MOV     #161,@RSCS1     ;GO WRITE
021276          TST     R3              ;MORE THEN 1 DRIVE?
021300          BNE     13$             ;YES
021302          MOV     R5,@RSCS2       ;NO MODIFY UNIT #
021306          BR      14$
```

```
021310  13$:    MOV     (R2)+,@RSCS2    ;LOAD UNIT#
021314          MOV     #131,@RSCS1     ;DO SEARCH
021322          DEC     R3              ;DONE ALL DRIVES YET?
021324          BNE     13$             ;NO
021326  14$:    MOV     #200,@#PS       ;ENABLE INTERRUPTS
021334  WTDV:   WAIT
021336  TSTVEC: MOV     UNNUM,@RSCS2    ;GET 1ST DRIVE
021344          MOV     @RSCS1,BAD      ;GET CS1
021350          BIC     #BIT15,BAD      ;CLEAR SC
021354          MOV     #4260,GOOD      ;GET CORRECT ANS
021360          CMP     GOOD,BAD        ;IS CS1 CORRECT?
021362          BEQ     4$              ;NO! X-FER OK
021364          HLT                     ;CS1 SHOULD = 14270 OR 4270
021366          HLT     !DS!AS
021370  4$:     TST     @RSWC           ;TEST WC
021374          BEQ     .+4             ;WORD COUNT DID OVERFLOW
021376          HLT     !WC             ;SHOULD = 0
021400          MOV     UNNUM,GOOD      ;GET CORRECT
021404          BIS     #100,GOOD       ;ANS OF CS2
021410          MOV     @RSCS2,BAD      ;GET CS2
021414          CMP     GOOD,BAD        ;IS CS2 CORRECT?
021416          BEQ     .+4             ;YES
021420          HLT                     ;GOOD = CORRECT ANS FOR CS2
021422          MOV     @RSBA,BAD       ;FETCH CURRENT ADDRESS
021426          MOV     @#OBUFSV,GOOD   ;WHAT RSBA SHOULD EQUAL
021432          ADD     #2000,GOOD      ;UPDATE IT
021436          CMP     BAD,GOOD        ;IS RSBA CORRECT
021440          BEQ     .+4             ;YES EXECUTE CONTINUE
021442          HLT                     ;RSBA FAILED TO INCREMENT
021444          CMP     #4,RS04DT       ;RS03LA?
021452          BNE     2$              ;NO
021454          CMP     #100,@RSDA      ;IS DA CORRECT?
021462          BEQ     3$              ;OK
021464          HLT     !DA!AS
021466          BR      3$              ;CONTINUE
021470  2$:     TST     RS04DT          ;IS THIS A RS04?
021474          BNE     5$              ;YES
021476          CMP     #70,@RSDA       ;IS DA CORRECT?
021504          BEQ     3$              ;YES
021506          HLT     !DA!AS          ;DA NOT CORRECT
021510          BR      3$              ;CONTINUE
021512  5$:     CMP     #64,@RSDA       ;WAS RSDA INCREMENTED
021520          BEQ     .+4             ;RSDA OK
021522          HLT     !DA!ER!DS       ;RSDA SHOULD CONTAIN A 64
021524  3$:     MOV     #TRE,@RSCS1     ;CLEAR ALL ERRORS IF ANY
021532          BIT     #BIT3,WORK1     ;MULTI DRIVE?
021540          BEQ     WTDV1           ;NO
021542  1$:     MOV     #TTVEC,@RSVEC   ;SETUP INT FOR NEXT DRIVE
021550          MOV     #WTDV2,(SP)     ;GET WAIT
021554          MOV     #100,@RSCS1     ;SET IE
021562          RTI                     ;RETURN
021564  WTDV2:  WAIT
```

```
                        ;SERVICE ROUTINE FOR SEARCH FUNCTIONS
021566  TTVEC:  CLR     R2                      ;CLEAR UNIT #
021570          CLC
021572          MOV     #401,WORK
021600  1$:     BIT     WORK,@RSAS              ;DID THIS DRIVE INT?
021606          BNE     2$                      ;YES
021610          INC     R2                      ;UPDATE UNIT #
021612          CLC
021614          ROL     WORK
021620          BCC     1$
021622          HLT     !AS                     ;WHY DID WE INT WITH NO ATA???
021624  2$:     MOV     R2,@RSCS2               ;GET DRIVE
021630          CMP     #110600,@RSDS           ;DID PIP CLEAR?
021636          BEQ     .+4                     ;YES
021640          HLT     !DS!AS                  ;PIP BIT DID NOT CLEAR
021642          CMP     #104230,@RSCS1          ;DID SC SET?
021650          BEQ     .+4                     ;YES
021652          HLT     !AS!DS                  ;SC DID NOT SET
021654          DEC     SAVEE                   ;COUNT # OF INT
021660          BEQ     WTDV1                   ;DONE YET?
021662          MOV     WORK,@RSAS              ;CLEAR AS
021670          MOV     #100,@RSCS1             ;SET IE
021676          MOV     #WTDV2,(SP)             ;RETURN TO WAIT
021702          RTI
021704  WTDV1:  MOV     #340,@#PS
021712          MOV     #500,SP                 ;CLEAR STACK
021716          MOV     RSVCPS,@RSVEC           ;RESTORE INT VECTOR
021724          CLR     @RSVCPS
021730  MODDON: SCOPE                           ;DONE
021732          MOV     TIMSV,TIMES             ;RESTORE LOOP COUNT
021740          MOV     #340,@#PS               ;RESTORE PS
021746          MOV     #1,ICNT                 ;FUGE TEST NUMBERS
021754  OUT:    JMP     @#TRYNX                 ;TEST NEXT DRIVE
                .SBTTL  $DONE - BELL AND SCOPE ROUTINE

021760  DONE:   SCOPE                           ;TERMINATIONG SCOPE FOR LOOPING
021762          ADD     #1,PCNT+2               ;ADD 1 TO THE PASS COUNT
021770          ADC     PCNT                    ;MAKE IT DOUBLE PREC.
021774          BIT     #SW10,@SWR              ;RING THE BELL?
022002          BNE     4$                      ;NO!
022004          TYPE    ,.+2                    ;.ASCIZ <BELL><177>
022014  4$:     MOV     @#42,R0                 ;GET MONITOR ADDRESS
022020          BEQ     $END1                   ;IF NONE
022022          RESET
022024  $ENDAD: JSR     7,(0)                   ;GO TO MONITOR
022026          240,240,240                     ;SAVE ROOM FOR ACT11
022034  $END1:  JMP     @#BEGIN                 ;RETURN

022040  .TBIT:  0                               ;T BIT FLAG

022042  DVTAB:  .BLKW   10
```

```
                .SBTTL          $TYPE - TTY TYPEOUT ROUTINE

                ;THIS ROUTINE IS USE TO TYPE ASCII MESSAGES ON THE TTY. THE
                ;CALL CAN BE IN ONE OF 3 FORMS: 1) "TYPE ,ADR" - TYPES THE
                ;MESSAGE STARTING IN LOCATION "ADR:"  2) "TYPE ,CHAR" - TYPES
                ;THE ASCII "CHAR"  AND 3) "PRINT <<15><12>"MESSAGE"> - TYPES
                ;THE MESSAGE WHICH IS INLINE ASCII. THE FILLER CHARACTER WHICH IS
                ;TYPED AFTER A LINE FEED IS IN FILCHR AND THE NUMBER OF FILLERS
                ;IS IN FILCHR+1.

022062  .TYPE:   MOV     R4,-(6)         ;SAVE R4
022064          MOV     R5,-(6)         ;SAVE R5
022066          MOV     @4(6),R5        ;GET ADDRESS TO BE TYPED
022072          BIT     #177400,R5      ;IS IT A TYPEM?
022076          BNE     1$              ;NO
022100          MOV     4(6),R5         ;GET ADDRESS OF CHARACTER
022104  1$:     TSTB    (R5)            ;TERMINATOR?
022106          BEQ     2$              ;GET OUT IF SO
022110          CMPB    #12,(R5)        ;IS THE CHAR A LINE FEED
022114          BNE     4$              ;NO - GET OUT
022116          MOVB    FILCHR+1,R4     ;GET THE FILL COUNT
022122  5$:     MOVB    FILCHR,@#TPB    ;TYPE A FILLER
022130          TSTB    @#TPS           ;DONE YET?
022134          BPL     .-4             ;NO - WAIT
022136          DEC     R4              ;DEC COUNT
022140          BNE     5$              ;LOOP UNTIL 0
022142  4$:     MOVB    (R5)+,@#TPB     ;LOAD AND TYPE THE CHARACTER
022146          TSTB    @#TPS           ;IS THE PRINTER READY
022152          BPL     .-4             ;WAIT UNTIL IT IS
022154          BR      1$              ;GET THE NEXT CHARACTER
022156  2$:     MOV     @4(6),-(6)      ;GET ADDRESS TO BE TYPED
022162          ADD     #2,6(6)         ;ADD 2 TO THE ADDRESS
022170          CMP     (6)+,4(6)       ;IS IT .+2?
022174          BNE     3$              ;NO
022176          ADD     #2,R5           ;ADD 2 TO THE ADDRESS
022202          BIC     #1,R5           ;BACK UP TO AN EVEN BYTE
022206          MOV     R5,4(6)         ;RESTORE ADDRESS
022212  3$:     MOV     (6)+,R5         ;RESTORE R5
022214          MOV     (6)+,R4         ;RESTORE R4
022216          RTI                     ;RETURN
```

```
                .SBTTL          $SCOPE - SCOPE LOOP HANDLER

                ;THIS ROUTINE HANDLES THE ITERATIONS, LOOPING, ERROR
                ;LOOPING, AND THE DISPLAYING OF THE TEST NUMBER.
                ;"SCOPE" IS PLACED BETWEEN EACH SUBTEST IN THE TEST AND
                ;RECORDS THE STARTING ADDRESS OF THE SUBTEST IN "LAD:"

022220  .SCOPE: KBDIN                           ;GO CHECK FOR ^G
022224          BIT     @#SW8,@#SWR             ;LOOP ON SPEC. TEST?
022232          BEQ     1$                      ;NO LOOP ON SPEC. TEST
022234          CMPB    @#SWR,ICNT              ;ON RIGHT TEST?   #SW7-0#
022240          BEQ     .OVER                   ;NOT RIGHT TEST
022242  1$:     BIT     @#SW14,@#SWR            ;LOOP ON TEST?
022250          BNE     .KIT                    ;LOOP ON TEST IS SET
022252          BR      3$                      ;SKIP - NOP FOR XOR TESTER
022254          MOV     @#4,-(6)                ;PUSH @#4 ON STACK
022260          MOV     #4$,@#4                 ;SET FOR TIMEOUT
022266          TST     @#177060                ;ERROR ON XOR?
022272          MOV     (6)+,@#4                ;POP STACK INTO @#4
022276          BR      .SVLAD                  ;NO ERROR - GO TO NEXT TEST
022300  4$:     CMP     (6)+,(6)+               ;CLEAR STACK
022302          MOV     (6)+,@#4                ;POP STACK INTO @#4
022306          BR      .KIT                    ;ERROR - LOOP ON TEST
022310  3$:     BIT     @#SW11,@#SWR            ;KILL ITERATIONS
022316          BNE     .SVLAD                  ;YES - KILL ITERATIONS
022320          TSTB    ICNT+1                  ;FIRST ONE?
022324          BEQ     2$                      ;BRANCH IF FIRST
022326          CMPB    TIMES,ICNT+1            ;DONE?
022334          BGT     .KIT                    ;BRANCH IF NOT
022336  2$:     MOVB    @1,ICNT+1               ;FIRST ITERATION
022344  .SVLAD: INCB    ICNT                    ;COUNT TEST NUMBERS
022350          MOV     (6),LAD                 ;SAVE LOOP ADDRESS
022354          MOV     ICNT,@#DISPLAY          ;DISPLAY TEST NO. AND ITERATION COUNT
022362          RTI                             ;RETURN

022364  .KIT:   INCB    ICNT+1                  ;INC THE ITERATION COUNT
022370  .OVER:  MOV     ICNT,@#DISPLAY          ;SET UP DISPLAY
022376          TST     LAD                     ;FIRST ONE?
022402          BEQ     .SVLAD                  ;YES
022404          MOV     LAD,(6)                 ;FUDGE RETURN ADDRESS
022410          RTI                             ;FIXES PS

022412  TIMES:  100                             ;RUN 100 TIMES
```

```
                .SBTTL          $HLT - HLT ROUTINE (ERROR TYPEOUT)

                ;THIS ROUTINE PRINTS OUT ERROR MESSAGES STARTING WITH THE
                ;ADDRESS OF THE "HLT".  IT ALSO COUNTS THE NUMBER OF ERRORS
                ;AND HAS THE CAPABILITY OF LOOPING ON ERROR, BELL ON ERROR,
                ;"HALT" ON ERROR, AND INHIBIT TYPEOUTS. AN OPTIONAL ARGUMENT
                ;(HLT+3) WILL BE PLACED IN ".HLTCT:" FOR ADITIONAL TYPEOUTS.

022414  .HLT:   KBDIN                   ;GO CHECK FOR ^G
022416          BIT     #SW10,@SWR      ;BELL ON ERROR?
022424          BEQ     1$              ;NO - SKIP
022426          TYPE    ,BELL           ;RING BELL
022432  1$:     INC     ERRORS          ;COUNT THE NUMBER OF ERRORS
022436          BIT     #SW13,@SWR      ;SKIP TYPEOUT IF SET
022444          BNE     2$              ;SKIP TYPEOUTS
022446          TYPE    .+2             ;.ASCIZ <15><12>
022456          MOV     (6),HLTADR      ;PUT ADDRESS OF INSTRUCTION ON STACK
022462          SUB     #2,HLTADR       ;FUDGE ADDRESS
022470          MOVB    @HLTADR,.HLTCT  ;GET HLT ARGUEMENT
022476          MOV     HLTADR,-(6)     ;PUT HLTADR ON STACK
022502          TYPEO                   ;TYPE STACK IN OCTAL
022504          TYPE    .+2             ;.ASCIZ " "
022514          JSR     PC,RSREG        ;GO TO USER ERROR ROUTINE
022520  2$:     TST     @SWR            ;HALT ON ERROR
022524          BPL     .+4             ;SKIP IF CONTINUE
022526          HALT                    ;HALT ON ERROR!
022530          BIT     #SW9,@SWR       ;CHECK FOR INHIBIT LOOP ON ERROR
022536          BNE     3$              ;SKIP IF LOOP ON ERROR
022540          CLRB    ICNT+1          ;CLEAR ITERATION COUNT
022544          RTI                     ;RETURN
022546  3$:     JMP     .KIT            ;LOOP ON TEST UNTIL NO ERRORS

022552  .HLTCT: 0                       ;HLT ARGUMENT
```

```
                        .SBTTL          SOCTAL - OCTAL TYPEOUT ROUTINE

                        ;THIS ROUTINE IS USED TO TYPE AN OCTAL NUMBER ON THE TTY. IT WILL TYPE
                        ;ALL 6 CHARACTERS, SUPPRESS LEADING ZEROES, OR TYPE THE
                        ;16 BITS. IT IS CALLED VIA THE TYPOCT, TYPBIT, OR TYPOCS MACRO'S.

022554  .TYPEB: MOV     #170101,.PR     ;SET BIT FLAG AND 16. CHARACTER COUNT
022562          BR      .PTIT           ;NOW TYPE IT IN BIT FORM
022564  .TYPEO: MOVB    #1,.PR          ;SET ZERO FILL SWITCH
022572          BR      .+6             ;SKIP
022574  .TYPES: CLR     .PR             ;SUPRESS LEADING ZERO'S
022600          MOVB    #-6,.PR+1       ;SET COUNT
022606  .PTIT:
022606          MOV     R4,-(6)         ;PUSH R4 ON STACK
022610          MOV     R5,-(6)         ;PUSH R5 ON STACK
022612          MOV     10(6),R5        ;GET THE DATA
022616          MOV     #.PR+2,R4       ;SET POINTER TO FIRST ASCII CHAR.
022622          CLRB    (4)             ;CLEAR FIRST BYTE
022624          BR      .PRF            ;ROTATE FIRST BIT
022626  .PRL:   CLRB    (4)             ;CLEAR BYTE OF CHARACTER
022630          BIT     #100,.PR        ;BIT TYPING MODE?
022636          BNE     .PRF            ;YES - SKIP 2 ROTATES
022640          ROL     R5              ;ROTATE BIT INTO C
022642          ROLB    (4)             ;PACK IT
022644          ROL     R5              ;ROTATE BIT INTO C
022646          ROLB    (4)             ;PACK IT
022650  .PRF:   ROL     R5              ;ROTATE BIT INTO C
022652          ROLB    (4)             ;PACK IT
022654          TSTB    (4)             ;IS IT ZERO?
022656          BEQ     .+6             ;SKIP INC
022660          INCB    .PR             ;SET FILL SWITCH
022664          TSTB    .PR             ;CHECK FILL SWITCH
022670          BEQ     .+6             ;SKIP BITSET
022672          BISB    #'0,(4)+        ;MAKE INTO ASCII CHAR
022676          INCB    .PR+1           ;INC COUNT
022702          BNE     .PRL            ;REPEAT
022704          CMP     #.PR+2,R4       ;EMPTY BUFFER?
022710          BNE     .+6             ;SKIP IF NOT
022712          MOVB    #'0,(4)+        ;LOAD 1 ZERO
022716          CLRB    (4)             ;NULL TERMINATOR
022720          TYPE    .PR+2           ;TYPE IT
022724          MOV     (6)+,R5         ;POP STACK INTO R5
022726          MOV     (6)+,R4         ;POP STACK INTO R4
022730          MOV     2(6),4(6)       ;GET RID OF
022736          MOV     (6)+,(6)        ;DATA WORD
022740          RTI                     ;RETURN

022742  .PR:     .BLKW   12              ;COUNT, SWITCH, AND OUTPUT BUFFER
```

```
                .SBTTL          SPOWER - POWER DOWN AND UP ROUTINES

                ;THIS IS THE POWER FAIL ROUTINE WHICH WILL SAVE ALL
                ;THE GENERAL REGISTERS AND USER DEFINED REGISTERS THEN
                ;WAIT FOR POWER TO GO DOWN AND BE RESTORED.
                ;IF THERE ISN'T ENOUGH TIME FOR SAVING ALL THE REGISTERS,
                ;THE PROGRAM WILL HALT AT '.ILLUP'.

022766  .POWER: MOV     #.ILLUP,@.PUVEC ;SET FOR FAST UP
022774          MOV     #340,@.PUVEC+2  ;PRIO:7
023002          MOV     R0,-(6)         ;PUSH R0 ON STACK
023004          MOV     R1,-(6)         ;PUSH R1 ON STACK
023006          MOV     R2,-(6)         ;PUSH R2 ON STACK
023010          MOV     R3,-(6)         ;PUSH R3 ON STACK
023012          MOV     R4,-(6)         ;PUSH R4 ON STACK
023014          MOV     R5,-(6)         ;PUSH R5 ON STACK
023016          MOV     SP,.SAVR6       ;SAVE SP
023022          MOV     #.POWUP,@.PUVEC ;SET UP VECTOR
023030          HALT                    ;WAIT FOR PF

023032  .POWUP: MOV     .SAVR6,SP       ;GET SP
023036          CLR     R1              ;WAIT LOOP FOR THE TTY
023040  1$:     INC     R1              ;WAIT FOR THE INC
023042          BNE     1$              ;OF  WORD
023044          MOV     (6)+,R5         ;POP STACK INTO R5
023046          MOV     (6)+,R4         ;POP STACK INTO R4
023050          MOV     (6)+,R3         ;POP STACK INTO R3
023052          MOV     (6)+,R2         ;POP STACK INTO R2
023054          MOV     (6)+,R1         ;POP STACK INTO R1
023056          MOV     (6)+,R0         ;POP STACK INTO R0
023060          MOV     #.POWER,@#24    ;SET UP THE POWER DOWN VECTOR
023066          MOV     #340,@#26       ;PRIO:7
023074          TYPE    ,,+2            ;.ASCIZ <15><12>"POWER"
023110          RTI                     ;RETURN

023112  .ILLUP: HALT                    ;THE POWER UP SEQUENCE WAS STARTED
023114          BR      .-2             ; BEFORE THE POWER DOWN WAS COMPLETE

023116  .SAVR6: 0                       ;PUT THE SP HERE
023120  .PUVEC: 24,26                   ;POWER UP VECTOR
```

```
                .SBTTL          $RDOCT - OCTAL INPUT ROUTINE

                ;THIS ROUTINE CALLS RDLIN, INPUTS A LINE FROM THE TTY AND CONVERTS
                ;IT INTO AN OCTAL NUMBER WHICH IS THE FIRST WORD ON THE STACK.

023124  .RDOCT: MOV     (6),-(6)        ;MOVE THE PC
023126          MOV     4(6),2(6)       ;MOVE THE PS
023134          MOV     R1,-(6)         ;PUSH R1 ON STACK
023136          MOV     R2,-(6)         ;PUSH R2 ON STACK
023140          MOV     R3,-(6)         ;PUSH R3 ON STACK
023142  4$:     RDLIN                   ;READ A LINE INTO INPUT
023144          CLR     R1              ;INIT DATA WORD
023146          CLR     CTN             ;CLEAR COUNT WORD
023152          MOV     #INPUT,R3       ;INIT POINTER
023156  1$:     MOVB    (3)+,R2         ;GET A BYTE
023160          CMPB    #15,R2          ;WAS IT A CR?
023164          BEQ     2$              ;GET OUT IF YES
023166          CMPB    #'0,R2          ;CHECK FOR 0 OR GREATER
023172          BGT     3$              ;ERROR - LESS THAN 0
023174          CMPB    #'7,R2          ;CHECK FOR 7 OR LESS
023200          BLT     3$              ;ERROR - GREATER THAN 7
023202          ROR     R2              ;GET
023204          ROR     R2              ;INTO
023206          ROR     R2              ;POSITION
023210          ROL     R1              ;FIRST BIT
023212          ROL     R2              ;GET
023214          ROL     R1              ;SECOND BIT
023216          ROL     R2              ;GET
023220          ROL     R1              ;THIRD BIT
023222          INC     CTN             ;YES HE TYPED SOMETHING
023226          BR      1$              ;LOOP
023230  2$:     MOV     R1,12(6)        ;SAVE THE RESULT
023234          MOV     (6)+,R3         ;POP STACK INTO R3
023236          MOV     (6)+,R2         ;POP STACK INTO R2
023240          MOV     (6)+,R1         ;POP STACK INTO R1
023242          RTI                     ;RETURN

023244  3$:
023244          TYPE    ,.+2            ;.ASCIZ "?"<15><12>
023254          BR      4$              ;TRY AGAIN
```

```
                .SBTTL          $RDLIN - TTY INPUT ROUTINE

                ;THIS ROUTINE INPUTS A LINE TERMINATED BY A RETURN INTO ADDRESS
                ;INPUT AND RETURNS A LINE FEED. THE BUFFER HAS A NULL TERMINATOR
                ;INSTEAD OF THE RETURN. RUBOUTS ARE HANDLED BY RETYPING
                ;THE LINE. BUFFER OVERFLOW ERRORS LIKE A RUBOUT.

023256  .RDLIN: MOV     R5,-(6)         ;SAVE R5
023260  1$:     MOV     #INPUT,R5       ;GET ADDRESS
023264  2$:     CMP     #INPUT+16.,R5   ;BUFFER FULL?
023270          BEQ     4$              ;YES - TYPE "?"
023272          TSTB    @#177560        ;WAIT FOR
023276          BPL     .-4             ;A CHARACTER
023300          MOVB    @#177562,(5)    ;GET CHARACTER
023304          BICB    #200,(5)        ;GET RID OF JUNK
023310          CMPB    #25,(5)         ;IS IT A ^U
023314          BNE     5$              ;BRANCH IF NOT
023316          TYPE    .+2             ;.ASCIZ "^U"<15><12>
023330          BR      1$              ;START OVER
023332  5$:     CMPB    #177,(5)        ;IS IT A RUBOUT
023336          BNE     3$              ;SKIP IF NOT
023340  4$:
023340          TYPE    .+2             ;.ASCIZ "?"<15><12>
023350          BR      1$              ;ZAP THE BUFFER AND LOOP
023352  3$:     MOVB    (5),#0          ;SET UP FOR TYPING
023356          TYPE    3$+2            ;ECHO IT
023362          CMPB    #15,(5)+        ;CHECK FOR RETURN
023366          BNE     2$              ;LOOP IF NOT RETURN
023370          TYPE    12              ;TYPE A LINE FEED
023374          MOV     (6)+,R5         ;RESTORE R5
023376          RTI                     ;RETURN

023400  INPUT:  .BLKB    16.             ;TTY INPUT AREA
                .SBTTL          $TRAP - TRAP HANDLER

                ;THIS ROUTINE DECODES A TRAP CALL AND JUMPS TO THE APROPRATE
                ;SUBROUTINE. THE CALL IS A "TRAP+N" WHERE N IS A MULTIPLE OF 2.
                ;THE "SET" MACRO WILL CREATE THE TABLE NEEDED. IT HAS TO
                ;FOLLOW THIS MACRO.

023420  .TRAP:  MOV     (6),-(6)        ;GET ADDRESS OF TRAP +2
023422          SUB     #2,(6)          ;MAKE IT ADDRESS OF TRAP
023426          MOV     @(6),(6)        ;GET TRAP INSTRUCTION
023432          ADD     #.TRP+2-TRAP,(6);GET DATA AND MAKE IT AN OFFSET
023436  .TRP:   MOV     @(6)+,PC        ;GO TO PROPER SUBROUTINE

023440          .SCOPE                  ;SCOPE  =  TRAP+0       (104400)
023442          .TYPE                   ;TYPE   =  TRAP+2       (104402)
023444          .TYPEO                  ;TYPEO  =  TRAP+4       (104404)
023446          .TYPES                  ;TYPES  =  TRAP+6       (104406)
023450          .RDOCT                  ;RDOCT  =  TRAP+10      (104410)
023452          .RDLIN                  ;RDLIN  =  TRAP+12      (104412)
023454          .CLRDK                  ;CLRDK  =  TRAP+14      (104414)
023456          .KBDIN                  ;KBDIN  =  TRAP+16      (104416)
023460          .SUSWR                  ;SUSWR  =  TRAP+20      (104420)
023462          .CNTLU                  ;CNTLU  =  TRAP+22      (104422)
```

```
                ;ROUTINE TO ALLOW THE OPERATOR TO SET BITS
                ;IN THE I/O REGISTERS VIA THE SWITCH REGISTER

                ;WORD COUNT REGISTER
023464  $RSWC:  MOV     #500,SP         ;SET UP STACK FOR TRAP CALL
023470  1$:     KBDIN                   ;CHECK THE WORLD
023472          MOV     @SWR,@RSWC      ;MOV SWR INTO WORD COUNT REG
023500          MOV     @RSWC,@DISPLAY  ;DISPLAY IN LIGHTS
023506          BR      1$

                ;CURRENT ADDRESS REGISTER
023510  $RSBA:  MOV     #500,SP         ;INIT THE STACK
023514  1$:     KBDIN                   ;CTW
023516          MOV     @SWR,@RSBA      ;MOV SWR INTO CURRENT ADDR REG
023524          MOV     @RSBA,@DISPLAY  ;SHOW IN LIGHTS
023532          BR      1$

                ;DISK ADDRESS REGISTER
023534  $RSDA:  MOV     #500,SP         ;INIT THE STACK
023540  1$:     KBDIN                   ;CTW
023542          MOV     @SWR,@RSDA      ;MOV SWR INTO DISK ADDR REG
023550          MOV     @RSDA,@DISPLAY  ;SHOW IN LIGHTS
023556          BR      1$

                ;DRIVE STATUS REGISTER
023560  $RSDS:  MOV     #500,SP         ;INIT THE STACK
023564  1$:     KBDIN                   ;CTW
023566          MOV     @SWR,@RSDS      ;MOV SWR INTO DRIVE STATUS
023574          MOV     @RSDS,@DISPLAY  ;SHOW IN LIGHTS
023602          BR      1$

                ;DRIVE ERROR REGISTER
023604  $RSER:  MOV     #500,SP         ;INIT THE STACK
023610  1$:     KBDIN                   ;CTW
023612          MOV     @SWR,@RSER      ;LOAD ER REG
023620          MOV     @RSER,@DISPLAY  ;DISPLAY IT IN LIGHTS
023626          BR      1$              ;LOOP

                ;WATCH LOOK AHEAD REGISTER
023630  $RSLA:  MOV     @RSLA,@DISPLAY  ;SHOW IN LIGHTS
023636          BR      $RSLA
```

```
                        ;RSCS2 REGISTER
023640  $RCS2:  MOV     #500,SP             ;INIT THE STACK
023644  1$:     KBDIN                       ;CTW
023646          MOV     @SWR,@RSCS2         ;LOAD CS2
023654          MOV     @RSCS2,@DISPLAY     ;DISPLAY IT
023662          BR      1$

                        ;RSAS REGISTER
023664  $RAS:   MOV     #500,SP             ;INIT THE STACK
023670  1$:     KBDIN                       ;CTW
023672          MOV     @SWR,@RSAS          ;LOAD RSAS
023700          MOV     @RSAS,@DISPLAY      ;DISPLAY IT
023706          BR      1$

                        ;RSMR REGISTER
023710  $RSMRR: MOV     #500,SP             ;INIT THE STACK
023714  1$:     KBDIN                       ;CTW
023716          MOV     @SWR,@RSMR          ;LOAD RSMR
023724          MOV     @RSMR,@DISPLAY      ;DISPLAY IT
023732          BR      1$

                        ;DISK CONTROL STATUS REGISTER
023734  $RSCS1: MOV     #500,SP             ;INIT THE STACK
023740  1$:     KBDIN                       ;CTW
023742          MOV     #340,@#PS           ;LOCK UP INTERRUPTS
023750          MOV     #177777,@RSWC       ;SET WORD COUNT -1 WORD
023756          MOV     @#OBUFSV,@RSBA      ;SET UP CURRENT ADDRESS
023764          MOV     @SWR,@RSCS1         ;MOV SWR INTO CONTROL REG
023772          BIT     #BIT0,@RSCS1        ;IS FUNCTION BITS SET
024000          BEQ     1$                  ;FUNCTION BITS NOT SET
024002  2$:     TSTB    @RSCS1              ;TEST FOR DISK READY
024006          BPL     2$                  ;DISK STILL NOT READY
024010          BR      1$                  ;DISK NOT BUSY SECT NEW CR
```

```
                ;THIS ROUTINE GIVES THE OPERATOR THE ABILITY TO
                ;SELECT DA, WC, UNIT # AND DESIRED PATTERN. PATTERN = NUMBER TYPED
                ;WITH SW12 SET THE PROGRAM WILL LOOP ON A READ WITH LOC OUTBUF+2 AS
                ;THE BA ADDR. WITH BIT12 0 IN THE SWR THE PROGRAM
                ;WILL WRITE WITH OUTBUF AS THE BA ADDR. BAI IS ALWAYS SET
                ;SWITCHES 0 TO 11 WILL DETERMINE THE DA
                ;EXAMPLE:        TYPE UNIT # 5
                ;                TYPE POSITIVE (OCTAL) WC 64
                ;                TYPE PATTERN DESIRED 1252525

024012  TKSEL:  MOV     #500,SP         ;SET STACK
024016          NOP
024020          TYPE    ,.+2            ;.ASCIZ <15><12>"TYPE UNIT # "
024044          RDOCT
024046          MOV     (6)+,UNNUM
024052          TYPE    ,.+2            ;.ASCIZ <15><12>"TYPE POSITIVE (OCTAL) WC "
024112          RDOCT
024114          MOV     (6)+,WORK
024120          COM     WORK
024124          TYPE    ,.+2            ;.ASCIZ <15><12>"TYPE PATTERN DESIRED "
024160          RDOCT
024162          MOV     (6)+,OUTBUF
024166          BIC     #BIT0,SWI       ;CLEAR THE BEENHEREBIT
024174          SUSWR                   ;INIT SWITCHLESS
024176  TK1:    MOV     @SWR,WORK2      ;SAVE SWR
024204  TK2:    CLRDK                   ;CLEAR ALL RS REG
024206          BIS     #BIT3,@RSCS2    ;SET BAI
024214          MOV     @SWR,WORK1      ;GET SWR FOR DSK ADDR
024222          BIC     #170000,WORK1   ;CLEAR UNIT #
024230  TKKS:   MOV     WORK1,@RSDA     ;LOAD THE DA
024236          MOV     WORK,@RSWC      ;LOAD WORD COUNT
024244          BIT     #BIT12,@SWR     ;READ?
024252          BEQ     WTE             ;NO
024254          MOV     #OUTBUF+2,@RSBA ;LOAD CURRENT ADDRESS
024262          MOV     #71,@RSCS1      ;GO AND READ
024270  WT:     TSTB    @RSCS1          ;TEST FOR READY
024274          BPL     .-4
024276          BR      SWRCHG
024300  WTE:    MOV     #OUTBUF,@RSBA
024306          MOV     #61,@RSCS1
024314          BR      WT
024316  SWRCHG: MOV     @RSCS1,@DISPLAY ;DISPLAY CS1
024324          TST     @RSCS1          ;ANY ERRORS?
024330          BPL     1$              ;NO
024332          HLT     !DA!WC
024334  1$:     KBDIN                   ;CHECK FOR NEW VALUE
024336          CMP     @SWR,WORK2      ;DID SWR CHANGE?
024344          BNE     TK1             ;YES
024346          BR      TK2             ;NO
```

```
                ;*****************************************************************************
                ;TEST 122                WRITE LOCK TEST
                ;*****************************************************************************
024350  TST122: SCOPE

024352  WRTLCK:
024352          TYPE    ,.+2            ;.ASCIZ <15><12>"LOAD SW WITH UNIT # AND CONT"
024416          CMP     #SWREG,SWR
024424          BEQ     7$              ;CHECK IF SWITCHLESS CPU
024426          HALT
024430          BR      8$              ;GO AROUND TRAP CALL
024432  7$:     CNTLU                   ;GET SWREG VALUE
024434  8$:     MOV     @SWR,UNNUM      ;GET UNIT #
024442          CLRDK                   ;CLEAR ALL REG
024444          CLR     OUTBUF          ;PUT A 0 INTO DATA BUFFER
024450          MOV     #OUTBUF,@RSBA   ;SETUP REG TO
024456          MOV     #7700,@RSDA     ;TO A WRITE
024464          MOV     #-1,@RSWC
024472          MOV     #61,@RSCS1
024500  6$:     TSTB    @RSCS1          ;WAIT FOR DONE
024504          BPL     6$
024506          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRITE LOCK ENABLE AND CONTINUE"
024560          HALT
024562  1$:     MOV     #0,@RSDA
024570          CMP     #14600,@RSDS
024576          BEQ     .+4
024600          HLT     !DS!DA          ;DS SHOULD=14600
024602          MOV     #100,@RSDA
024610          CMP     #10600,@RSDS
024616          BEQ     .+4
024620          HLT     !DS!DA          ;DS SHOULD=10600
024622          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRT LOC SW 0 AND CONT"
024662          HALT
024664  2$:     CMP     #14600,@RSDS
024672          BEQ     .+4
024674          HLT     !DS!DA          ;DS SHOULD=14600
024676          MOV     #300,@RSDA
024704          CMP     #10600,@RSDS
024712          BEQ     .+4
024714          HLT     !DS!DA          ;DS SHOULD=10600
024716          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRT LOC SW 1 AND CONT"
024756          HALT
024760  3$:     CMP     #14600,@RSDS
024766          BEQ     .+4
024770          HLT     !DS!DA          ;DS SHOULD=14600
024772          MOV     #700,@RSDA
025000          CMP     #10600,@RSDS
025006          BEQ     .+4
025010          HLT     !DS!DA          ;DS SHOULD=10600
025012          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRT LCK SW 2 AND CONT"
025052          HALT
```

```
025054  4$:     CMP     #14600,@RSDS
025062          BEQ     .+4
025064          HLT     !DS!DA          ;DS SHOULD=14600
025066          MOV     #1700,@RSDA
025074          CMP     #10600,@RSDS
025102          BEQ     .+4
025104          HLT     !DS!DA          ;DS SHOULD=10600
025106          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRT LCK SW 3 AND CONT"
025146  HALT:   HALT
025150          CMP     #14600,@RSDS
025156          BEQ     .+4
025160          HLT     !DS!DA          ;DS SHOULD=14600
025162          MOV     #3700,@RSDA
025170          CMP     #10600,@RSDS
025176          BEQ     .+4
025200          HLT     !DS!DA          ;DS SHOULD=10600
025202          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRT LCK SW 4 AND CONT"
025242          HALT
025244          CMP     #14600,@RSDS
025252          BEQ     .+4
025254          HLT     !DS!DA          ;DS SHOULD=14600
025256          MOV     #6000,@RSDA
025264          CMP     #10600,@RSDS
025272          BEQ     .+4
025274          HLT     !DS!DA          ;DS SHOULD=10600
025276          TYPE    ,.+2            ;.ASCIZ <15><12>"SET WRT LCK SW 5 AND CONT"
025336          HALT
025340          CMP     #14600,@RSDS
025346          BEQ     .+4
025350          HLT     !DS!DA          ;DS SHOULD=14600
025352          MOV     #7700,@RSDA
025360          CMP     #14600,@RSDS
025366          BEQ     .+4
025370          HLT     !DS!DA          ;DS SHOULD=14600
025372          MOV     #-1,OUTBUF      ;PUT A 1 INTO DATA BUFFER
025400          MOV     #OUTBUF,@RSBA   ;SETUP REG TO
025406          MOV     #7700,@RSDA     ;TO A WRITE
025414          MOV     #-1,@RSWC
025422          MOV     #61,@RSCS1      ;TRY TO WRITE
025430  7$:     TSTB    @RSCS1          ;WAIT FOR DONE
025434          BPL     7$
025436  5$:     TSTB    @RSCS1          ;WAIT FOR READY
025442          BPL     5$
025444          CMP     #154600,@RSDS
025452          BEQ     .+4
025454          HLT     !DS!DA          ;DS SHOULD=154600
```

```
025456          CMP     #4000,@RSER
025464          BEQ     .+4
025466          HLT     !DS!DA                  ;ER SHOULD=4000
025470          CLRDK                           ;CLEAR ALL REG
025472          CMP     #14600,@RSDS            ;DID WLE CLEAR?
025500          BEQ     .+4                     ;NO
025502          HLT     !DS                     ;A CLEAR SHOULD NOT CLEAR WLE
025504          CLR     OUTBUF                  ;PUT A 0 INTO DATA BUFFER
025510          MOV     #OUTBUF,@RSBA           ;SETUP REG TO
025516          MOV     #7700,@RSDA             ;TO A WRITE
025524          MOV     #-1,@RSWC
025532          MOV     #71,@RSCS1              ;DO A READ TO SEE IF DISK DID
025540  8$:     TSTB    @RSCS1                  ;ACTUALLY GET WRITTEN ON TO
025544          BPL     8$                      ;WAIT FOR DONE
025546          TST     OUTBUF                  ;IS DATA STILL 0 ON THE DSK?
025552          BEQ     .+4                     ;YES
025554          HLT     !DS                     ;NO DSK DID GET WRITTEN ONTO WITH WLE SET
025556          TYPE    ,.+2                    ;.ASCIZ <15><12>"RESET ALL W/L SWITCHES"
025614          HALT
025616          CMP     #10600,@RSDS            ;DID WLE CLEAR
025624          BEQ     .+4                     ;YES
025626          HLT     !DS                     ;NO

        ;ROUTINE FOR FINDING MEMORY ON "B" PORT
025630  FINDM:  MOV     #MAXREF,4               ;SET UP I/O BUS TRAP
025636          MOV     #340,6                  ;SET PS
025644          BIT     #BIT12,@SWR             ;INHIBIT OBUFSV FROM CHANGING?
025652          BNE     EXREF                   ;YES
025654          ADD     #20000,OBUFSV           ;ADD 4 K
025662  EXREF:  TST     @OBUFSV                 ;LEGAL LOC ? IF NO TRAPS
025666          MOV     #6,4                    ;RESTORE I/O BUS TRAP
025674          CLR     6
025700          CMP     #177446,OBUFSV          ;TEST FOR GREATER THEN 28K
025706          BLO     MAXRF1                  ;YES
025710          JMP     WRTSTB                  ;RETRY WRITING
025714  MAXREF: CMP     (6)+,(6)+               ;CLEAR STACK
025716  MAXRF1: MOV     #6,4                    ;RESTORE I/O BUS TRAP
025724          CLR     6
025730          MOV     #OUTBUF,OBUFSV          ;RESTORE ORIGINAL VALUE
025736          BIT     #BIT13,@SWR             ;INHIBIT TYPEOUT?
025744          BNE     1$                      ;YES
025746          BIT     #BIT13,ONCEE            ;DID WE TYPE THIS YET?
025754          BNE     1$                      ;YES
025756          TYPE    ,.+2                    ;.ASCIZ <15><12>"COULD NOT FIND MEMORY ON -B- PORT"<15><12>
        .EVEN
026030  1$:     BIS     #BIT13,ONCEE            ;SET TYPE FLAG
026036          SCOPE                           ;UPDATE
026040          SCOPE                           ;TEST NUMBER
026042          JMP     NXM                     ;CONT TESTING

        ;CLEAR ALL DISK REGISTERS
026046  .CLRDK: MOV     #40,@RSCS2              ;CLEAR ALL DSK REG
026054          MOV     UNNUM,@RSCS2            ;GET UNIT NUMBER
026062          RTI
```

```
                ;ERROR TYPTXTOUT ROUTINE

026064  RSREG:  TST     .HLTCT          ;SHOULD WE TYPTXT GOOD AND BAD
026070          BNE     8$              ;NO
026072          TYPE    @.+2            ;.ASCIZ " BAD="
026104          MOV     BAD,-(6)        ;PUT BAD ON STACK
026106          TYPEO                   ;TYPE STACK IN OCTAL
026110          TYPE    @.+2            ;.ASCIZ " GOOD="
026124          MOV     GOOD,-(6)       ;PUT GOOD ON STACK
026126          TYPEO                   ;TYPE STACK IN OCTAL
026130          JMP     PTDONE          ;GET OUT
026134  8$:
026134          TYPE    @.+2            ;.ASCIZ " CS1="
026146          MOV     @RSCS1,-(6)     ;PUT @RSCS1 ON STACK
026152          TYPEO                   ;TYPE STACK IN OCTAL
026154  1$:
026154          TYPE    @.+2            ;.ASCIZ " ER="
026166          MOV     @RSER,-(6)      ;PUT @RSER ON STACK
026172          TYPEO                   ;TYPE STACK IN OCTAL
026174  2$:
026174          TYPE    @.+2            ;.ASCIZ " CS2="
026206          MOV     @RSCS2,-(6)     ;PUT @RSCS2 ON STACK
026212          TYPEO                   ;TYPE STACK IN OCTAL
026214          BIT     #200,.HLTCT     ;TYPTXT SECOND SET ?
026222          BNE     SEEC            ;YES
026224          BIT     #AS,.HLTCT      ;TYPTXT ER ?
026232          BEQ     3$              ;NO
026234          TYPE    @.+2            ;.ASCIZ " AS="
026246          MOV     @RSAS,-(6)      ;PUT @RSAS ON STACK
026252          TYPEO                   ;TYPE STACK IN OCTAL
026254  3$:     BIT     #BA,.HLTCT      ;TYPTXT BUS ASSRESS
026262          BEQ     4$              ;NO
026264          TYPE    @.+2            ;.ASCIZ " BA="
026276          MOV     @RSBA,-(6)      ;PUT @RSBA ON STACK
026302          TYPEO                   ;TYPE STACK IN OCTAL
026304  4$:     BIT     #DA,.HLTCT      ;TYPTXT DA ?
026312          BEQ     5$              ;NO
026314          TYPE    @.+2            ;.ASCIZ " DA="
026326          MOV     @RSDA,-(6)      ;PUT @RSDA ON STACK
026332          TYPEO                   ;TYPE STACK IN OCTAL
026334  5$:     BIT     #WC,.HLTCT      ;TYPTXT WC?
026342          BEQ     6$              ;NO
026344          TYPE    @.+2            ;.ASCIZ " WC="
026356          MOV     @RSWC,-(6)      ;PUT @RSWC ON STACK
026362          TYPEO                   ;TYPE STACK IN OCTAL
```

```
026364  6$:     BIT     @DS,.HLTCT      ;DRIVE STATUS
026372          BEQ     PTDONE          ;NO
026374          TYPE    .+2             ;.ASCIZ " DS="
026406          MOV     @RSDS,-(6)      ;PUT @RSDS ON STACK
026412          TYPEO                   ;TYPE STACK IN OCTAL
026414          JMP     PTDONE          ;GET OUT
026420  SEEC:   BIC     #200,.HLTCT     ;CLEAR COMMON BIT
026426          BIT     #DT,.HLTCT      ;TYPTXT DRIVE TYPE?
026434          BEQ     9$              ;NO
026436          TYPE    .+2             ;.ASCIZ " DT="
026450          MOV     @RSDT,-(6)      ;PUT @RSDT ON STACK
026454          TYPEO                   ;TYPE STACK IN OCTAL
026456  9$:     BIT     #DB,.HLTCT      ;TYPTXT DATA BUFFER
026464          BEQ     10$             ;NO
026466          TYPE    .+2             ;.ASCIZ " DB="
026500          MOV     @RSDB,-(6)      ;PUT @RSDB ON STACK
026504          TYPEO                   ;TYPE STACK IN OCTAL
026506  10$:    BIT     #MR,.HLTCT      ;TYPTXT MN?
026514          BEQ     11$             ;NO
026516          TYPE    .+2             ;.ASCIZ " MR="
026530          MOV     @RSMR,-(6)      ;PUT @RSMR ON STACK
026534          TYPEO                   ;TYPE STACK IN OCTAL
026536  11$:    BIT     #LA,.HLTCT      ;TYPTXT LA?
026544          BEQ     PTDONE          ;NO
026546          TYPE    .+2             ;.ASCIZ " LA="
026560          MOV     @RSLA,-(6)      ;PUT @RSLA ON STACK
026564          TYPEO                   ;TYPE STACK IN OCTAL
026566  PTDONE: BIS     #BIT15,ONCEE    ;SET FORND ERROR FLAG
026574          RTS     PC

026576  WAITRY: CLR     WORK            ;CLEAR COUNTER
026602  1$:     TSTB    @RSCS1          ;TEST READY
026606          BMI     2$              ;OK CONT
026610          INC     WORK            ;UPDATE COUNTER
026614          TST     WORK            ;DONE YET?
026620          BEQ     3$              ;READY DID NOT COME UP
026622          BR      1$              ;CONTINUE WAITING
026624  2$:     ADD     #2,(SP)         ;UPDATE RETURN PC
026630  3$:     RTS     PC              ;RETURN
```

```
                ;RANDOM DATA GENERATOR SUBROUTINE

026632  RANDOM: MOV     LONUM,LOSAV
026640          MOV     HINUM,HISAV
026646  RAND1:  MOV     LONUM,R0        ;SET UP R0 WITH 5 DIGITS LOW
026652          MOV     HINUM,R4        ;SET UP R1 WITH 5 DIGITS HIGH
026656          MOV     #7,R3           ;SET UP SHIFT COUNT
026662          CLR     R2              ;CLEAR R2
026664  SHIFT:  ASL     R0              ;SHIFT R0 LEFT AND
026666          ROL     R4              ;ROTATE CARRY INTO LSB OF R1 INTO
026670          ROL     R2              ;ROTATE CARRY OUT OF R1 INTO R2
026672          DEC     R3              ;DECREMENT R3
026674          BNE     SHIFT           ;CONTINUE SHIFT LOOP
026676          ADD     LONUM,R0        ;ADDN IN NUMBER TO MAKE X 129
026702          ADC     R4              ;PROPOGATE CARRY
026704          ADD     HINUM,R4        ;ADDN IN NUMBER TO MAKE X 129
026710          ADC     R2              ;PROPOGATE CARRY
026712          ADD     #1057,R0        ;ADDN LOW CONSTANT
026716          ADC     R4              ;PROPOGATE CARRIES
026720          ADC     R2              ;PROPOGATE AGAIN
026722          ADD     #47401,R4       ;ADDN HIGH CONSTANT
026726          ADC     R2              ;PROPOGATE CARRY
026730          ADD     #6,R2           ;ADDN HIGHEST CONSTANT
026734          ADD     #2,R0           ;REPRIME R0 WITH HIGH DIGIT
026740          ADC     R4              ;PROPOGATE CARRY
026742          MOV     R0,LONUM        ;PUT R0 BACK IN LONUM
026746          MOV     R0,(R1)+        ;LOAD WC
026750          DEC     WORK
026754          BEQ     EXGEN
026756          MOV     R4,HINUM        ;PUT R1 BACK IN HINUM
026762          MOV     R4,(I)+         ;HOLD HINUM FOR PROGRAM
026764          DEC     WORK
026770          BNE     RAND1
026772  EXGEN:  RTS     R5              ;RETURN TO PROGRAM
026774  LONUM:  0
026776  HINUM:  0
027000  LOSAV:  0
027002  HISAV:  0
027004  RANEND:

027004  .SUSWR: BIT     #BIT0,SWI
027012          BNE     XXX
027014          MOV     6,-(SP)         ;SAVE 6 ON STACK
027020          MOV     4,-(SP)         ;SAVE 4 ON STACK
027024          MOV     #1$,4           ;SET UP TRAP ADDRESS
027032          CMP     #-1,@SWR        ;TEST 177570
027040          BEQ     2$              ;FAKE OUT
027042          BR      3$              ;HARDWARE AVAILABLE
027044  1$:     CMP     (SP)+,(SP)+     ;ADJUST STACK
027046  2$:     MOV     #SWREG,SWR      ;SET UP SOFTWARE REGISTERS
027054          MOV     #DISPREG,DISPLAY
027062  3$:     CMP     #SWREG,SWR      ;1ST TIME THRU?
027070          BNE     4$              ;NO CHANGE STILL 177570
027072          TST     @2              ;ANY XXDP OR ACT
027076          BNE     4$              ;SWR=000000
027100          CNTLU                   ;GET INITIAL SETTINGS
```

```
027102  4$:     MOV     (SP)+,4         ;REPLACE 4 FROM STACK
027106          MOV     (SP)+,6         ;REPLACE 6 FROM STACK
027112  XXX:    BIS     #BIT0,SWI       ;SET THE BEENHEREBIT
027120          RTI                     ;ALL DONE

027122  SWI:    0


027124  .KBDIN: TST     42              ;GOT XXDP OR ACT
027130          BNE OKT                 ;YES,GET OUT
027132          CMP     #SWREG,SWR      ;GOT SWITCH-LESS MACHINE?
027140          BNE     OKT             ;NO GET OUT
027142          TSTB    @TKS            ;HAVE A CHARACTER
027146          BPL     OKT             ;NO GET OUT
027150          MOV     @TKB,.MSG
027156          BIC     #177600,.MSG    ;STRIP OFF GARBAGE
027164          CMPB    #7,.MSG         ;DO WE HAVE A ↑G
027172          BNE OKT                 ;NO GET OUT
027174          TYPE    ,.+2            ;.ASCIZ <15><12>"↑G"
027206  .CNTLU:
027206          TYPE    ,.+2            ;.ASCIZ <15><12>"SWR= "
027222          MOV     SWREG,-(6)      ;PUT SWREG ON STACK
027226          TYPEO                   ;TYPE STACK IN OCTAL
027230          TYPE    ,.+2            ;.ASCIZ "    NEW= "
027246          RDOCT
027250          MOV     (SP)+,.MSG      ;GET NEW VALUE OFF STACK
027254          TST     CTN             ;DID HE TYPE <CR> OF 000000?
027260          BEQ     OKT             ;DONT CHANGE IF <CR>
027262          MOV     .MSG,SWREG      ;CHANGE VALUE OF SWREG
027270  OKT:    RTI                     ;ALL DONE-EXIT

027272  .MSG:   0
027274  CTN:    0
```

```
                ;TABLES FOR ILLEGAL FUNCTION TESTS

027276  ILLTAB:  3
027300           5
027302           7
027304           13
027306           15
027310           17
027312           23
027314           25
027316           27
027320           33
027322           35
027324           37
027326           41
027330           43
027332           45
027334           47
027336           0

027340  ILFTB2:  53
027342           55
027344           57
027346           63
027350           65
027352           73
027354           75
027356           77
027360           0
027362  OUTBUF:  .BLKW    300
030162  INBUF:   .BLKW    300
030762  PARITY:  0        ;USED FOR PARITY TEST 67
                 .END
```

```
ADDCF   012120
AS    = 000100
ATA   = 100000
AOB1    001166
BA    = 000020
BAD   =%000000
BAI   = 000010
BAITST  007754
BEGIN   001202
BELL  = 000007
BITBA   004350
BITCS2  004234
BITST   004162
BITWC   004300
BIT0  = 000001
BIT1  = 000002
BIT10 = 002000
BIT11 = 004000
BIT12 = 010000
BIT13 = 020000
BIT14 = 040000
BIT15 = 100000
BIT2  = 000004
BIT3  = 000010
BIT4  = 000020
BIT5  = 000040
BIT6  = 000100
BIT7  = 000200
BIT8  = 000400
BIT9  = 001000
BLOCK   010206
BPORTT  001170
CHCKDV  001650
CLRDK = 104414
CNTLU = 104422
CSTST   012050
CS1   = 000001
CS2   = 000200
CTN     027274
DA    = 000004
DAO   = 001000
DAOTST  015512
DAOTT   015670
DB    = 000210
DCK   = 100000
DCKTST  014362
DISPLA  001030
DISPRE  000174
DKADR   015052
DLT   = 100000
DONCS   012236
DONE    021760
DONEE   002016
DONINT  020756
DRCLR   005754
DRY   = 000200
DS    = 000040
DT    = 000240
DVNUM   001346
DVTAB   022042
ER    = 000002
ERINT   020760
ERR   = 040000
ERRINT  021050
ERRORS  001002
ERRR    012002
ERTST   016034
EXGEN   026772
EXREF   025662
EXTRP   020410
EXTTRP  020416
EXTTST  017674
EXTT1   020216
EXT1    020420
FILCHR  001014
FINDM   025630
FINTST  021064
FLOTBA  003052
FLOTDA  003352
FLOTWC  003212
FUNDO   016616
GOOD  =%000001
HALT    025146
HINUM   026776
HISAV   027002
HLT   = 104000
HLTADR  001012
IAERR   015126
ICNT    001000
IE    = 000100
ILFDN   010762
ILFDNE  011332
ILFTB2  027340
ILF67   011334
ILLFUN  010764
ILLTAB  027276
ILL51   010506
INBUF   030162
INCW    014574
INPUT   023400
INTDON  020640
INTR4   020642
INTR5   020536
INT112  020632
INT114  020744
IR    = 000100
KBDIN = 104416
KIPAR0= 172340
KIPAR1= 172342
KIPAR2= 172344
KIPAR7= 172356
KIPDR0= 172300
KIPDR1= 172302
KIPDR2= 172304
KIPDR7= 172316
LA    = 000204
LAD     001010
LASTSC  017164
LATDON  012046
LATST   011724
LBT   = 002000
LONUM   026774
LOP1    003772
LOP2    004042
LOP3    004112
LOSAV   027000
MAXREF  025714
MAXRF1  025716
MEMOUT  020424
MODDON  021730
MODNUM  021066
MPRO  = 172100
MR    = 000220
MULTII  001316
N     = 000123
NED   = 010000
NEDDON  015420
NEDTST  015242
NNDD    015502
NNOOP   005244
NNOP21  005562
NOOP    005120
NOOP21  005424
NOPAR   012442
NOWGO   002022
NXM     007526
NXMTSM  010060
OBUFSV  001102
OKT     027270
ONCEE   001160
OOUT    010504
OR    = 000200
OUT     021754
OUTBUF  027362
PARITY  030762
PART    012240
PARTST  011646
PATST   016330
PATTST  016770
PCNT    001004
PGE   = 002000
PGETST  013414
PGTRAP  020520
PI?   = 020000
PRTP    012422
PRTP1   012424
PS    = 177776
PSW   = 177776
PTDONE  026566
QES     020440
QESDON  020534
QQ    = 000001
RANDOM  026632
RAND1   026646
RANEND  027004
RANNU   001150
RANTS   003742
RDLIN = 104412
RDOCT = 104410
RDTST   006376
RDTSTB  007154
RMRT1   013614
RMRT2   013772
RMRT3   014102
RMRT4   014212
RSAS    001122
RSBA    001112
RSBAB   001146
RSCS1   001104
RSCS1B  001140
RSCS2   001106
RSCS2B  001142
RSDA    001114
RSDB    001126
RSDS    001116
RSDT    001132
RSER    001120
RSLA    001124
RSMR    001130
RSMRR   023710
RSREG   026064
RSVCPS  001136
RSVEC   001134
RSWC    001110
RSWCB   001144
RSWCWT  006626
RS04DT  001162
RW    = 000006
SAVBAD  001100
SAVEE   001172
SC    = 100000
SCOPE = 104400
SECT    017330
SEEC    026420
SETPAT  016502
SHIFT   026664
SILO    004632
SILOB   004422
SILOFL  005004
SRAS    023664
SRCS2   023640
SRSBA   023510
SRSCS1  023734
SRSDA   023534
SRSDS   023560
SRSER   023604
SRSLA   023630
SRSWC   023464
SRO   = 177572
STRT    000230
STTEST  001432
SUSWR = 104420
SWI     027122
SWR     001026
SWRCHG  024316
SWREG   000176
SW10  = 002000
SW11  = 004000
SW12  = 010000
SW13  = 020000
SW14  = 040000
SW15  = 100000
SW8   = 000400
SW9   = 001000
TIMES   022412
TIMSV   001164
TKB     001022
TKKS    024230
TKS     001020
TKSEL   024012
TK1     024176
TK2     024204
TMEOUT  012234
TPB     001024
TPS     001016
TRE   = 040000
TRY     001326
TRYNX   001634
TSTAGN  012266
TSTNEM  010120
TSTVEC  021336
TST1    001314
TST10   003050
TST100  015050
TST101  015124
```

```
TST102  015240        TST25   003616        TST6    002626        WC     = 000010        .CNTLU  027206
TST103  015510        TST26   003644        TST60   010504        WCE    = 040000        .HLT    022414
TST104  015666        TST27   003702        TST61   010762        WCEDNB  013354        .HLTCT  022552
TST105  016032        TST3    002274        TST62   011332        WCEDNE  012770        .ILLUP  023112
TST106  016326        TST30   003740        TST63   011644        WCEDON  013012        .KBDIN  027124
TST107  016500        TST31   004160        TST64   011722        WCEDOS  013376        .KIT    022364
TST11   003102        TST32   004232        TST65   011736        WCETB   013052        .MSG    027272
TST110  016614        TST33   004276        TST66   012046        WCETSB  013022        .OVER   022370
TST111  016766        TST34   004346        TST67   012236        WCETST  012460        .POWER  022766
TST112  017162        TST35   004420        TST7    002766        WCETT   012466        .POWUP  023032
TST113  017326        TST36   004522        TST70   012456        WORK    001174        .PR     022742
TST114  017672        TST37   004630        TST71   013020        WORK1   001176        .PRF    022650
TST115  020436        TST4    002506        TST72   013412        WORK2   001200        .PRL    022626
TST116  020534        TST40   005002        TST73   013612        WRCKT   006564        .PTIT   022606
TST117  020640        TST41   005116        TST74   013770        WRCKTB  007350        .PUVEC  023120
TST12   003126        TST42   005242        TST75   014100        WRTLCK  024352        .QQ.   = 000024
TST120  020756        TST43   005422        TST76   014210        WRTST   006150        .RDLIN  023256
TST121  021064        TST44   005560        TST77   014360        WRTSTB  006736        .RDOCT  023124
TST122  024350        TST45   005752        TTAGG   002276        WT      024270        .SAVR6  023116
TST13   003210        TST46   006146        TTMOUT  010502        WTDV    021334        .SCOPE  022220
TST14   003242        TST47   006374        TTVEC   021566        WTDV1   021704        .SUSWR  027004
TST15   003266        TST5    002600        TYPE   = 104402        WTDV2   021564        .SVLAD  022344
TST16   003350        TST50   006562        TYPEO  = 104404        WTE     024300        .SWOPT= 167400
TST17   003402        TST51   006734        TYPES  = 104406        WWP    = 000004        .TBIT   022040
TST2    002052        TST52   007152        UNCMP   001156        XXX     027112        .TRAP   023420
TST20   003426        TST53   007346        UNITST  007544        ZERONE  004524        .TRP    023436
TST21   003470        TST54   007542        UNITSV  001154        $ENDAD  022024        .TYPE   022062
TST22   003512        TST55   007752        UNNUM   001152        $END1   022034        .TYPEB  022554
TST23   003534        TST56   010056        UP     = 000000        .       030764        .TYPEO  022564
TST24   003560        TST57   010204        WAITRY  026576        .CLRDK  026046        .TYPES  022574

. ABS.  030764      000

ERRORS DETECTED:  0

DZRSBF,DZRSBF/DOC=DZRSBF.SML,DZRSBF.P11
RUN-TIME:  11 15  .5 SECONDS
RUN-TIME RATIO: 248/27=9.1
CORE USED:  21K  (41 PAGES)

DOCUMENT PAGES:  109
```