

PERIPHERAL EQUIPMENT DIVISION

TITLE INDEX - D3000 SERIES				PIB NO. DK3000	
PRODUCT LINE:	TAPE DISK FORMATTER	EQUIPMENT CHANGED N/A	MODEL SERIES AFFECTED D3000	EFFECTIVE DATE 3/15/77	

CLASS OF BULLETIN:	ORDER PART KIT NO.	EFFECTIVITY
<input type="checkbox"/> IMPROVEMENT <input type="checkbox"/> RETROFIT ON FAILURE <input type="checkbox"/> RETROFIT RECOMMENDED <input checked="" type="checkbox"/> SERVICE INFORMATION ONLY	N/A	All D3000 models

DOCUMENT NUMBER	DESCRIPTION
DK-3000A- ^{Don't have}	Updating Pertec's Information Flow
DK-3001A	+ 10 Volt Power Supplies
DK-3002	Speed Control Heat Sensitivity
DK-3003	Logic to Chassis Ground Feed Through
DK-3004-	Darlington Amplifiers
DK-3005	High Reliability Thyristor (Triac)
DK-3006A	Care and Cleanliness of D3000 Disk Drives and Media
-3007	Single To Dual Platter Conversion of D3000 Disk Drives
DK-3008	D3000 Programmable Array J123
DK-3009B	Heat Sink Transistor Locations
DK-3010	Intermittent Lamps in Compu-lite Switches
DK-3011A	"Index To Data" (Circumferential) Adjustments
DK-3012	Emergency Unloads
DK-3013	Upper Sector Transducer Adjustment
DK-3014-	X+90 Adjustment on 200 TPI Units
DK-3015	Positioner Transducer Lamp Removal and Replacement Procedure
DK-3016	Positioner Scale Removal and Replacement Procedures
DK-3017	Positioner Reticle Removal and Replacement Procedures
DK-3018B	Optical Sector Transducer Deterioration
DK-3019	Door Opener Bail Height On Front Load Disk Drives
DK-3020	Drawing Errors On One/Shot Schematic/PCBA Layout
DK-3021	Positioner Assembly Removal/Replacement Procedure
DK-3022	Positioner Lamp Life Improvement

Should Additional Information Be Required — Contact

DISTRIBUTION CODE 6318

PERTEC

PERIPHERAL EQUIPMENT DIVISION
 9600 Irondale Avenue, Chatsworth, California 91311
 Phone (213) 882-0030/TWX (910) 494-2093
 ATTENTION: PRODUCT SUPPORT MANAGER

TITLE INDEX - D3000 SERIES		PIB NO. DK3000
<u>DOCUMENT NUMBER</u>	<u>DESCRIPTION</u>	
DK-3023A	Intermittent Data Errors (Static Discharge)	
DK-3024A	New Static Discharge Spring	
DK-3025	Excessive Overshoot/Settle Time Delay Register	
DK-3026	One Shot Data Decode Phase In/Adjustment Procedures	
DK-3027	Drive and Media Preparation	
DK-3028	Difference Between Glass and Mylar Reticles	
DK-3029	Intermittant Brush Cycling - SC--907 Logic PCBA's	
DK-3030	Positioner Reticle Checklist	
DK-3031	D3000 Operator Control Panel Switches	
DK-3032	Marginal Cartridge/Door Lock Solenoids	
DK-3033	+10 Volt Supply Oscillations	
DK-3034	Schematic Error On Logic Schematic 103684	
DK-3035	To Eliminate Shorting Of NTRHGC and NLAU2G On 200 TPI	
DK-3036	D3000 Cabinet Slides	
DK-3037	Increase One/Shot Read/Write Margins	
DK-3038	Speed Out Of Tolerance Emergency Unloads	
DK-3039	D3000 Product Enhancement Changes	
DK-3040	D3000 Base Casting Change For <u>Positioner Lamp</u>	
DK-3041	Void	
DK-3042	Void	
DK-3043A	General Information On Connector and Tools	
DK-3044	Edge Connector Contacts On PCBA Assemblies - Color Of	
DK-3045	Connector Harness Strain Relief	
DK-3046	Improved Control Of Positioner Mechanical Resonance	
DK-3047B	Temperature Compensation Adjustment Procedure For Units Fitted With System Compensation PCBA	
DK-3048	A,C, Motor Speed Control	
DK-3049	False Triggering Of Drive Motor	
DK-3050B +C	Temperature Compensation Adjustment Procedure	
DK-3051	Void	
DK-3052	Motor Pulleys	
DK-3053A	New Manufacturer Of Front Panel Switches	
DK-3054A	Rectify Track Skipping	
DK-3055	Increase Stability Of Phase Lock Loop (Diablo)	

PERIPHERAL EQUIPMENT DIVISION

TITLE	INDEX - D3000 SERIES	PIB NO. DK3000
<u>DOCUMENT NUMBER</u>	<u>DESCRIPTION</u>	
DK-3056A	Data Decode Window Setting (103751)	
DK-3057	Tension Idler Assembly	
DK-3058	C.E. Alignment Specification For D3000 Disk Drive	
DK-3059	New Motor Control PCBA 103571	
DK-3060A	Procedure For Replacing Lower Platter	
DK-3061	D3000 <u>Voltage and Frequency Conversion</u>	
DK-3062	X+90 Adjustment Pot	
DK-3063	Void	
DK-3064	Extra Upper Sector Pluses	
DK-3065	To Eliminate Data Errors Due To Cross Talk From Temperature & Write Comp. PCBA To R/W PCBA	
DK-3066	Servo, X+0 Changing	
DK-3067	Cartridge Door Opener Binding On Front Loads	
DK-3068	Glyptol Contamination	
DK-3069A	Reduce Positioner Emergency Unload Velocity	
DK-3070	Scale Assy Replacement	
DK-3071	Hi-Pot Testing	
DK-3072	Extra Indes Pulses (32Sector, 2400 RPMONLY)	
DK-3073 +A	Improve Air Cleanliness In Disk Cavity	
DK-3074	Approved Disk Cartridge Vendors	
DK-3075	<i>Carriage Retainer, D3000</i>	<i>3-3-78</i>
DK-3076	<i>Elimination of Brushes and Brush Motor</i>	<i>7-5-78</i>