

PRODUCT IMPROVEMENT BULLETIN


TITLE Carriage Retainer, D3000						PIB NO. DK 3075
PRODUCT TAPE DISK X0 LINE: FORMATTER D		EQUIPMENT CHANGED N/A		MODEL SERIES AFFECTED D3000		EFFECTIVE DATE 3-3-78
CLASS OF BULLETIN: IMPROVEMENT RETROFIT ON FAILURE RETROFIT RECOMMENDED SERVICE INFORMATION ONLY		ECN NO.	10739	:	EFFECTIVITY N/A	
		PARTS KIT NO.	N/A			
		TIME REQ.	N/A			

The balance counterweight for the head carriage assembly has been redesigned to serve as a carriage retainer to prevent damage to the head carriage assembly during shipment. This part must be moved from its shipping position to its operating position, before attempting to operate the machine. The illustration shows both positions of the counterweight.

For proper operation of the machine, the weight must be installed on the head carriage, as shown by the dotted outline in the illustration. When the machine is to be transported the weight must be placed back in the shipping position. Both mounting screws should be kept in the carriage assembly to prevent their loss.

NOTE

Tie wrap straps, or a similar means, should be used to secure the head carriage assemblies for shipment on those machines which do not have the new style carriage retainers.



Should Additional Information Be Required - Contact

PERTEC COMPUTER CORPORATION

PERTEC DIVISION 9600 Irondale Avenue, Chatsworth, California 91311 Phone (213) 882-0030 / TWX (910) 494-2093 ATTENTION: PRODUCT SUPPORT MANAGER Distribution Code: 6318