CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

Bulletin No. . 1590-06

Description SUPER SCRIPSIT

Model Model 3

Stock No. 26-1590 Version 01.02.01

Date Ocotber 31, 1983

Page 1 of

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

The DWP410 driver will not work on DWP210 printer.

* * THE FOLLOWING PATCHES ARE OPTIONAL! * *

Solution

The following patches will allow DWP410 and DWP210 to interface.

COPY DWP41Ø/CTL:Ø DWP21Ø/CTL:Ø
PATCH DWP21Ø/CTL (ADD=BBØ2,FIND=1Ø,CHG=ØE)
PATCH DWP21Ø/CTL (ADD=BBØC,FIND=1Ø,CHG=ØE)