

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	491Ø-15
Description	PARSER SVC
Model	Model II
Stock No.	26-491Ø Ver. 1.2 & 2.Ø
Date	August 1Ø, 1981
Page 1 of	1

Problem

The Technical information section of the Model II manual contains an error pertaining to the PARSER SVC.

Solution

The correct function code to use the PARSER SVC is 46. This correction should be made on page 4/69 and 4/7Ø on the earlier manuals and pages 272 and 273 in the later manuals.