

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	491Ø-2Ø
<b>Description</b>	Basic Interpreter
<b>Model</b>	Model II
<b>Stock No.</b>	26-491Ø Version 2.Øa
<b>Date</b>	Jan. 27, 1982
<b>Page 1 of</b>	1

### **Problem**

Model II BASIC always sends a carriage return after 132 characters (TRSDOS 1.2, 1.2a) or 255 characters (TRSDOS 2.Ø, 2.Øa). This is undesirable to some users. In order to negate this feature of BASIC, the following patch should be applied.

### **Solution**

At TRSDOS READY, apply these patches to correct the problem.

```
PATCH BASIC A=3584 F=D4BA57 C=ØØØØØØØØ
PATCH BASIC A=35B8 F=D4BA57 C=ØØØØØØØØ
PATCH BASIC A=56F8 F=CCØD57 C=C3Ø157
```

### **\*\*\*NOTE\*\*\***

This patch should be applied ONLY if a user is writing his own software and is experiencing the problem. Under NO circumstances should this patch be applied for use by any Radio Shack software packages.