

DISPLAY/CONTROL BOARD CAPACITOR MODIFICATIONS

NOTE: THE FOLLOWING CAPACITOR VALUE SUBSTITUTIONS ARE CRITICAL IN THE OPERATION OF AN ALTAIR SYSTEM USING 4K DYNAMIC MEMORY BOARDS. THE NECESSARY CAPACITORS WILL BE INCLUDED WITH EACH ALTAIR KIT AND WITH EACH 4K MEMORY BOARD KIT, BUT THE SUBSTITUTIONS NEED BE PERFORMED ONLY ONCE. PERFORM THE SUBSTITUTIONS WHETHER YOU HAVE 4K BOARDS OR NOT.

THE FOLLOWING CAPACITORS ON THE DISPLAY/CONTROL BOARD ARE TO BE CHANGED TO THE VALUES INDICATED BELOW:

C7 should now be 0.01 μ f

C8 should now be 0.1 μ f

THESE SUBSTITUTIONS ARE TO IMPROVE THE OPERATION OF THE ALTAIR'S DEPOSIT CIRCUITRY.