

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	1506-01
Description	CASSETTE PORTFOLIO
Model	Model III
Stock No.	26-1506 Version (ALL)
Date	Oct. 6, 1981
Page 1 of	1

Problem

Sell Transactions may not exactly match the original purchase if fractional units are involved. This results in the lot being left on file (i e units left after sell are not exactly equal to zero).

Solution

The problem is corrected by following the steps listed below.

1. In BASIC load the program by typing CLOAD "TTRAN".
2. Make the following corrections:

CHANGES (Retype the line or refer to the Edit section of the owners manual)

Old Line: 126 ...IFS(J,0)=0THENGOSUB132

New Line: 126 ...IFS(J,0)<.005THENGOSUB132

Old Line: 123 ...IFD!>S(J,0)THEN116

New Line: 123 ...IFD!>S(J,0)+.005THEN116

3. Type CSAVE "TTRAN" to save the changes in the program.
5. At TRSDOS Ready, make a backup copy of the corrected tape.