

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	415Ø-Ø9
Description	TRSDOS II 4.1 Terminal
Model	Model II
Stock No.	26-491Ø Version 4.1
Date	August 24, 1982
Page 1 of	2

### Problem

Unexpected results are encountered with TERMINAL when going "on-line" with Dow Jones and Compuserve.

\* \* THESE PATCHES ARE OPTIONAL! \* \*

(The patches listed below provide TRSDOS 4.1 with the same options that Customer Service Bulletin #491Ø-12 gave to 2.Øa.)

### Solution

1. Patch one is used to eliminate Terminal flagging parity errors.

PATCH TERMINAL R=6 B=54 F=2ØØC C=ØØØØ

2. Patch two should be applied to terminal to eliminate the screening of special control characters. To install this, execute the following at the TRSDOS READY prompt.

PATCH TERMINAL R=8 B=35 F=7F C=ØØ

3. Patch three is optional. Currently, Terminal uses a table to determine if a character should or should not be filtered. Below is a reproduction of the filter table.

R= 8

B= 244            1B, Ø1, Ø2, Ø3, Ø4, Ø5, Ø6  
B= 251            Ø7, ØB, ØC, ØE, ØF, 1Ø

R= 9

B= 1              11, 12, 13, 14, 15, 16, FF  
B= 8              FF, 1E, 1F, FF, FF, FF, FF  
B= 15             FF

# CUSTOMER SERVICE BULLETIN

**Subject** TRSDOS II 4.1 Terminal #4150-09 **Page** 2 **Of** 2

If the user wished to filter or avoid filtering a character, he should patch the above table. Any value other than FFH indicates that the character indicated in that location is to be filtered. A value of FFH is just a place holder for values to be added.

For example:

```
PATCH 'TERMINAL R=8 B=244 F=1B C=FF
```

tells Terminal not to filter a 1BH (1BH clears the screen and homes the cursor). To restore the filtering of 1BH, the following patch should be applied.

```
PATCH 'TERMINAL F=8 B=244 F=FF C=1B
```