

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4910-22
Description	TRSDOS
Model	MODEL II
Stock No.	26-4910 Version 2.0a
Date	Feb. 9, 1982
Page 1 of	1

### Problem

The BACKUP utility contains a bug which will cause it to report a TRSDOS ERROR 39 for any file that uses all 16 extents. The following patches will circumvent the bug and allow BACKUP to operate properly.

### Solution

At TRSDOS READY, apply the following patches.

```
PATCH BACKUP A=28C9 F=21022CCDC632 C=0000000000000000
PATCH BACKUP A=2C02 F=1D4F6E6C7920474F4F44 C=22B22A112000197E3263
PATCH BACKUP A=2C0C F=2066696C65732063616E C=2B22612B36FFC32E352A
PATCH BACKUP A=2C16 F=20626520636F70696564 C=612B3A632B7721FFFFC9
PATCH BACKUP A=352B F=22B22A C=C3022C
PATCH BACKUP A=35F4 F=21FFFF C=C3152C
```